FLEET STATUS REPORT

| DATE | DEPT | VEHICLE | REPAIR | Hours | Parts Costs | MECH |
|-----------|--------|-----------|--|-------|-------------|---------|
| | | | Cut out bolts for frame. Prepped and fit new bed on body. Installed body nuts. | | | |
| 5/9/2019 | PW | 101 | Cleaned inside of truck. | 7.5 | \$19.04 V | N,J,D,T |
| 5/9/2019 | PW | T-16 | Replaced holders and cutters. | 11 | \$1,246.29 | I,D |
| 5/9/2019 | PW | 18 | Cleaned the back of truck bed out. Cleaned inside of truck. | 1.5 | \$0.00 V | N |
| 5/9/2019 | Code | 54 | Troubleshoot misfire. Found broken wire. | 6 | \$0.00 1 | Г |
| | | | Repaired wire harness. Taped harness back up. Fixed transmission leak. | | | |
| 5/10/2019 | Code | 54 | Replaced driver rear blinker. Took to inspection - passed. | 4.5 | \$1.90 7 | Г,D |
| | | | Lifted spool in control valve, it was stuck in down position, broke free and lubed | | | |
| 5/10/2019 | | 100 | detent cartridge. | 1 | T | |
| 5/10/2019 | PW | 235 | Checked out safety switch. Replaced PTO belt. | 1 | \$61.04 . | J |
| | | | Finished installing cutters and holder. Hooked up truck and moved grinder out of | | | |
| 5/10/2019 | PW | T-16 | pole barn for clean-up weekend. | 6 | \$0.00 J | I,D |
| | | | Cleaned and power washed shop floors and maintenance shop office. Swept and | | | |
| 5/10/2019 | PW | Shop | mopped, took out trash. | 10 | \$0.00 N | N,J,D,T |
| 5/10/2019 | Polico | 1914 | Preventive maintenance service. Replaced cabin filter. Inspected tires and brakes. Checked TPMS with scan tool. | 2.5 | \$46.78 \ | Λ/ |
| 5/10/2019 | | 1808 | Replaced passenger side headlight bulb and socket. | 2.5 | - | |
| | | | | | • | |
| 5/13/2019 | Police | 1812 | Changed computer battery pack from 1811 to 1812. Preventive maintenance service. Changed cabin filter. Checked TPMS system. | 0.5 | \$0.00 1 | |
| 5/13/2019 | Police | 1804 | Removed and replaced front brakes pads and rotors. | 3.5 | \$259.23 1 | F |
| 5/13/2019 | | 1120 | Took plate light apart it was melted. | 0.5 | - | |
| 5/13/2019 | | 6 | Took gate latch apart. | 0.5 | - | |
| 5/13/2019 | | 209 | Charged dead battery. Replaced shifter indicator. Checked for draw. | 2 | - | |
| | | 209 17 | Preventive maintenance. Inspected tires and brakes. | 2 | - | |
| 5/13/2019 | | | • | | • | |
| 5/13/2019 | | 101 | Replaced all shocks. | 1.5 | | |
| 5/13/2019 | PVV | 102 | Replaced driver side headlight and checked tire pressure. Checked fluids. | 1 | \$18.13 N | /V |
| | | | Check over for mowing season. Left front and rear tires leaking through the | | | |
| 5/13/2019 | PW | 1447 | sidewalls. Cleaned off top of mower deck and greased. Exhaust needs extension. | 3 | \$0.00 \ | I,T |
| 5/13/2019 | PW | 104 | The loader control handle popped bell crank off of pin. | 2 | \$0.00 \ | J |
| | | | Disassembled valve spool on mower lift, cleared detent assembly; so valve would | | | |
| | | | not stick. During test drive found hydraulic pump drive belt was bad on front of | | | |
| 5/13/2019 | PW | 100 | tractor. | 2.5 | \$6.56 . | J |

FLEET STATUS REPORT

| DATE | DEPT | VEHICLE | REPAIR | Hours | Parts Costs | MECH |
|-----------|--------|---------|---|-------|-----------------------------|------|
| 5/13/2019 | PW | 214 | Jumped dead batteries. | 0.5 | \$0.00 J | |
| | | | Road Call - Rental scissor lift at Presidential Lakes Firehouse shut down while | | | |
| 5/13/2019 | PW | Rental | platform was in the air. Released safeties to lower down. | 2 | \$0.00 J, | Т |
| 5/14/2019 | PW | 102 | Retrofit new bed. | 6.5 | \$0.00 D | |
| 5/14/2019 | PW | 8 | Removed bed from 12 and put back on 8. | 3.5 | \$19.04 T | J |
| 5/14/2019 | PW | 15 | Removed tool box. Cleaned bed out. Removed bed liner. Put tool box back on. | 2 | \$0.00 T | J |
| 5/14/2019 | PW | 6 | Fixed tail gate latch. Drilled and tapped, put spring back on. | 1 | \$0.00 T | |
| 5/14/2019 | PW | 36 | Replaced burnt flasher. | 0.5 | \$9.65 T | |
| 5/14/2019 | PW | 32 | Checked brakes. Checked front end. Test drove. | 2 | \$0.00 T | |
| | | | Preventive maintenance service. Cleaned battery terminals. Replaced license plate | | | |
| 5/14/2019 | Water | 61 | bulb. Inspected brakes, tires. | 2 | \$52.49 W | 1 |
| 5/14/2019 | PW | Shop | Put away sweeper brushes in conex. | 1 | \$0.00 W | 1 |
| 5/14/2019 | PW | 209 | Put back together interior panels and replaced battery. | 1.5 | \$118.98 W | 1 |
| | | | Removed and replaced driver side front tire. Replaced battery. Checked all tires. | | | |
| 5/14/2019 | | 1805 | Road tested. | 2 | | 1 |
| 5/14/2019 | PW | 18 | Jump started. | 5 | \$0.00 J | |
| 5/14/2019 | PW | 12 | Jump started. | 0.5 | \$0.00 J | |
| - / / / | 5 | | Replaced front left tire, adjusted wheel hub bearing. Checked over. Added exhaust | | * ~~ ~ ~ . | |
| 5/14/2019 | | 1447 | pipe extension and cleaned up. | 2 | - | |
| 5/14/2019 | | 100 | Replaced hydraulic pump drive belt. Test ran unit. | 1 | * · _ · · * · | _ |
| 5/15/2019 | | 101 | Install retrofitted on and fabricated brackets. Wired tail lights. | 5.5 | | , |
| 5/15/2019 | | T-32 | Road call to Trenton Road at Dans Road. Removed flat and put spare on. | 2 | | , |
| 5/15/2019 | Water | Mower | Replaced belt and put pulley kit on. Bent back adjusters. | 2 | \$46.98 T | D,J |
| 5/15/2019 | PW | 8 | Adjusted exhaust, put on new clamp. Inspected brakes. Took rear apart and ordered parts. Cleaned wheels, painted. | 5.5 | \$0.00 T | W |
| 5/15/2019 | PW | 102 | Road tested to check for vibration in drive line. Replaced pulley, tensioner and belt. | 1.5 | \$69.49 W | , |
| 5/15/2019 | PW | 28 | Readjusted exhaust stack and cleaned soot off of side of truck. | 1.5 | \$0.00 W | 1 |
| | | | Jump started and brought to shop. Drilled off two lug nuts. Inspected brakes. Front | | | |
| 5/15/2019 | Admin. | 2 | and rear brakes on order. | 3 | \$0.00 W | ,Τ |
| 5/15/2019 | PW | T-15 | Got numbers off motor, pumps, chipper and leaf vac at Lester Street. | 1 | \$0.00 J | |
| 5/15/2019 | Fire | 1818 | Labeled switch with correct sticker. | 1 | \$0.00 J | |

| DATE | DEPT | VEHICLE | REPAIR | Hours | Parts Cost | s MECH |
|----------|------|---------|--|----------|------------|--------|
| 5/15/201 | 9 PW | 106 | Protective ring was crushed against grease fitting. | | 1 \$0.00 | 0 J |
| 5/15/201 | 9 PW | JDZ1 | Sharpened blades and cleaned off spindles. | C | .5 \$0.00 | 0 J |
| 5/15/201 | 9 PW | JDZ3 | Sharpened blades and cleaned off spindles. | C | .5 \$0.00 | 0 J |
| | | | Total Hours Worked | 128 | .5 | |
| | | | Time Off (e.g., sick, vacation, etc) Misc. Time (e.g., Class, CDL Drug Test, etc) | 32.0 |)0 | |
| | | | TOTAL HOURS | 160. | 50 | |
| | | | TOTAL PARTS COST | \$2,337. | 57 | |