FLEET STATUS REPORT

DATE D	EPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
3/28/2019 Pc	olice	1833	Preventive maintenance service. Troubleshoot TPMS system. Ordered parts.	2.5	\$36.39 T	
3/28/2019 Cd	ode	50	Preventive maintenance service. Checked TPMS system.	1.5	\$30.99 T	
3/28/2019 Cd	ode	51	Preventive maintenance service. Checked TPMS system.	1.5	\$30.99 T	
			Road call Pemberton Browns Mills Rd. Loaded jack tools. Removed and replaced			
3/28/2019 W	/ater	64	tire.	1	\$0.00 T	
3/28/2019 PV	W	107	Removed right side final drive unit and resealed.	14.5	\$0.00 D,	DD,J
3/29/2019 PV	W	Shop	Cleaned shop and emptied trash.	6	\$0.00 J,E	D,T
3/29/2019 PV	W	107	Removed and rebuilt final drives. Mounted house reel. Put hose on reel. Put fittings on machine for air hose. Had	9	\$0.00 J,[)
3/29/2019 PV	W	74	keys made. Made air hose from machine and reel.	4.5	\$87.09 T	
			Preventive maintenance service. Road call for tire with bad sidewall. Replaced			
4/1/2019 Fir	re	1804	clamp on muffler. Replaced wipers.	4	\$30.56 J,E)
			Checked starter; intermittently not starting. Checked all starter connections and			
4/4/0040 PI		044	tightened alternator belt. Replaced pony air filters. Checked engine codes for pony		ΦΕ7.00 D	
4/1/2019 PV		211	engine. Fabricated body safety bar. Replaced hydraulic filter.	3	•	
4/1/2019 Pc		7	Checked air pressure in all tires.	0.5	•	
4/1/2019 W	ater	64	Troubleshoot. Replaced two rear tires.	2	\$270.15 J	
			Fixed strobes. Adjusted shift cable, checked all linkage. Adjusted emergency brakes (driver's side only). Power steering seized. Cleaned out trash. Attached			
4/1/2019 PV	W	13	moldings and seals. Removed and replaced brake light. Checked tire pressure.	2.5	\$1.90 J	
4/1/2019 PV	W	6	Unplugged wiper motor.	0.5	\$0.00 J	
4/2/2019 PV	W	210	Unit blew a water line. Removed and order parts to make a new line.	0.5	\$0.00 T	
4/2/2019 Pc	olice	1812	Fixed loose driver side end link. Road tested.	1	\$0.00 T	
4/2/2019 PV	W	32	Pressure tested system. Found metal tube rotted out. Ordered new part.	1	\$0.00 T	
			Troubleshoot. Found rotted lines and power steering lines leaking. Ordered new			
4/2/2019 PV	W	10	parts.	1	\$0.00 T	
1/0/0010 5			Prevent maintenance service. Checked TPMS system. Cleaned around oil sensor		* 40 40 *	
4/2/2019 Po		1811	to locate small leak.	2.5	•	
4/2/2019 Fir		1802	Air conditioner compressor making noise. Order clutch kit.	0.5	•	
4/2/2019 PV	W	107	Replaced pins and bushings in angle cylinders. Rebuilt leaking lift cylinders.	10	\$0.00 J,E)
4/2/2019 PV	W	9	Checked over unit that had no power. Checked all turbo and induction system hoses and clamps. Ordered service parts.	1	\$0.00 D	

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs MECH
4/2/201	9 Rec	77	Bad connection on door fuse.	0.5	\$0.00 J
4/2/201	9 PW	T-32	Replaced emergency line cracked due to uv rays. Road call. Nut fell off of blade slider shaft; found nut on road and put back	1	\$62.00 J
4/2/201	9 PW	37	together.	1	\$0.00 J
4/3/201	9 Rec	77	Located door module.	1.5	\$0.00 J
4/3/201	9 PW	24	Removed leaking lube hose from block to compressor.	1.5	\$0.00 J
4/3/201	9 PW	105	Removed angle cylinder and bushings. Installed grease hoses.	4	\$0.00 J
4/3/201	9 PW	74	Made key holder and bolted to machine.	0.5	\$0.27 T
4/3/201	9 Police	3356	Picked up from Craig's Auto. Put wiper on.	1.5	\$343.60 T,DD
4/3/201	9 PW	16	Found a screw in passenger side tire. Plugged and checked front tires.	0.5	\$0.99 T
4/3/201	9 PW	9	Preventive maintenance service. Greased truck. Changed both fuel filters. Greased boom. Road call lights on dash. Followed vehicle back to yard. Installed coolant. Road	2.5	\$162.07 T
4/3/201	9 PW	22	tested.	1.5	\$14.56 T,DD
4/3/201	9 PW	210	Made new water hose. Greased machine. Adjusted belt.	1	\$68.19 T
			Total Hours Worked	87.5	
			Time Off (e.g., sick, vacation, etc)	64.00	
			Misc. Time (e.g., Class, CDL Drug Test, etc) TOTAL HOURS	151.50	-
			TOTAL PARTS COST	\$1,239.55	