

FLEET STATUS REPORT

8/12/2019

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
4/18/2019	Fire	1836	Road call to Country Lakes Fire Dept. Troubleshoot on board charger not working. Bring unit back to shop. Repair bad connection at on board charger and replace two 20 amp fuses. Delivered to Finance.	3	\$0.00	D,J,T
4/18/2019	PW	32	Pulled all wheel and inspected brakes. Started replacing rear pads and rotors. Diff cover was leaking.	1.5	\$181.38	D
4/18/2019	Fire	M183	Drained lower unit and removed low unit. Took apart water pump impeller.	1.5	\$0.00	D
4/18/2019	Police	1805	Replaced fans. Troubleshoot short.	3.5	\$0.00	T
4/18/2019	Code	52	Preventive maintenance service. TPMS system check.	2	\$26.81	T
4/18/2019	Water	61	Checked brakes. Checked fluids. Checked codes. Unplugged wire from master cylinder. Bad float in master cylinder.	1	\$0.00	J
4/18/2019	PW	T-3	Troubleshoot. Cutter wheel bearings bad.	7.5	\$0.00	J,D,T
4/23/2019	PW	JDZ2	Replaced battery and mower blades. Get running. Checked over unit.	1.5	\$59.52	D,T
4/23/2019	PW	32	Replaced new differential cover. Finished replacing rear brake pads and rotors.	2	\$112.97	D
4/23/2019	PW	18T1	Aired up flat tires. Moved trailer to get mowers out.	1	\$0.00	D,T
4/23/2019	PW	JDZ1	Installed battery and got unit running. Checked over unit.	1.5	\$7.76	D,T
4/23/2019	Police	1807	Jump started. Checked codes. Test drove and erased codes.	1	\$0.00	D
4/23/2019	Police	1816	Diagnose purge valve is bad. Replaced with new.	1.5	\$32.54	T
4/23/2019	Police	1808	Diagnosed driver rear wheel bearing bad.	1.5	\$0.00	D,T
4/23/2019	Police	1812	Test drove and put on lift. Steering rack bad. Deadlined.	1.5	\$0.00	T,D
4/23/2019	PW	180	Greased and checked over.	0.75	\$0.00	T
4/23/2019	PW	233	Troubleshoot. Needs belt. Greased and went over.	0.75	\$0.00	T
4/24/2019	PW	104	Replaced bearing at neutral lever at HST linkage. Adjusted neutral center. Replaced left hand brake linkage return spring.	5.5	\$125.86	D,T
4/24/2019	PW	M-183	Replaced water pump impeller. Charged lower unit oil. Replaced fuel line and primer bulb.	1.5	\$93.86	D
4/24/2019	Police	1833	Replaced both valve covers.	3.5	\$43.12	T
4/24/2019	Police	1808	Replaced driver side wheel bearing.	2.5	\$173.08	T
4/24/2019	Fire	1815	Replaced spark plug.	0.5	\$4.03	T
4/25/2019	PW	40	Removed and replaced idler arms. Checked exhaust.	2	\$391.70	J
4/25/2019	PW	T-3	Made parts list.	0.5	\$0.00	J

FLEET STATUS REPORT

8/12/2019

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
4/25/2019	PW	28	Replaced side boards with 2x6.	1	\$0.00	J
4/25/2019	Fire	1891	Picked up from Browns Mills Firehouse. Installed exhaust clamp.	3	\$11.94	J,D
4/25/2019	Police	1845	Road call. Picked up and got running at BCC.	3	\$0.00	T,D,J,DD
4/25/2019	PW	JDZ2	Took belt from another mower and installed.	1	\$0.00	T,D
4/25/2019	Police	1820	Replaced battery and let charge.	0.5	\$119.74	T
4/25/2019	Police	1812	Removed old rack and started putting new rack in.	4.5	\$0.00	T
4/25/2019	PW	18	Charged batteries, got running and removed flat right rear tire.	0.5	\$0.00	D
4/25/2019	Fire	1821	Road call to Browns Mills Fire Dept. Checked all lights that were out - pump panel and driver side compartments.	1	\$0.00	D,DD
4/25/2019	PW	4	Charged dead battery, got running and removed snow plow.	0.5	\$0.00	D
4/25/2019	PW	Shop	Dumped trash, loaded water department trucks with cold patch.	0.5	\$0.00	D
4/25/2019	PW	32	Replaced right rear caliper.	1	\$99.34	D
4/25/2019	Fire	M-183	Got running, tested water pump. Delivered to Country Lake Fire Department.	1.5	\$0.00	D,J
4/26/2019	PW	37	Replaced air filter.	0.25	\$35.99	D
4/26/2019	PW	18	Replaced right rear tire with good used one. Test drove.	1	\$0.00	D
4/26/2019	PW	1821	Picked up unit from Browns Mills Fire Dept. Replaced driver side pump panel light. Replaced driver side panel cabinet light and repaired broken wire harness. Checked left side quarter light, needs parts. Repaired driver side tail light. Delivered to Browns Mills Fire Dept.	4.5	\$20.98	D,DD,T
4/26/2019	PW	T-34	Troubleshoot power shutting off at rear control box for heater. Replaced faulty circuit breaker at control panel (30 amp). Reassembled and tested. Straightened shovel door latch.	3	\$3.69	D,DD
4/26/2019	Police	1812	Put on tie rods and end links. Double checked rack. Took to Craig's for alignment. Cleared P0344 camshaft position sensor. Replaced driver side tie rod end. Troubleshoot oil smell. Bad valve cover gaskets. Started to replace them.	2.5	\$772.60	T,DD
4/26/2019	Fire	1804	Replaced oil fill gasket.	4	\$98.07	T
4/26/2019	PW	104	Removed and replaced cutting edge.	3.5	\$0.00	J
4/26/2019	PW	107	Installed rock guards and covers.	2.5	\$0.00	J
4/26/2019	PW	JDZ3	Installed new deck/PTO belt. Greased unit. Checked over.	1	\$0.00	J

FLEET STATUS REPORT

8/12/2019

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
4/29/2019	PW	214	Preventive maintenance service. Replaced cabin filter. Inspected tires and brakes. Lubed truck.	2	\$64.12	W
4/29/2019	PW	JDZ3	Replaced blade switch and checked wires for clutch.	1	\$29.99	DD/T
4/29/2019	Fire	1804	Finished driver side valve cover gasket.	2.5	\$0.00	T
4/29/2019	Police	1823	Picked up parts.	0.25	\$182.98	T
4/29/2019	PW	5	Jump started.	0.25	\$0.00	T
4/29/2019	PW	26	Followed back to shop from Route 70/Mt. Misery, changed tire.	3		T,DD,W
4/29/2019	Police	1805	Picked up from Craig's. (PCM programmed).	1.5	\$150.00	T,DD
4/29/2019	Police	1812	Picked up Craig's. (Alignment)	1	\$89.95	T,DD
4/29/2019	PW	27	Replaced side boards on dump body.	1.5	\$0.00	W
4/29/2019	PW	6	Replaced washer hose and two hood nozzles. Adjusted lift gate and greased chain fittings.	2	\$25.69	W
4/29/2019	PW	Shop	Swept up shop bays.	0.5	\$0.00	W
4/29/2019	PW	107	Finished final assembly of under carriage. Adjusted tracks.	13	\$15.57	J,D
4/30/2019	PW	213	Preventive maintenance. Replaced cabin filter. Inspected tires and brakes. Replaced rear license plate bulb.	2	\$66.09	W
4/30/2019	PW	29	Add two top side boards. Repaired tear in tarp. Replaced lower mirror. Replaced headlight. Checked fluids. Greased fittings. Inspected tires. Replaced cabin filter. Repaired rear strobe light. Replaced insurance card.	3.7	\$262.17	W
7/11/1905	Police	7965	Started and let charge. Found broken brake line. Started taking off lines.	2	\$0.00	T
4/30/2019	Police	1833	Fixed leak and plugged sensor in.	1.5	\$0.00	T
4/30/2019	Police	1814	Dropped off for turning off. Run codes Dropped off to Medford Ford.	2.5	\$0.00	T,D
4/30/2019	PW	T-74	Put card holder on for insurance card.	0.5	\$9.06	T,DD
4/30/2019	PW	T-34	Put card holder on for insurance card.	0.5	\$9.06	T,DD
4/30/2019	PW	Shop	Going over new scanner with Matco representative.	2	\$0.00	T,D,J,DD
4/30/2019	Code	55	Put plates on. Got insurance and registration together in holder.	0.5	\$0.00	T
4/30/2019	Fire	M-181	Check left tire. Replaced valve core at Browns Mills Fire Dept.	0.5	\$0.00	D
4/30/2019	PW	18	Removed left front caliper.	0.5	\$0.00	D
4/30/2019	PW	28	Replaced passenger side mirrors. Checked fluids and tire pressure.	2	\$184.00	D
4/30/2019	PW	3026	Tried to jump start.	2	\$0.00	J,D

FLEET STATUS REPORT

8/12/2019

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
4/30/2019	PW	T-16	Cleaned up around grinder and shoveled off mulch. Got ready for maintenance.	3	\$0.00	J,D
4/30/2019	PW	104	Removed and welded in cutting edge on loader bucket.	3.5	\$106.25	J
4/30/2019	PW	207	Installed tail gate.			
4/30/2019	PW	26	Replaced rubber in glad hand.	0.25	\$0.99	J
5/1/2019	Police	1812	Troubleshoot switch on sieve box. Sprayed down with contact cleaner.	1.5	\$0.00	J,T
5/1/2019	PW	32	Jump started.	0.5	\$0.00	J
5/1/2019	Police	1839	Pulled out lights, gps, radio equipment and put in box.	1.5	\$0.00	W
5/1/2019	Police	1802	Preventive maintenance service. Replaced tensioner and drive belt. Checked tires. Replaced rear brake pads. Checked TPMS with scan tool. Changed battery. Road tested.	4	\$370.92	W
5/1/2019	PW	18	Replaced driver side caliper and bled. Replaced driver's side rear brake line and bled. Replaced driver's side rear leaf spring.	5	\$61.31	J,T,W
5/1/2019	PW	211	Picked up from Melton Industries for repair.	2	\$0.00	J,DD
5/1/2019	Police	1806	Troubleshoot. Ordered parts. Preventive maintenance service.	3	\$34.71	T
5/1/2019	Fire	1892	Diagnosed bad mother board. Parts got to hot and popped. Did multi test.	2.5	\$0.00	T
			Total Hours Worked	164.7		
			Time Off (e.g., sick, vacation, etc....)	88.00		
			Misc. Time (e.g., Class, CDL Drug Test, etc....)	2		
			TOTAL HOURS	252.70		
			TOTAL PARTS COST		\$4,077.84	