

FLEET STATUS REPORT

8/12/2019

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
6/20/2019	Fire	1836	Picked up unit from Country Lakes firehouse. Replaced leaking air cylinder at pump supply valve. Reinstalled fuse in onboard charger. Delivered to Country Lakes Firehouse. (Had to detour, roads were shut down due to flooding.)	4	\$48.93	D,T
6/20/2019	PW	4	Removed rotten exhaust manifold. Removed broken bolts.	2	\$0.00	D
6/20/2019	PW	Shop	Load dump trucks with stone.	0.5	\$0.00	D
6/20/2019	Police	1806	Removed and replaced cat.	2.5	\$200.56	T
6/20/2019	PW	Shop	Picked up cones at Helen A. Fort School, took to White Pine Court and blocked off sink hole.	3	\$0.00	T,W
6/20/2019	PW	T-3	Checked over. Greased, cleaned air cleaner and blew out radiator.	1.5	\$0.00	J
6/20/2019	PW	Shop	Checked over all chain saws on bucket truck for storm.	2	\$0.00	J
6/20/2019	Fire	1815	Installed water hose, filled with antifreeze. Installed drive shaft. Repaired rear compartment door.	4.5	\$79.96	J,D
6/20/2019	PW	37	Road call to Evergreen Blvd., solenoid on hydraulic accumulator was getting hot. Unplugged wire so job could be completed. Went to Hammonton to Cat, picked up solenoid. Installed new solenoid.	4	\$273.12	J
6/20/2019	Fire	1802	Replaced driver side pins, bushing and battery. Took back to Browns Mills Firehouse.	3	\$217.13	T,W
6/20/2019	PW	18	Inspected truck for brake fluid leak, replaced rear line. Bled brakes.	2	\$10.38	W,D
6/20/2019	PW	102	Bled brakes all around and road tested.	1.5	\$3.69	W,T
6/21/2019	Police	1816	Replaced broken exhaust pipe.	1	\$259.27	T
6/21/2019	Police	1842	Replaced blower motor and resistor. Fixed driver brake light.	1.5	\$173.57	T
6/21/2019	Rec	76	Picked up from Craig's for alignment.	1	\$93.55	T,DD
6/21/2019	Water	61	Load test battery failed. Replaced with a new battery.	0.5	\$118.74	T
6/21/2019	Police	1820	Remount camera.	0.5	\$0.00	T
6/21/2019	Police	1808	Checked blower motor out and fuses . Ordered parts.	1.5	\$0.00	T
6/21/2019	Police	1807	Checked air conditioning system had blocked air pocket.	1.5	\$0.00	T/D
6/21/2019	PW	105	Replaced two blown hydraulic hoses. Fabricated one hose.	1.5	\$243.75	D
6/21/2019	PW	19	Charged dead batteries. Troubleshoot unit that was not charging, found alternator was not putting out. Removed alternator.	1.5	\$0.00	D
6/21/2019	PW	211	Checked unit for noise at the turbine wheel. Removed all access panels and found failed pillow block bearing at turbine fan drive.	2	\$0.00	D,W

FLEET STATUS REPORT

8/12/2019

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
6/21/2019	PW	4	Replaced rotten driver side exhaust manifold and removed broken bolts. Greased front end.	3.5	\$217.97	D,W
6/21/2019	Police	1804	Preventive maintenance service. Replaced cabin filter. Inspected brakes. Replaced rear rotors and pads. Checked tires. Checked TPMS with scan tool. Road tested.	3	\$302.39	W
6/21/2019	PW	21	Batteries dead, checked with load tester. Pulled out batteries and charged over night.	0.5	\$0.00	W
6/21/2019	PW	Shop	Cleaned shop. Took out trash. Wiped down tire machine.	1	\$0.00	W
6/21/2019	PW	29	Tied wires up under rear of truck. Repaired broken ABS wire on right rear wheels.	1	\$0.00	J
6/21/2019	PW	T-4	Replaced trailer light cord. Aired up tire to proper psi. Repaired break in cable.	2	\$0.00	J
6/21/2019	PW	Shop	Checked over.	1	\$0.00	J
6/21/2019	PW	Shop	Checked all trucks for emission inspection dates.	1	\$0.00	J
6/24/2019	Police	1845	Oil light was on - bad sensor. Scanned for inspection. Picked up a part at Dodge.	1.5	\$0.00	T
6/24/2019	Police	1808	Replaced blower motor and resistor.	1	\$154.48	T
6/24/2019	Police	1804	Replaced battery and checked charging system.	1	\$75.65	T
6/24/2019	Police	1802	Bad battery, caused transmission to slip. Replaced battery. Preventive maintenance service. Checked tpms.	2.5	\$154.62	T
6/24/2019	Police	1842	Removed passenger side exhaust manifold, torched out exhaust studs.	4	\$0.00	W,J,T
6/24/2019	PW	21	Cleaned battery terminals and reinstalled battery and checked charging system.	0.5	\$5.10	W
6/24/2019	PW	21	Checked fluids, they are good.	0.5	\$5.10	W
6/24/2019	Police	1820	Inspected front two tires for leaks and replaced them. Checked tpms with scan tool. Repaired front siren mount. Repaired river side front lower bumper.	2.5	\$266.04	W
6/24/2019	Water	67	Checked out starting system, did load and draw test.	1	\$0.00	J
6/24/2019	PW	105	Replaced mower frame bolt.	1	\$53.90	J
6/24/2019	PW	37	Installed seal on auxiliary fan drive shaft.	2.5	\$42.48	J,W
6/24/2019	PW	19	Installed alternator. Checked all fluids. Cleaned out cab and swept. Mounted radio speaker.	2	\$148.00	J
6/25/2019	PW	5	Inspected passenger side rear tire, found a leak and replaced valve stem and plugged nail hole. Greased front end grease points. Checked fluids.	1.5	\$4.04	W

FLEET STATUS REPORT

8/12/2019

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
6/25/2019	PW	T-16	Refueled with diesel and refilled DEF and greased all grease points. Refueled #34 with diesel.	1.5	\$14.99	W
6/25/2019	PW	JDZ1	Straightened and readjusted throttle cable.	1	\$0.00	J
6/25/2019	PW	211	Took to DeHart's.	2.5	\$0.00	J
6/25/2019	Water	67	Removed old starter and started to install new one.	2.5	\$195.00	J,T
6/25/2019	PW	104	Right front tire was flat, aired up. Bead leaks slightly. Reconnected linkage on loader control valve.	1	\$0.00	J
6/25/2019	Police	1807	Tested with scanner on air conditioning system. Troubleshooting.	2.5	\$0.00	T
6/25/2019	PW	2	Put cluster and center console back together.	0.5	\$0.00	T
6/25/2019	Rec	76	Dropped new van off.	1	\$0.00	T,W
6/25/2019	Police	1845	Replaced oil sending unit and replaced battery to get ready for inspection.	2	\$150.90	T
6/25/2019	Water	61	Found bad switch for the beacon light. Picked up part. Replaced switch.	1	\$7.69	T
6/25/2019	Water	64	Replaced passenger side front caliper. Bled front brakes. Checked fluids. Road tested.	2	\$67.72	W
6/25/2019	PW	Shop	Cleaned shop. Took out old batteries in conex. Wiped down tool box.	1.5	\$0.00	W
6/26/2019	Fire	M183	Picked up from Country Lakes Station. Put power outlet in. Took back to station.	2	\$20.05	T,DD,W
6/26/2019	Fire	1831	Charged air conditioning.	2	\$8.88	T,D
6/26/2019	Police	1812	Preventive maintenance service.	2	\$37.45	T
6/26/2019	Police	1802	Removed screw from tire. Order parts for fan not working.	2	\$0.00	T
6/26/2019	Police	1809	Replaced driver side rear tire. Mounted and balanced tire.	0.5	\$0.00	T
6/26/2019	Water	T-65	Installed two plugs in right rear tire. Jacked up and removed tire to plug.	1	\$0.00	J
6/26/2019	Water	67	Finished installing starter. Checked over. Tied up hydraulic line from around drive shaft.	1	\$0.00	J
6/26/2019	PW	12	Began to fabricate new flat bed.	4.5	\$0.00	J
6/26/2019	PW	Shop	Put PEM stickers on equipment/containers. Cleaned shop. Put away supplies.	3.5	\$0.00	W
6/26/2019	PW	99	Replaced and cleaned out cabin filter.	0.5	\$15.61	W
6/26/2019	Fire	1804	Troubleshoot engine light on. Checked codes with scanner. Inspected random misfire. Cleared codes. Repaired missing horn relay. Road tested.	2	\$0.00	W
Total Hours Worked				116		

FLEET STATUS REPORT

8/12/2019

<u>DATE</u>	<u>DEPT VEHICLE</u>	<u>REPAIR</u>	<u>Hours</u>	<u>Parts Costs</u>	<u>MECH</u>
		Time Off (e.g., sick, vacation, etc....)	36.00		
		Misc. Time (e.g., Class, CDL Drug Test, etc....)			
		TOTAL HOURS	<u>152.00</u>		
		TOTAL PARTS COST		\$3,665.61	