

FLEET STATUS REPORT

8/12/2019

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
6/6/2019	PW	106	Welded bucket shanks on.	7.5	\$555.25	D,J,W
6/6/2019	Police	1812	Replaced passenger side headlight bulb.	0.5	\$10.99	D
6/6/2019	PW	Shop	Picked up propane for forklift at Allen's.	1	\$0.00	D
6/6/2019	Police	1807	Tire light was on. Checked found nail in tire. Remove and replaced all four tires. Replaced relay and fuses for air conditioning. Took to Craig's for alignment.	3.5	\$543.07	T,DD
6/6/2019	PW	34	Picked up from Creekside.	1	\$260.00	T,DD
6/6/2019	PW	101	Road call. Dead battery at beach building. Jumped truck.	0.5	\$0.00	T
6/6/2019	PW	Shop	Went to Clydesdale Welding Supply for mig wire and welch gas. Went to Vermeer and Jesco for parts.	4	\$0.00	T,DD
6/6/2019	PW	Shop	Swept up. Put tires in container and metal in bin.	1	\$0.00	T,W
6/6/2019	PW	16	Checked fluids. Inspected tires. Checked over and made list for needed repairs.	2.5	\$0.00	W
6/6/2019	PW	Shop	Took off nuts and bolts, cut metal and put back on trailer in maintenance yard.	1	\$0.00	W
6/6/2019	Senior	78	Took through inspection.	1	\$0.00	W
6/6/2019	PW	17	Checked out front end and tires for noise. Made parts list.	1	\$0.00	J,W
6/6/2019	PW	11	Replaced exhaust manifold and studs.	4	\$320.14	J,W
6/6/2019	PW	4	Driver complained of exhaust fumes. Found gap between manifold and turbo pipe.	0.5	\$0.00	J
6/7/2019	PW	503	Power washed engine compartment.	0.5	\$0.00	D
6/7/2019	PW	Shop	Fabricated hydraulic cylinder to anchor fixture and welded to shop outer wall I-beam.	5	\$0.00	D
6/7/2019	PW	Shop	Cleaned up shop.	3.5	\$0.00	D,W,J,T
6/7/2019	Fire	1836	Put in new auto charge. Put new bulb in rear step light.	2	\$683.39	T,DD
6/7/2019	Police	1806	Picked up from Medford Ford-warranty work.	2	\$0.00	T,DD
6/7/2019	Police	1816	Preventive maintenance service. Checked motor mounts. Ordered motor mounts, transfer case seal.	3	\$34.41	T
6/7/2019	PW	106	Welded tooth holders to bucket. Cleaned up.	9	\$0.00	J,W
6/7/2019	PW	Shop	Put away Vermeer parts.	0.5	\$0.00	W
6/7/2019	PW	103	Preventive maintenance service. Cleaned cabin filter. Checked tires. Greased all fittings. Replaced wiper blade. Cleaned out trash.	2	\$70.65	W
6/10/2019	PW	503	Removed hood and floor panels and removed battery. Wrong harness, put back together.	1	\$0.00	D
6/10/2019	PW	31	Removed leaking bucket cylinder. Started taking apart for rebuild.	6	\$0.00	D,J

FLEET STATUS REPORT

8/12/2019

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
6/10/2019	PW	Forklift	Put bonnet back on.	1	\$0.00	D,J
6/10/2019	PW	16	Unhooked trailer to bring #16 into the shop. Replaced front transmission cooler hoses and replaced horn.	6.5	\$231.11	W
6/10/2019	PW	106	Finished welding holders on bucket. Repaired tear in back of bucket.	2	\$0.00	J
6/10/2019	PW	8	Road call to Upper Mill Road. Plugged and inflated tire.	1	\$0.00	J
6/10/2019	PW	37	Replaced cutting edges. Replaced air conditioner belt. Located leak at transmission (for drive on transmission leaking from seal).	4	\$256.90	J,D
6/11/2019	PW	31	Rebuilt loader bucket cylinder.	5.5	\$210.48	D,J
6/11/2019	Police	1807	Picked up unit from Craig's for alignment.	1	\$0.00	D,DD
6/11/2019	Fire	1836	Checked air cylinder that was leaking at pump. Road call to Country Lakes Fire Department. Order parts at Blaze.	2	\$0.00	D,DD
6/11/2019	PW	211	Plug right rear outside tire.	0.5	\$0.99	D
6/11/2019	PW	T-32	Trailer brakes were hung up.	0.5	\$0.00	J
6/11/2019	PW	26	Moved trailer lines to better location for hook up.	1.5	\$0.99	J
6/11/2019	PW	106	Welded patch on heel of bucket. Cleaned up.	3.5	\$0.00	J
6/11/2019	PW	16	Replaced passenger side lower ball joint and drag link and top and bottom tie rod ends.	5	\$258.05	W,J
6/11/2019	PW	Shop	Cleaned up shop. Put away sealer and scissor lift in barn.	1.5	\$0.00	W
6/11/2019	PW	103	Replaced two turn signal bulbs and refueled diesel fuel.	0.5	\$2.86	W
6/12/2019	PW	38	Power washed entire machine. Removed and rebuilt one loader bucket cylinder and one loader lift cylinder.	10.5	\$339.70	D,J
6/12/2019	PW	16	Installed new rotor and pads on driver side. Installed new snap ring on passenger side ball joint knuckle.	1.5	\$202.50	W
6/12/2019	Police	1823	Checked and pressure tested radiator. Found a crack in radiator. Started to take radiator out.	1.5	\$0.00	W
6/12/2019	Police	1806	Preventive maintenance service. Replaced cabin filter. Inspected and replaced rear and front rotors and pads. Checked TPMS with scanner. Repaired passenger side tire. Road tested.	3.5	\$420.99	W
Total Hours Worked				116.5		
Time Off (e.g., sick, vacation, etc....)				44.00		
Misc. Time (e.g., Class, CDL Drug Test, etc....)						

FLEET STATUS REPORT

8/12/2019

<u>DATE</u>	<u>DEPT VEHICLE</u>	<u>REPAIR</u>	<u>Hours</u>	<u>Parts Costs</u>	<u>MECH</u>
		TOTAL HOURS	160.50		
		TOTAL PARTS COST		\$4,402.47	