

FLEET STATUS REPORT

8/13/2019

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
			Got two dirt bikes and two quads running. Charged batteries. Brought into shop.			
7/5/2019	Police	Shop	Picked up parts at Mt. Holly Motorsports.	3	\$0.00	D
7/5/2019	PW	13	Checked out leaking brake line.	0.5	\$0.00	D
			Went to Cherry Valley Tractor to pick up parts. Removed feed control valve. Took apart broken valve spool. Took apart parts valve and made one good one.			
			Reinstalled valve. Troubleshoot weak hydraulics - found bad safety over ride solenoid. Removed solenoid.	3	\$0.00	D
7/5/2019	PW	T-3				
7/5/2019	PW	219	Rubberized undercarriage.	4	\$89.85	W
7/5/2019	PW	220	Started rubberizing undercarriage.	2.5	\$71.88	W
7/5/2019	PW	12	Make new flat bed body.	8.5	\$0.00	J,W
7/5/2019	Fire	1838	Checked air conditioning - low on freon, system had 25 lbs. of psi.	2.5	\$4.44	J
7/5/2019	PW	12	Built flat bed body.	4	\$0.00	J
			Replaced rear tube. Removed and drained gas tank. Started removing carburetor to clean.	2	\$18.95	D
7/8/2019	Police	18M2				
7/8/2019	Police	1822	Checked over unit - no front brakes. Replaced front master cylinder cover, refilled master cylinder. Bled brakes.	1.5	\$49.99	D
7/8/2019	Police	18Q1	Checked unit over.	1	\$0.00	D
			Road call to Presidential Lakes Firehouse. Charged dead batteries and got unit running.	1	\$0.00	D
			Replaced rear tube. Removed and drained gas tank. Started removing carburetor to clean.	1	\$110.65	D
7/8/2019	Police	18M3				
7/8/2019	Police	1804	Temporarily fixed mic box cord.. Tightened up camera. Ordered parts.	1.5	\$0.00	T
7/8/2019	Fire	1600	Changed passenger side headlight bulb.	0.5	\$27.49	T
			Repaired and remade abs brake line to rear brake line. Picked up part for brake line.	4.5	\$20.58	T,D
7/8/2019	PW	13				
7/8/2019	PW	100	Troubleshoot inside lift handle. Control cable was out of housing.	1	\$0.00	J
7/8/2019	PW	12	Made side boards and installed plates on body.	6.5	\$52.25	J,W
7/8/2019	PW	220	Finished undercoating truck.	0.5	\$17.97	W
7/8/2019	PW	18	Battery was dead. Jumped with cables and jump box.	0.5	\$0.00	W
7/8/2019	Water	Shop	Repaired water division suck hose.	0.5	\$0.00	W
7/8/2019	Rec	Shop	Dropped off water buoy to be blown up.	0.5	\$0.00	W
			Preventive maintenance service. Replaced cabin filter and license plate bulb.			
7/8/2019	Police	1807	Inspected brakes and checked tires with TPMS scan tool.	2	\$55.09	W

FLEET STATUS REPORT

8/13/2019

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
7/8/2019	Water	71	Replaced passenger side front brake hose. Bled brakes. Checked tire pressure with TPMS scanner tool. Checked fluids and road tested.	2	\$22.74	W,T
7/9/2019	Senior	78	Replaced rear tag light.	0.5	\$7.25	W
7/9/2019	PW	12	Fastened bumper top frame.	32.5	\$0.00	J,W
7/9/2019	PW	Shop	Training at Gloucester Township Public Works	25	\$0.00	J,D,DD,T,V
7/9/2019	Police	18M2	Removed and rebuilt carburetor. Replaced rear tire tube.	2	\$19.95	D
7/9/2019	Police	Shop	Made radar brackets.	1	\$0.00	T
7/9/2019	PW	13	Put intake tube back on and battery back in service.	0.5	\$0.00	T
7/10/2019	Police	1390	Check air conditioning system. Needs condenser.	1	\$0.00	T,DD
7/10/2019	Fire	1802	Check air conditioning system. - Needs compressor.	1	\$0.00	T,DD
7/10/2019	Police	1818	Preventive maintenance service. TPMS system check.	2	\$37.41	T
7/10/2019	Police	1833	Replaced accumulator, evacuation system. Recharged.	2	\$61.30	T,J
7/10/2019	Water	68	Took tire off, brought to shop. Looked for new tire, have to wait until tomorrow. Put tire back on to take to Tri State Tire.	3.5	\$0.00	T,J,DD
7/10/2019	PW	Shop	Got trucks in line for inspection.	1.5	\$0.00	T,J,DD
7/10/2019	PW	Shop	Cleaned up and swept. Wiped down tire machine and parts washer.	1	\$0.00	W
7/10/2019	Police	3026	Replaced starter and firewall solenoid. Diagnosed electrical problem to push button starter.	4.5	\$373.00	W
7/10/2019	Senior	78	Repaired front passenger side tire and checked all tire pressures.	1	\$0.99	W
7/10/2019	Police	18M2	Reinstalled carburetor and fuel tank. Cleaned air box.	1	\$0.00	D
7/10/2019	PW	31	Removed and replaced blown hydraulic hose at leader bucket auxiliary circuit.	1.5	\$104.36	D
7/10/2019	Fire	1891	Fabricated hydraulic hose.	1.5	\$104.36	D
7/10/2019	Fire	1891	Road call to Browns Mills Fire Dept. Troubleshoot no back up alarm. Replaced back up alarm.	1	\$30.11	D
			Total Hours Worked	137		
			Time Off (e.g., sick, vacation, etc....)	20.00		
			Misc. Time (e.g., Class, CDL Drug Test, etc....)	25		
			TOTAL HOURS	157.00		
			TOTAL PARTS COST		\$1,176.25	