FLEET STATUS REPORT

| DATE [| DEPT | VEHICLE | REPAIR | Hours | Parts Costs | MECH |
|-------------|---------|---------|---|-------|-------------|------|
| 1/31/2019 P | W | 211-P | Replaced starter. | 3.2 | \$0.00 | W,D |
| 1/31/2019 S | Seniors | 77 | Jump started with jumper box. Brought to shop. Checked charging system and checked for draw. | 1.5 | \$0.00 | W |
| 1/31/2019 C | Code | 52 | Put air in tires. | 0.3 | \$0.00 | W |
| 1/31/2019 P | W | Shop | Cleaned up shop. | 2 | \$0.00 | W |
| 1/31/2019 P | νW | 22 | Installed transmission cooler and mounting brackets. Installed upper and lower radiator cooler hoses. Replaced driver side auger shaft bearing. | 5.5 | \$3,136.91 | D,T |
| 1/31/2019 P | PW | Shop | Made an air line adapter for 3/4 inch drive gun. Organized shop truck tools, put fittings away. Put exhaust and car back together. Filled transmission and PTO. Took radar out of | 1 | \$1.69 | D |
| 1/31/2019 P | Police | 1808 | car. | 6 | \$52.06 | Т |
| 2/1/2019 P | W | Shop | Ran loader and loaded trucks. | 1 | \$0.00 | |
| 2/1/2019 P | W | 213 | Installed and wired rear LED back up flood lights. | 3.5 | \$21.23 | D |
| 2/1/2019 P | W | 26 | Got unit running, that would not start. | 0.5 | \$0.00 | D |
| 2/1/2019 P | W | T-3 | Mounted fuel/hydro tank. Back down lost bolts. | 0.5 | \$0.00 | Т |
| 2/1/2019 P | W | 25 | Torch off bearing for spreader box. Cleaned up and put new bearing on. | 2 | \$17.36 | T,D |
| | | | Checked for fuel leak. Gasket leaking at water pump for bottom radiator hose. | | | |
| 2/1/2019 P | W | 208 | Replaced gasket. | 5 | \$26.38 | T |
| 2/1/2019 P | W | T-31 | Replaced rain cap on muffler. | 0.5 | \$13.47 | DD |
| 2/1/2019 S | Seniors | 77 | Started and warmed up bus. | 0.5 | \$0.00 | W |
| 2/1/2019 P | W | 16 | Jump started with jumper box. | 0.5 | \$0.00 | W |
| 2/4/2019 P | W | 22 | Made and installed two coolant lines for transmission cooler. | 5 | \$341.68 | D |
| 2/4/2019 P | W | 27 | Road call to Ridge Road and Noteboom. | 3 | \$0.00 | D,DD |
| 2/4/2019 P | Police | 1851 | Engine light on. Checked scanner. Evap pressure switch stuck closed. Inspected floor board on passenger side water weather stripping is leaking. Checked engine light on. Evap system medium leak. Transmission control system, replaced no. 2 coil pack with used one. Preventive maintenance. Inspected brakes | 1.5 | \$0.00 | W |
| 2/4/2019 P | Police | 1834 | and tires. Road tested. Repaired 2-way radio. Replaced marker stick on plow passenger side. Inspected front driver side tire for leaks, tightened valve stem. Repaired passenger side wiper | 3.5 | \$29.50 | W |
| 2/4/2019 P | | 21 | nozzle. | 1.5 | | |
| 2/4/2019 P | W | 207 | Fixed front grill strobe. Fixed strobe. | 1.5 | \$0.00 | Т |

FLEET STATUS REPORT

| DATE | DEPT | VEHICLE | REPAIR | Hours | Parts Costs | MECH |
|---------|-----------|---------|---|-------|-------------|--------|
| | | | Preventive maintenance service. Fixed right door sweep. Fixed screw behind driver | | | |
| 2/4/201 | 19 Rec | 78 | seat. | 1.5 | \$0.00 | Т |
| 2/4/201 | 19 Fire | 1818 | Diagnosed problems, light bar box is bad, fuse holder is burnt. | 3.5 | \$0.00 | Τ |
| | | | Picked up from Station 1. Learned how to lift cab, got part numbers to order parts. | | | |
| 2/5/201 | 19 Fire | 1811 | Started preventive maintenance service. | 3 | \$0.00 | T,DD |
| 2/5/201 | 19 PW | Shop | Matco training on new scanner. | 3 | 3 | T,DD,W |
| 0/=/00 | : | 4040 | Preventive maintenance service. Fixed maxi fuse holder. Put light bar back | | | |
| 2/5/201 | | 1818 | together. Inspected visor lights. Took back to station. | 4 | • | • |
| 2/5/201 | | 217 | Repaired driver side rear tire. | 0.3 | • | |
| 2/5/201 | | 207 | Inspected passenger side rear inside tire. Pulled out screw, no leaks. | 0.3 | · · | |
| 2/5/201 | | Shop | Helped clean out upstairs, put lawn mower parts and tires in conex. | 3.2 | • | |
| 2/5/201 | | Shop | Organized maintenance shop conex. Cleaned up office, mopped and swept. | 1.5 | • | |
| 2/6/201 | 19 PW | Shop | Cleaned up shop bays. | 0.5 | \$0.00 | W |
| | | | Preventive maintenance service. Inspected brakes and tires. Removed snow | | | |
| 2/6/201 | | 207 | spreader and wire harness. | 2.5 | • | · |
| 2/6/201 | 19 PW | 209 | Replaced dead battery with good used battery. | 0.5 | \$0.00 | W |
| | | | Troubleshoot engine light on. Preventive maintenance service. Inspected brakes | | | |
| 2/6/201 | | 112 | and tires. Checked TPMS. Dropped off at Medford Ford for warranty cat codes. | 4 | • | • |
| 2/6/201 | 19 PW | T-34 | Replaced trailer plug and re-route trailer plug into harness. Tested circuits. | 1 | • | |
| 2/6/201 | 19 PW | Shop | Weather proofed all snow plow connections on pick up truck plows. | 0.5 | \$0.00 | D |
| 2/6/201 | 19 PW | Shop | Cleaned oil off of lift and cleaned salt from rolling jack. Took out scrap metal. | 1.5 | \$0.00 | D |
| 2/6/201 | 19 PW | 31 | Road call to Noteboom. Aired up two front tires. | 0.5 | \$0.00 | D |
| | | | Troubleshoot no turn signals. Replaced failed flasher and fuse. Replaced broken | | | |
| 2/6/201 | 19 PW | 24 | hood latch on driver's side. | 1 | \$73.87 | D |
| | | | Preventive maintenance service. Ran codes. Removed and replaced fuel filters. | | | |
| 2/6/201 | 19 Fire | 1811 | Repaired burnt wire on fuel filters. | 4.5 | \$302.73 | T,D,DD |
| - / - / | | | Took 1802 to Country Lakes Firehouse to pick up 1638 for preventive maintenance | | | _ |
| 2/6/201 | | 1838 | service. | 0.5 | • | |
| | 19 Police | 1806 | Vehicle was shutting off. Took to Medford Ford. | 1 | ***** | |
| | 19 Police | 7915 | Computer had no power. Removed and replaced fuse in back up charger. | 0.5 | • | |
| 2/6/201 | 19 PW | 5 | Added three quarts of oil. | 0.5 | \$0.00 | T |

| DATE | DEPT VEHICLE | REPAIR | Hours | Parts Costs | MECH |
|------|--------------|--|------------|-------------|------|
| | | | | | |
| | Total I | Hours Worked | 88.8 | | |
| | Time (| Off (e.g., sick, vacation, etc) | 55.00 | 1 | |
| | Misc. | Fime (e.g., Class, CDL Drug Test, etc) | 3 | 1 | |
| | | TOTAL HOURS | 143.80 | <u>-</u> | |
| | | TOTAL PARTS COST | \$4.180.15 | | |