

FLEET STATUS REPORT

8/7/2019

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
3/14/2019	Police	1816	Replaced passenger rear inner door handle. Preventive maintenance service.	2.5	\$49.49	T
3/14/2019	Police	3356	Preventive maintenance service.	2	\$81.49	T
3/14/2019	PW	209	Dropped off and picked up at Creekside. Replaced windshield.	1.5	\$260.00	T,DD
3/14/2019	PW	45	Picked up from Creekside.	5	\$255.00	T
3/14/2019	Police	1819	Checked tire, installed battery and fluids.	0.5	\$0.00	T
3/14/2019	PW	37	Troubleshoot unit that only has two forward gears.	4	\$0.00	D,DD
3/14/2019	PW	107	Removed all bottom rollers, rear sprockets, rock guards and T track adjusters. Removed front left tire and broke down, cleaned up bead on rim and mounted.	7	\$0.00	D,J
3/14/2019	PW	104	Checked over and cleaned up.	1	\$0.00	J
3/14/2019	PW	24	Used thermal gun to locate engine miss.	1.5	\$0.00	J
3/14/2019	Police	1819	Jump started and checked over.	0.5	\$0.00	J
3/14/2019	PW	209	Jump started.	1	\$0.00	J
3/15/2019	PW	Shop	Cut bolts from old tire machine, cleaned floor, put balancer in place. Hung car lift arm support. Cleaned office and shop.	4	\$0.00	T,D,J
3/15/2019	Police	1812	Fixed front lower grill in bumper. Preventive maintenance service. Checked front end and ordered parts.	3	\$255.09	T
3/15/2019	Police	1808	Replaced passenger side marker lights. Topped off washer fluid.	1	\$6.28	T
3/15/2019	PW	104	Looked up and recorded parts for repair.	1	\$0.00	J
3/15/2019	PW	107	Removed under carriage and ordered parts. Pressure washed machine and floor. Ran tap through all threaded holes.	10	\$0.00	D,J
3/18/2019	PW	37	Troubleshoot transmission problem. Cleaned and checked solenoid valve bank at transmission.	6	\$0.00	D,DD
3/18/2019	PW	100	Road call to Brandywine. Charged battery and got unit running. Removed hydraulic pump belt, got parts and put belt back on. Drained fuel and removed and cleaned carburetor. Replaced spark plug and fuel.	1.5	\$0.00	D
3/18/2019	PW	Shop	Got running and tested unit.	1	\$3.94	D
3/18/2019	PW	36	Checked front end and greased.	1	\$0.00	T
3/18/2019	PW	15	Replaced wipers.	0.25	\$34.50	T
3/18/2019	Police	1814	Mounted dash bracket and radar on dash. Made a radar bracket and ran wires to the rear. Mounted rear radar bracket.	2.5	\$0.00	T

FLEET STATUS REPORT

8/7/2019

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
3/18/2019	PW	207	Set strobes. Ordered plow plug. Removed salt spreader and hooked bed back up. Put magnet on light.	2.75	\$3.49	T
3/18/2019	PW	107	Cleaned up undercarriage to paint.	6.5	\$0.00	J,D
3/18/2019	PW	24	Checked over air brake system.	0.5	\$0.00	J
3/18/2019	PW	14	Installed tool box in bed of truck.	0.5	\$0.00	J
3/18/2019	PW	208	Connected wire from main panel.	1	\$0.00	J
3/19/2019	Police	3356	Troubleshoot revving problem. Took PCM apart. PCM was bad from water damage.	3	\$0.00	T
3/19/2019	Rec	78	Replaced wipers.	0.25	\$34.50	T
3/19/2019	PW	Shop	Repaired hose end.	0.25	\$16.99	T
3/19/2019	Police	1812	Removed driver side control arm and end link. Removed sway bar bushing.	3	\$173.36	T
3/19/2019	PW	218	Repaired water leak at water manifold.	0.5	\$0.00	D
3/19/2019	PW	100	Got unit running. Removed covers and guards. Checked belt. Removed side mower cover and removed damaged belts and failed idler pulley.	2	\$0.00	D,DD
3/19/2019	Fire	Shop	Checked fuel leak and ordered parts.	0.5	\$0.00	D
3/19/2019	PW	31	Replaced and fabricated leaking hose at hydraulic bucket coupler pin cylinder.	1	\$39.96	D
3/19/2019	PW	107	Cleaned rust and dirt off of under carriage to get ready for paint. Cleaned up.	7.5	\$16.99	J,D
3/19/2019	PW	37	Removed and cleaned shift control valves. Installed transmission controller assembly. Installed and cleaned solenoid cover. Drove and checked that all gears are operational.	4.5	\$1,150.03	DD,D,J
3/20/2019	PW	107	Cleaned under carriage. Removed seized pin. Cleaned up.	4.5	\$0.00	J,T
3/20/2019	PW	24	Brought in to shop and put on lift. Found engine oil leaks, pto leaks, power steering reservoir needs to be washed.	1	\$0.00	J
3/20/2019	Police	1811	Coolant leak on top of turbo cooler. Cut line, pushed on and tightened clamp.	4	\$7.22	T,J
3/20/2019	Police	1805	Checked rear brakes. Ordered control arms. Fixed front lower grill.	1	\$0.00	T
3/20/2019	Police	1812	Replaced passenger side end link. Replaced sway bar bushings on both sides. Replaced passenger side headlight harness.	2	\$68.70	T
3/20/2019	Police	1816	Reset breaker and tried out gun rack.	0.5	\$0.00	T

FLEET STATUS REPORT

8/7/2019

<u>DATE</u>	<u>DEPT VEHICLE</u>	<u>REPAIR</u>	<u>Hours</u>	<u>Parts Costs</u>	<u>MECH</u>
		Total Hours Worked	104.5		
		Time Off (e.g., sick, vacation, etc....)	56.00		
		Misc. Time (e.g., Class, CDL Drug Test, etc....)			
		TOTAL HOURS	<u>160.50</u>		
		TOTAL PARTS COST		\$2,457.03	