

FLEET STATUS REPORT

8/7/2019

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
3/21/2019	PW	100	Put on new belt and checked pulleys. Ordered parts.	2	\$12.13	D
3/21/2019	PW	1132	Wired dual water pumps together until wiring diagrams and service manual arrive for troubleshooting.	1	\$0.00	D
3/21/2019	Police	1805	Removed and replaced both front lower control arms.	3.5	\$260.80	T
3/21/2019	PW	Shop	Loaded welding tanks up. Dumped trash and cleaned up shop.	6	\$0.00	T,D
3/22/2019	PW	12	Charged batteries to get unit running. Removed bed to put on unit 102.	4	\$0.00	D,J
3/22/2019	PW	Shop	Loaded oxygen and shop gas bottles; took to Clydesdale and exchanged six bottles. Brought back to shop, unloaded and set up in shop truck, cart and spares.	2.5	\$0.00	D,J
3/22/2019	PW	102	Removed and replaced bed. Checked out exhaust leak. Put undercoat on new bed.	6.5	\$86.56	D,J
3/25/2019	Police	1805	Put new lock nut on arm. Red lock is tight.	1	\$0.00	T
3/25/2019	Police	3356	Took old pcm out and put in new. Took new one to Craig's to be programmed.	2	\$0.00	T,J
3/25/2019	Police	1802	Troubleshoot. Blew air in box and sprayed switch with contact cleaner. Blew out.	2.5	\$0.00	T
3/25/2019	PW	102	Inspected truck for leaks. Ordered parts.	1	\$0.00	T
3/25/2019	PW	28	Changed passenger side rear inside tire.	1.5	\$0.00	D,T,J
3/25/2019	PW	107	Rebuilt undercarriage.	11		J,D
3/26/2019	PW	215	Preventive maintenance service. Sway bar bushing replaced. Driver upper control arm replaced.	4.5	\$186.93	T
3/26/2019	Police	4198	Started taking intake manifold off and bank 1 cat.	1.75	\$0.00	T
3/26/2019	PW	115523	Start and let run.	0.25	\$0.00	T
3/26/2019	PW	37	Clean dirt out of transmission belly pan. Drain transmission fluid. Remove and reseal transmission solenoid control valves. Change transmission fluid and filter.	6.5	\$93.51	D
3/26/2019	PW	107	Rebuild under carriage. Paint rails. Clean up rock guards.	5	\$0.00	J
3/26/2019	Rec	78	Lube all door and window seals with silicone spray. Complete off lift inspection.	1.5	\$12.50	J
3/27/2019	PW	113	Troubleshoot electrical problem at water pumps. Found faulty selector switch. Lubed sticking throttle cable.	2	\$0.00	D
3/27/2019	Fire	Saw #2	Replaced fuel lines, spark plug and intake gaskets. Tested unit.	1	\$24.24	D
3/27/2019	PW	Chainsaw	Removed leaking fuel lines, drained fuel tank.	0.5	\$0.00	D
3/27/2019	Police	1802	Put new catalytic converter in. Chased threads on studs. Replaced pcm control relay. Test drove.	2.5	\$235.69	T

FLEET STATUS REPORT

8/7/2019

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
3/27/2019	PW	207	Replaced plow plug end on the truck side.	0.5	\$80.69	T
3/27/2019	PW	888	Dropped off and picked up vehicle from Creekside.	2	\$270.00	D,J,T
3/27/2019	PW	40	Preventive maintenance service. Picked up parts at Advance Auto.	2.5	\$45.86	T
3/27/2019	PW	Shop	Went to hardware store to get key tags.	0.5	\$0.00	T
3/27/2019	PW	107	Paint undercarriage parts. Repaired spring boxes.	8.5	\$0.00	J,D
Total Hours Worked				84		
Time Off (e.g., sick, vacation, etc....)				56.00		
Misc. Time (e.g., Class, CDL Drug Test, etc....)						
TOTAL HOURS				140.00		
TOTAL PARTS COST					\$1,308.91	