

FLEET STATUS REPORT

7/30/2019

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
7/18/2019	PW	26	Troubleshoot air conditioning not working. Found leak at receiver dryer and condenser. Started replacing dryer.	2.5	\$214.64	D,T
7/18/2019	PW	26	Preventive Maintenance Service. Check out oil leak. Turbo return lines leaking at o-rings.	2.5	\$232.30	D
7/18/2019	PW	T-0	Replaced lower feed wheel drive motor.	2	\$777.24	D
7/18/2019	PW	211	Picked sweeper and parts up at DeHart. Truck was dead they had to charge it.	6	\$0.00	T,DD
7/18/2019	Police	1816	Preventive Maintenance Service. Checked tpms system.	2	\$35.42	T
7/18/2019	PW	285	Jump started and charged.	0.5	\$0.00	T
7/18/2019	PW	22	Charged air conditioning.	0.5	\$6.10	T
7/18/2019	PW	217	Tore down driver's side front axle for ball joints.	2.5	\$163.29	J
7/18/2019	PW	29	Replaced inner belt tensioner. Hunter sent wrong part. Reordered.	3.5	\$215.00	J,D
7/18/2019	Water	64	Preventive maintenance service.	2	\$39.35	J
7/18/2019	PW	37	Aired out and washed out radiator, condenser, transmission cooler. Power washed.	6.5	\$0.00	W
7/19/2019	Fire	1604	Repair RR tire and check others.	1	\$1.50	T
7/19/2019	PW	8	Broken brake line on rear, check front end.	2	\$0.00	T
7/19/2019	PW	105	Troubleshoot turn signals and check all lights.	1.5	\$0.25	T
7/19/2019	Police	1806	PM Service, Scan TPMS system.	2	\$35.42	T
7/19/2019	Fire	Saw 2	Replace bar oil cap, check choke operation remove decompression valve.	1	\$4.49	D
7/19/2019	Fire	Saw 3	Replace gas and oil caps, check choke operation.	1	\$4.49	D
7/19/2019	Water	68	Replace RF tire and re-install.	1	\$145.53	D
7/19/2019	PW	26	Replace turbo oil o-rings, replace A/C condensor.	3.5	\$741.03	D
7/19/2019	PW	T-1	Plug RF tire.	0.5	\$0.99	W
7/19/2019	PW	112	Repair Tow/Haul button.	0.5	\$0.00	W
7/19/2019	Water	71	PM Service, Scan TPMS system.	2	\$29.72	W
7/19/2019	PW	11	Road Test, Clean brake slides.	1.5	\$0.00	W
7/19/2019	PW	22	Power wash truck.	1.5	\$0.00	W
7/19/2019	PW	Shop	Put tires away in conex.	0.5	\$0.00	W
7/22/2019	PW	217	Replace RS upper and lower ball joints.	2	\$163.29	J
7/22/2019	PW	107	Road Call: PL Firehouse. Jump dozer.	1	\$0.00	W
7/22/2019	PW	22	PM Service, Work on rear lights.	5.5	\$167.02	W

FLEET STATUS REPORT

7/30/2019

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
7/22/2019	PW	26	Re-install A/C box, check for leaks, Charge A/C, repair door light switch.	2.5	\$9.32	D,DD
7/22/2019	PW	211	Replace fan shaft bearings and fan assembly.	9	\$1,426.00	D,J
7/23/2019	PW	4	No Speedodometer: check and order new rear speed sensor.	2	\$0.00	D
7/23/2019	PW	211	Pressure wash, re-install water tanks, grease complete unit.	4.5	\$0.00	D,J,W
7/23/2019	PW	12	Road Call: Country Lakes, unit stalling , tow back to shop.	2	\$0.00	D,T
7/23/2019	PW	8	Remove rusted brake line to make a new one.	1	\$0.00	T
7/23/2019	Police	1806	Install new A/C belt and install new radar bracket.	1.5	\$19.46	T
7/23/2019	Fire	1605	PM Service, repair headlight wiring, order A/C parts.	3.5	\$42.03	T,DD
7/23/2019	PW	Generator	Check all fluid levels, Fill with fuel and adjust fuel gauge float.	2.5	\$0.00	W,J
7/23/2019	PW	6	Drain brine tank and strap on to truck.	2	\$0.00	J,W
7/23/2019	PW	22	Replace Air Filter and continue to work on tail lights.	1.5	\$112.55	W
7/23/2019	PW	38	Clean fan shroud, radiator install oil cooler (wrong cooler, correct one ordered)	4.5	\$0.00	J,D
7/23/2019	PW	217	Finish ball joints on RF and install new 4WD hubs.	2.5	\$259.58	J,W
7/24/2019	PW	32	Front and rear brake job. Replace LS caliper and bleed system	6	\$341.09	W
7/24/2019	PW	Shop	Went to office to see Tom.	1	\$0.00	W,DD
7/24/2019	PW	Fire	Replace door linkage clip so door will open.	2.5	\$0.35	D,T,DD
7/24/2019	PW	107	Road Call: Evergreen, jumpstart Dozer.	1	\$0.00	D
7/24/2019	Fire	1615	Get info off of broken mirror to be replaced.	0.5	\$0.00	D
7/24/2019	PW	66	Road Call: PL Firehouse, check hydraulic leak.	1	\$0.00	T,D
7/24/2019	PW	B&G	Road Call: PL Fire house, Hook up water pump to water tank.	0.5	\$0.00	D
7/24/2019	Fire	1612	Remove broken U-Bolts on rear axle to get sized for new ones.	4	\$0.00	D,T
7/24/2019	Police	1816	Check front end noise, Bad steering rack, parts on order.	0.5	\$0.00	T
7/24/2019	PW	204	Replace RR tail light assembly.	0.5	\$14.95	T,D
7/24/2019	PW	105	Replace flasher relay.	0.25	\$103.55	T
7/24/2019	PW	8	Put new brake line on and bleed system.	1.5	\$12.50	T,J
7/24/2019	Fire	1605	Replace A/C dryer, orifice tube and low pressure switch. Recharge system.	1	\$96.17	T
7/24/2019	PW	36	Replace sway bar bushings, start to replace shocks.	2	\$152.69	J,T
7/24/2019	PW	S&R	Load barriers to be returned to United Rental.	0.5	\$0.00	J
7/24/2019	PW	11	Replace RF brake caliper and brake line.	2	\$114.04	J
7/24/2019	PW	38	Clean unit.	1	\$0.00	J

FLEET STATUS REPORT

7/30/2019

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
7/24/2019	PW	24	Replace/Repair chain for tarp system	1	\$0.00	J
7/24/2019	PW	217	Drop off at Craig's for an alignment.	0.5	\$0.00	J,T

Total Hours Worked	124.75
Time Off (e.g., sick, vacation, etc....)	20.00
Misc. Time (e.g., Class, CDL Drug Test, etc....)	4
TOTAL HOURS	<u>144.75</u>
TOTAL PARTS COST	\$5,681.35