

FLEET STATUS REPORT

1/20/2017

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
01/05/17	PW	Shop	To Hainesport Truck for hydraulic hoses.	1.00	\$0.00	C
01/05/17	PW	34	Install plow solinoid, fill with oil.	2.00	\$78.59	C
01/05/17	PW	6	Replace marker light.	0.50	\$4.22	J
01/05/17	PW	plow 10	Add oil.	0.50	\$8.59	J
01/05/17	PW	plow 5	Add oil.	0.50	\$8.59	J
01/05/17	PW	16	No power to plow controller, replace tail light, straighten plow bracket and secure.	3.00	\$55.83	J,C
01/05/17	PW	plow 3	Drill holes for saftey pins on plow bracket, install pins.	0.50	\$6.27	J
01/05/17	PW	plow 102	Drill holes for saftey pins on plow bracket, install pins.	0.5	\$6.27	J
01/05/17	PW	plow 14	Drill holes for saftey pins on plow bracket, install pins.	0.5	\$6.27	J
01/05/17	PW	plow 15	Drill holes for saftey pins on plow bracket, install pins.	0.5	\$6.27	J
01/05/17	PW	21	Replace blown hydraulic hose on spreader, adjust spreader cable.	1.5	\$70.20	D,J
01/05/17	PW	25	Repair plow lights.	1	\$0.00	D
01/05/17	PW	3	Hook up plow, check out plow and truck.	2	\$0.00	D,C
01/05/17	PW	14	Hook up plow, check out plow and truck.	2	\$0.00	D,C
01/05/17	PW	Shop	Set up electrical wire rack with new supplies for use.	1	\$0.00	D
01/05/17	PW	PTPD 2	Jump start and get running.	0.5	\$0.00	D
01/05/17	PW	T-3	Jump start and get running, replace L.S. tail light bulb.	0.5	\$1.49	D
01/05/17	Water	65	Straighten mounting bracket for spreader and hydraulic hose.	1	\$63.90	D
01/06/17	PW	25	Repair and replace plow light wiring.	2.5	\$2.06	D
01/06/17	PW	24	Repair wiring harness for PTO and plow lights, replace 1 hydraulic hose, adjust brakes.	3.5	\$43.09	D,J,C
01/06/17	PW	26	Replace bolt on spreader collar, clean out window washer hoses.	1	\$0.20	D
01/06/17	PW	38	Replace R.R. tire.	1	\$732.95	D
01/06/17	PW	31	Install new altenator on unit, check starting and charging systems.	0.5	\$195.00	J
01/06/17	PW	17	Drill holes for saftey pins on plow bracket, install pins.	0.5	\$6.27	J
01/06/17	PW	21	Repair broken plow chain. (Road Call)	1.5	\$0.00	J,C
01/06/17	PW	29	Lube tail gate handle and linkage.	0.5	\$0.00	J
01/06/17	PW	101	Drill holes for saftey pins on plow bracket, install pins, Change tail light bulb, remount strobe light switch.	0.5	\$6.27	J
01/06/17	PW	24	Replace head light breaker.	0.5	\$8.34	J
01/06/17	PW	plow 4	Refurb plow face.	2	\$0.00	J
01/06/17	PW	11	Install wiper motor and transmission.	1.5	\$215.89	J
01/06/17	Police	1811	Remove metal ring binding steering rack.	2	\$0.00	C
01/06/17	Police	1819	Replace head light bulb.	0.5	\$9.59	C
01/06/17	PW	13	Jump start.	0.5	\$0.00	C
01/06/17	PW	Shop	Clean shop, take out trash, drain oil drum.	2	\$0.00	C,J

FLEET STATUS REPORT

1/20/2017

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
01/07/17	PW	27	Repair plow lift control cable.	2	\$0.00	C,D
01/07/17	PW	101	Replace wiper blades.	0.5	\$34.97	C,D
01/07/17	PW	5	Replace wiper blades.	0.5	\$23.48	C,D
01/07/17	PW	23	Replace wiper blades, Install spacer clamp on spinner.	1	\$5.26	C,D
01/07/17	PW	18	Issue snow scraper to vehicle.	0.25	\$11.49	C,D
01/07/17	Water	67	Replace wiper blades.	0.5	\$23.48	C,D
01/07/17	Water	70	Replace wiper blades.	0.5	\$23.48	D,C
01/07/17	PW	102	Issue snow scraper to vehicle.	0.25	\$11.49	C,D
01/07/17	PW	24	Install bolt for salt box bracket.	1	..40	C,D
01/07/17	Water	65	Road Call: Replace bolt on L.S plow leg.	4	\$0.00	C,D
01/07/17	PW	4	Replace batteries.	2	\$111.09	C,D
01/07/17	PW	23	Repair air line for drivers seat, reset R.F. LED light, check blower motor.	2.5	\$0.00	C
01/07/17	Police	1805	Replace L.F. head light bulb.	0.5	\$12.58	C
01/09/17	PW	plow 4	Straighten and weld in new metal.	6	\$0.00	J
01/09/17	PW	SB 2	Rewrap pull cord, tighten carb bowl, reattach carb cover.	0.5	\$0.00	J
01/09/17	PW	plow 65	Drill holes for saftey pins on plow bracket, install pins.	0.5	\$15.77	J
01/09/17	PW	11	Check wiring for wiper motor.	1.5	\$0.00	C,D
01/09/17	PW	3	Drain plow oil and refill will new oil.	1	\$0.00	C
01/09/17	PW	101	Install hydraulic hose and top off oil.	1.5	\$60.37	C
01/09/17	PW	29	Pick up from Hunter International	5	\$0.00	C,DD
01/09/17	Police	18Q1	Get running for use. Had electrical wires melting after start up?	2	\$0.00	D,C
01/09/17	PW	14	Install wiper blades	0.25	\$12.49	PS
01/09/17	PW	25	Replace 2 spreader hoses and 2 hydraulic couplers.	2	\$143.95	D
01/09/17	PW	21	Replace 4 hydraulic couplers at spreader hoses.	2.5	\$29.33	D
01/10/17	Fire	1603	Jump start, bring back to twp.(BMFC does not want it)	1	\$0.00	C,DD
01/10/17	PW	101	Replace L.R. brake light bulb.	0.5	\$1.59	C
01/10/17	PW	34	Fill up transport fuel tank, rewire tail lights, installed new plow pins.	5	\$5.50	C
01/10/17	PW	23	Jump start.	0.5	\$0.00	C
01/10/17	Water	67	Test block heater,(good) replace air tank strap on R.S.	3	\$40.56	D
01/10/17	PW	old 63	check charging and starting systems, replace altenator and recheck system.	1.5	\$156.99	D
01/10/17	PW	plow 18	weld and repair center pin looseness on plow.	4	\$0.00	J,D
01/10/17	PW	12	Thaw out plow motor and pump.	0.5	\$0.00	J
01/10/17	PW	5	Clean and lube all plow solinoids and electrical connections, install plow pins.	1.5	\$6.27	J
01/10/17	PW	21	Install new engine block heater and refill cooling system with coolant.	1	\$73.10	DD
01/10/17	PW	SB 1	Install new drive belts on snow blower.	1	\$8.18	Rob

FLEET STATUS REPORT

1/20/2017

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
01/10/17	Police	1855	Clean out ducts and check operation of heat vents.(will probably need dash and heater box removed to clean out dog hair build up.)	1	\$0.00	J
01/11/17	PW	SB 3	Repair pull cord on unit.	0.5	0	C
01/11/17	Fire	1618	Install thermostat and refill system with coolant.	2.5	13.26	C
01/11/17	PW	27	Replace R.F. hub cover and refill with oil.	1	27.89	D
01/11/17	Police	1851	Check engine light on: Scan computer, replace B2,S2 oxygen sensor.	1.5	39.99	D
01/11/17	PW	18	Install repaired plow on truck, replace 1 plow light.	3	0	D,C
01/11/17	PW	SB 2	Replace shear bolts on auger.	0.5	0.2	D
Total Hours Worked				97.25		
Time Off (e.g., sick, vacation, etc...)				12		
Misc. Time (e.g., Class, CDL Drug Test, etc...)				0		
				TOTAL HOURS	109.25	
				TOTAL PARTS COSTS	\$2,347.57	