

FLEET STATUS REPORT

2/8/2018

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
01/04/18	PW	Shop	Fabricate hydraulic anchor fixture for rear hitch mount.	5.00	\$0.00	D,J
01/04/18	PW	4	Repair plow harness plug on plow that would not raise.	1.50	\$0.00	D
01/04/18	PW	27	Repair broken wires for sanding work light.	0.50	\$0.00	D
01/04/18	Water	65	Replace blades.	0.50	\$25.90	D
01/04/18	PW	31	Check right rear tire that was flat. Outter rim ring leaking. Air up tires.	0.50	\$0.00	D
01/04/18	PW	23	Replace wiper blades. Repair window washer hose.	0.50	\$9.98	D
01/04/18	PW	101	Troubleshoot plow not going up intermittently.	1.00	\$0.00	D
01/04/18	PW	10	Replace passenger side plow marker.	0.50	\$11.29	T
01/04/18	Water	67	Driver wiper replaced and swapped driver to passenger side.	0.50	\$4.99	T
01/04/18	Police	1802	Top washer fluid off. Replace driver side wiper.	0.50	\$12.49	T
01/04/18	PW	204	Replace wipers.	1.00	\$7.58	T,J
01/04/18	PW	280	Replace wiper blades.	0.50	\$7.58	T
01/04/18	Police	1812	Removed radio and moved around wires. Check all breakers and hoses.	2.00	\$0.00	T
01/04/18	PW	Shop	Go to Clydesdale for gas and oxygen.	2.50	\$0.00	J
01/04/18	PW	Shop	Snow blower-restrung recoil starter and got running.	1	\$0.00	J
01/04/18	PW	21	Running rough.	1	\$17.98	J,D
01/04/18	PW	25	No spreader work light. Headlights not staying on.	1.5	\$9.98	J
01/04/18	PW	4	Replace wiper blade.	0.5	\$4.99	J
01/04/18	PW	21	Jump start. Install wiper blades.	2	\$21.78	J,T,D
01/04/18	PW	26	Replace wiper blade.	0.5	\$0.99	J
01/05/18	PW	11	Check plow. Replace plow oil.	0.5	\$15.98	D
01/05/18	PW	18	Check tail lights not working - replace fuse.	0.5	\$0.00	D
01/05/18	PW	207	Troubleshoot plow angling by itself. Found bad driver side angle cylinder, took cylinder apart. Replaced cylinder.	2.5	\$145.74	D,T
01/05/18	PW	207	Replace wiper blades.	3	\$18.76	D,J,T
01/05/18	PW	24	Adjust rubber for plow. Put new marker on passenger side plow.	1	\$16.00	T
01/05/18	PW	102	Replaced wipers and driver side plow marker. Got spreader motor started.	2	\$23.28	T,J
01/05/18	PW	29	Replaced passenger side plow marker.	0.25	\$15.79	T
01/05/18	Police	1808	Changed wiper blades.	0.5	\$32.48	T
01/05/18	PW	101	Replaced plow controller after troubleshooting. Pick up controller.	1.5	\$0.00	J
01/05/18	PW	21	Air leak.	2	\$0.00	J
01/05/18	PW	Shop	Clean shop.	2.5	\$0.00	J,T,D

FLEET STATUS REPORT

2/8/2018

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
01/05/18	PW	1816	Take to Medford Ford for recall.	2	\$0.00	T,J
01/05/18	PW	208	Towed into shop. Replaced starter with new and retrim electrical connection on wire for starter.	2.5	\$175.00	T,D
01/08/18	PW	5	Put right front tire in water tank to find slow leak. Plugged tire.	1	\$0.00	T
01/08/18	Police	1842	Vehicle broke down at Mid Town Plaza. Was low on oil filled it up, took back to shop.	2	\$0.00	T
01/08/18	PW	27	Replaced passenger side plow marker.	0.5	\$31.58	T
01/08/18	PW	21	Adjust all four air brakes and fill front tires up.	1	\$0.00	T,D
01/08/18	PW	Shop	Repair shop space heater that was not running.	1	\$0.00	D,T
01/08/18	PW	26	Get unit running that was not plugged in.	1	\$8.36	D,T
01/08/18	PW	104	Get unit running - battery was dead.	1	\$0.00	D,T
01/08/18	PW	51	Preventive maintenance service.	1.5	\$19.57	D
01/08/18	PW	29	Changed wiper blades.	0.5	\$31.58	DL
01/08/18	PW	23	Charge batteries, get running.	0.5	\$0.00	D
01/08/18	PW	207	Check plow that would not angle. Remove and take apart right hand angle cylinder, found blown seals.	2.5	\$0.00	D,T
01/09/18	Fire	1801	Poured water on light bar to find which lights were bad. Needs new bar light.	0.5	\$0.00	T
01/09/18	Police	1815	Replaced rusted brake lines.	2	\$0.00	D
01/09/18	Police	Q2	Get unit running, check over unit for snow removal.	1	\$0.00	D
01/09/18	Fire	1836	Rear hub cap nut missing. Replace rear back up light assembly, repaired rear inside tire.	4	\$53.47	D,J
01/09/18	PW	6900	Get running, bring in shop, start to change batteries.	2.5	\$770.16	J
01/09/18	Fire	1815	Junction Box works, bulb was blown.	4	\$1.59	D,J
01/09/18	Fire	1811	Get information off tank gauge. Stripped screw in utility light that is out.	1	\$0.00	J,D
01/09/18	PW	SB-2	Recoil broken.	0.5	\$0.00	J
01/09/18	Police	1842	Preventive maintenance service.	2	\$35.27	T
01/09/18	Police	1806	Preventive maintenance service.	2	\$34.57	T
01/09/18	Fire	1801	Replace transmission line and clear codes for transmission.	1	\$10.20	T
01/10/18	Fire	1891	Pick up unit that was dead at Browns Mills Fire Dept. Charge and load test all batteries. Check rear left light out at rear light bar, take apart light bar and found broken wire, repair harness and reassemble. Deliver to Browns Mills Fire Dept.	4	\$1.99	T,D
01/10/18	PW	4	Added plow oil	0.5	\$7.99	D

FLEET STATUS REPORT

2/8/2018

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
01/10/18	Police		Went to Medford Ford to pick up 1816 and drop 1812 off. Door panel was not put back right, had to wait for them to fix.	1.5	\$0.00	T
01/10/18	PW	6900	Get ready for driver test.	7.5	\$67.60	J,D
01/10/18	PW	Shop	Dump trash and clean.	1.5	\$0.00	T
01/10/18	PW	104	Plug front left tire.	0.5	\$0.99	T
01/10/18	Police	1812	Radio is out of range. Computer was charging.	1	\$0.00	T
01/10/18	Police	1804	Put glove holder in rear.	0.5	\$0.00	T
01/10/18	Police	1816	Put glove holder in the rear.	0.5	\$0.00	T
01/10/18	Police	1815	Replace rusted brake lines.	1	\$0.00	D
Total Hours Worked				95.75		
Time Off (e.g., sick, vacation, etc....)				52.00		
Misc. Time (e.g., Class, CDL Drug Test, etc....)						
TOTAL HOURS				147.75		
TOTAL PARTS COST					\$1,653.48	