

FLEET STATUS REPORT

2/8/2018

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
01/11/18	PW	T25	Wire front marker lights. Check over all lights and tires for drivers' test.	2.00	\$9.70	J
01/11/18	PW	6900	Get ready for driving test.	2.50	\$22.41	J
01/11/18	Police	Shop	Drop off 1805 for recall and pick up 1812.	1.00	\$0.00	T
01/11/18	Police	1808	Replaced passenger side blinker bulb.	0.50	\$1.83	T
01/11/18	PW	36	Repaired door. Repaired driver side inside handle. Troubleshoot flasher relay board. Replaced flasher relay, ordered parts.	5.50	\$9.69	T
01/11/18	PW	Shop	Pulled forklift out.	0.50	\$0.00	D
01/11/18	PW	26	Check hesitation. Check out temperature gauge not working. Unit is not making heat, faulty engine thermostat. Remove and replace thermostat and housing gasket.	4.00	\$94.12	D
01/11/18	AC	43	Replace wiper blades.	0.50	\$8.74	D
01/11/18	Police	18Q2	Remove broken tire chains, drain carburetor. Fill with fuel and add stabilizer.	1.00	\$0.00	D
01/12/18	PW	6900	Replaced windshield wipers.	0.25	\$9.98	B
01/12/18	PW	207	Replace passenger side angle cylinder. Drill plow blade and install rubber deflector. Road call to Four Mile Road. Passenger front wheel locked up. Bring back to shop and troubleshoot.	2.00	\$230.61	D
01/12/18	PW	36		2.00	\$0.00	D,T
01/12/18	PW	26	Replace thermostat and test drive.	1.50	\$0.00	D
01/12/18	PW	Shop	Move shop equipment for new light fixture installation.	1.00	\$0.00	J,D
01/12/18	Police	1805	Picked up from Medford Ford for recall.	2	\$0.00	T,D
01/12/18	Police	1802	Preventive maintenance service. Install rubber glove holder.	2.5	\$25.81	T
01/12/18	Police	1814	Put rubber glove holder in rear.	0.5	\$0.00	T
01/12/18	Police	1820	Put rubber glove holder in rear. Open all doors and blew out dog hair and cleaned doors and dash.	1	\$0.00	T
01/12/18	PW	Shop	Truck 24 plow - flipped rubber edge, greased gauge wheels.	1	\$0.00	J
01/12/18	PW	Shop	Truck 22 plow - adjust rubber edge, greased gauge wheels.	0.5	\$0.00	J
01/12/18	PW	Shop	Truck 27 plow - Replace rubber edge grease gauge wheels.	1	\$330.00	J
01/12/18	PW	Shop	Truck 26 plow - flip rubber edge, tighten gauge wheel bolts.	1	\$0.00	J
01/12/18	PW	Shop	Truck 28 plow - flip rubber, grease wheels.	1	\$0.00	J
01/12/18	Water	Shop	Truck 67 plow - replace 10 ft.. Rubber, replace markers.	2	\$376.50	J
01/16/18	PW	29	Repair passenger side tail light. Replace spreader light.	0.5	\$0.00	T
01/16/18	Police	1811	Preventive maintenance service.	2	\$27.80	T

FLEET STATUS REPORT

2/8/2018

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
01/16/18	Police	1851	Preventive maintenance service. Took to inspection.	3	\$38.95	T
01/16/18	Police	1816	Troubleshoot check engine code, test drive, installed transmission fluid.	1	\$7.65	T
01/16/18	PW	22	Troubleshoot pushing water out of overflow tank, smells of diesel fuel.	1	\$0.00	J
01/16/18	PW	25	Checked plow frame on truck.	0.5	\$0.00	J
01/16/18	PW	21	Change plow rubber edge.	2	\$330.00	J
01/16/18	PW	23	Repair air leak.	2	\$83.34	J
01/16/18	PW	Shop	Sweep up shop and dump trash and scrap metal.	3	\$0.00	D,J,T
01/16/18	PW	36	Start replacing engine oil pan and gasket.	3.5	\$0.00	D
01/16/18	Fire	1801	Check over unit that has no high gear.	1	\$0.00	D
01/16/18	PW	37	Replace blade cutting edges.	2	\$206.28	D,J
01/16/18	PW	27	Added windshield wiper fluid.	0.5	\$1.99	B
			Replace engine oil and pan and gasket. Replace exhaust manifold y-pipe studs.			
			Replace front brake calipers, front brake hoses and pads. Bleed brakes.			
01/17/18	PW	36	Preventive maintenance service.	7	\$266.84	D,T
01/17/18	Fire	1802	Pick up from Browns Mills Firehouse. Repaired brake line. Replaced front pads.	4	\$60.62	T,J
01/17/18	Police	1801	Balanced and replaced tire.	1	\$136.00	T
01/17/18	Police	1805	Check fuses. Replaced and repaired wiper. Replaced bulb.	1.5	\$14.68	T
01/17/18	Police	1809	Replaced wipers and added washer fluid.	0.5	\$6.98	T
01/17/18	PW	Shop	Picked up parts from DeHarts.	2.5	\$0.00	J
			Troubleshoot, running poorly. Cleaned EGR 2 intake. Checked all hose connections. Replaced wiper blades.	2	\$19.97	J
01/17/18	PW	22	Install antifreeze. Take to Johnson and Towers for Repair estimate.	1	\$3.74	J
01/17/18	PW	SB2	Replaced recoil starter on snow blower.	1	\$0.00	J
			Total Hours Worked	79.25		
			Time Off (e.g., sick, vacation, etc....)	42.00		
			Misc. Time (e.g., Class, CDL Drug Test, etc....)			
			TOTAL HOURS	121.25		
			TOTAL PARTS COST		\$2,324.23	