

FLEET STATUS REPORT

2/16/2018

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
02/08/18	PW	Shop	Emptied shelf and moved tools.	0.50	\$0.00	J
02/08/18	PW	T-31	Welded holders and replaced teeth at Country Lakes.	1.50	\$19.22	D
02/08/18	Police	old 1802	Jump started and moved.	0.50	\$0.00	T
02/08/18	PW	18	Plugged block heater in. Jump started.	0.50	\$0.00	T
02/08/18	PW	Shop	Went to O'Brien and Son and had keys made. Picked up parts at Advance.	2.00	\$0.00	DD,T
02/08/18	PW	Shop	Moved stuff to new shop/parts room.	6.00	\$0.00	T,D
02/08/18	PW	99	Installed seven pin trailer plug.	2.00	\$0.00	J
02/08/18	PW	T-31	Replaced plug for lights.	1.00	\$9.99	J
02/08/18	PW	6900	Troubleshoot. Replaced air filter on air dryer.	6.00	\$36.25	J,D
			Replaced headlight. Test drove, found rear wheel bearing is bad and front sway bar links are bad. Removed and replaced headlight, wheel bearing and sway bar link.			
02/09/18	Police	1811		5.00	\$204.33	DD,T
02/09/18	PW	Shop	Had keys made for new bucket truck and ordered and picked up parts for shop.	1.50	\$0.00	T
02/09/18	Water	63	Fixed fuel filler neck.	0.50	\$0.00	T
02/09/18	PW	Shop	Picked up parts at Jesco and Lucas Dodge.	2.00	\$0.00	D,DD
02/09/18	PW	T-31	Road call. Replaced 10 teeth and checked loose skids.	1.50	\$0.00	D
			Road call to Sheep Pen Hill Road. Troubleshoot transmission oil leak. Ordered parts for blown transmission filter housing pressure line.			
02/09/18	PW	37		2.00	\$0.00	D,DD
			Preventive maintenance service. Extracted stripped engine oil drain plug. Started service on transmission that was slipping.			
02/09/18	PW	old 1803		2.00	\$27.78	D
			Replaced transmission filters, pan gasket and fluid. Swapped driver side front tire with passenger side rear tire to isolate front end noise. Slipping in high gear.			
02/12/18	Water	old 1803		2.50	\$65.83	D,T
12/12/18	PW	31	Removed left hand lift cylinder and took apart for rebuild.	6.50	\$0.00	D,T,J
02/12/18	Rec	75	Jump started at Country Lakes Recreation.	0.50	\$0.00	T
02/12/18	PW	Shop	Dumped shop truck.	0.50	\$0.00	T
			Charged battery. Put on new valve system in right rear tire and sealed the bead.			
02/12/18	Admin	2	Topped coolant off.	1.00	\$0.00	T
02/12/18	Fire	1818	Troubleshoot braking hard. Had rust from rain. Test drove.	0.50	\$0.00	T
02/12/18	Police	1820	Preventive maintenance service. Changed/cleaned cabin filter.	2.50	\$33.93	T
02/12/18	PW	37	Picked up parts from Giles and Ransome	2.00	\$119.27	J

FLEET STATUS REPORT

2/16/2018

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
02/12/18	Water	69	Road call to Browns Mills, jump started.	1.00	\$0.00	J
02/12/18	PW	23	Jump started. Load tested batteries. Checked charging system. Swapped out batteries with good used ones.	2.00	\$0.00	J
02/13/18	Fire	1801	Removed light bar from old stock car and installed.	4.50	\$5.58	T
02/13/18	Police	1802	Troubleshoot. Fixed door lock.	1.00	\$115.35	T
02/13/18	PW	31	Resealed two lift cylinders.	8.00	\$678.06	D,T,J
02/13/18	PW	Shop	Fabricate grate for storm drain.	2.00	\$0.00	J
02/13/18	Water	69	Replaced battery and checked codes.	3.00	\$0.00	J
02/13/18	PW	6900	Checked charging system.	1.00	\$0.00	J
02/14/18	PW	31	Reseal loader lift cylinder and reassemble. Grind out cracked bucket coupler.	8.00	\$90.60	D,T,J
02/14/18	PW	Shop	Notched the back of a toilet for plumbing with grinder - stainless steel toilet.	1.00	\$0.00	J
02/14/18	PW	37	Replaced transmission cooler line. Repack hydraulic cylinder.	5.50	\$197.76	J, D,T
02/14/18	Fire	1801	Charged battery. Wired up light bar. Wired up lights in back window and front grill.	4.50	\$0.00	T
02/14/18	PW	Shop	Put center console back together.	0.50	\$0.00	T
			Total Hours Worked	92.50		
			Time Off (e.g., sick, vacation, etc....)	18.00		
			Misc. Time (e.g., Class, CDL Drug Test, etc....)			
			TOTAL HOURS	110.50		
			TOTAL PARTS COST		\$1,603.95	