

FLEET STATUS REPORT

2/23/2018

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
02/15/18	Police	1801	Replaced driver side headlight.	0.50	\$9.69	T
02/15/18	Police	1833	Troubleshoot running rough.	1.50	\$0.00	T
02/15/18	Police	1807	Replaced wipers and filled up washer fluid.	1.00	\$26.97	T
02/15/18	Water	69	Diagnosed, removed and replaced.	1.50	\$154.14	T
02/15/18	Water	71	Removed tire, grinded inside and patched.	1.00	\$2.99	T
02/15/18	Police	1814	Preventive maintenance service.	2.00	\$34.56	T
02/15/18	PW	31	Welded cracked bucket coupler. Welded worn down bucket stops. Preventive maintenance service.	4.00	\$212.90	D
02/15/18	PW	21	Removed and replaced spreader control valve in cab.	2.00	\$0.00	J,D
02/16/18	PW	31	Finished preventive maintenance service.	2.00	\$45.71	D
02/16/18	PW	109	Troubleshoot unit, would crank; but not start. Repaired wire harness.	2.00	\$0.00	D,T
02/16/18	PW	Shop	Moved bolt bins, took wall down and moved shop stuff around. Measured truck and fire trucks.	13.50	\$0.00	D,T,DD
02/16/18	Police	1801	Preventive maintenance service.	2.00	\$32.57	T
02/20/18	PW	T-31	Welded on two holders. Replaced six teeth.	2.00	\$69.96	D
02/20/18	PW	207	Preventive maintenance service. Repaired flat tire.	2.00	\$34.83	D
02/20/18	Fire	1832	Went to Country Lakes Firehouse for low tire, took unit to Tri-State. Picked up unit from Tri-State and delivered to Country Lakes Firehouse.	2.00	\$0.00	D,DD
02/20/18	PW	22	Picked up unit from Johnson and Towers. Checked over.	3.00	\$0.00	D,DD
02/20/18	Police	1806	Preventive maintenance service. Took apart center console to move speaker next to passenger seat shoulder, swapped mic holders.	3.00	\$30.57	T
02/20/18	Police	1814	Put evap lines in place and fit plastic cover.	2.00	\$0.00	T
02/20/18	Police	1816	Removed driver rear door panel and pulled dent out. Checked engine codes.	1.50	\$0.00	T
02/21/18	PW	102	Removed tires with sledge hammer, took tires off, balanced and put on new tires. Put front and rear brake pads on. Preventive maintenance service. Checked over for inspection.	5.50	\$732.22	T
02/21/18	PW	15	Jump start.	0.50	\$0.00	T
02/21/18	Fire	1836	Road call to Country Lakes Firehouse. Troubleshoot pump primer not working.	1.50	\$0.00	D
02/21/18	PW	211	Serviced pony engine oil and filter.	1.50	\$35.40	D
02/21/18	Fire	1804	Preventive maintenance service. Repaired horn.	2.50	\$35.15	D,T

FLEET STATUS REPORT

2/23/2018

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
02/21/18	PW	21	Replaced auger/spinner control valve inside cab.	1.00	\$0.00	D
			Total Hours Worked	61.00		
			Time Off (e.g., sick, vacation, etc....)	30.00		
			Misc. Time (e.g., Class, CDL Drug Test, etc....)			
			TOTAL HOURS	91.00		
			TOTAL PARTS COST		\$1,457.66	