

FLEET STATUS REPORT

2/24/2017

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
02/16/17	Police	1816	PM Service, mount and balance 1 tire.	2.50	\$163.25	C
02/16/17	PW	28	Disconnect battery to try to clear check engine light.	0.50	\$0.00	C
02/16/17	PW	T-31	Road Call: (AM) Unit cutting out and shutting down, clean battery connections and all electrical connections and connectors on machine. Road Call: (PM) Bleed and check fuel system for contamination of dirt or water, nothing found and unit is running and performing.	5.00	\$0.00	DD,C
02/16/17	Police	1802	Start up in morning at check status of battery.	0.25	\$0.00	C
02/16/17	Police	old1802	Jump start, bring back to garage for a evaluation.	0.25	\$0.00	C
02/13/17	Police	old1804	Jump start, bring back to garage for a evaluation.	0.25	\$0.00	C
02/16/17	Police	1804	Start up new unit to check for for battery drain.	0.25	\$0.00	C
02/16/17	PW	12	Find material to repair plow bracket.	1	\$0.00	J
02/16/17	PW	21plow	Flip plow rubber and adjust.	1	\$0.00	J
02/16/17	PW	22plow	Flip plow rubber and adjust.	1	\$0.00	J
02/16/17	PW	29plow	Replace rubber edge on plow.	1	\$325.00	J
02/16/17	Fire	1691	Finish installing front shocks, air up all tires(6)all tires were at 50lbs., go over. Replace R.S. blade tilt and angle hydraulic hoses and lines, clean radiator and coolers in front or unit, recheck for leaks.	2	pre billed	J
02/16/17	PW	107		6.5	\$27.75	DD,C
02/17/17	Police	1808	Check noise and replace front hub wheel bearings.(R&L)	3	\$393.98	D
02/17/17	PW		Diabetes seminar.	2	\$0.00	D,J
02/17/17	Police	1851	Jump start, lubricate and free up hood latch.	1	\$0.00	D,J
02/17/17	PW	37	Check no start, needs starter.	0.5	\$0.00	D
02/17/17	PW	12	Get unit running.	0.5	\$0.00	D
02/17/17	Police	1821	Jump start and get unit running.(has been sitting)	1	\$0.00	D,J
02/17/17	Police	1811	Remove siren/light controller, check for shorts, clean debris out of controller and reinstall in unit.	0.5	\$0.00	D
02/17/17	PW	1872	Check over glow plugs and glow plug circuit for proper operation.	0.5	\$0.00	J
02/17/17	PW	7	Remove damaged bench vise off of rear bumper.	0.5	\$0.00	J
02/17/17	PW	29	Trim tail gate extension to fit properly.	1	\$5.64	J
02/17/17	PW	28	Deliver to Hunter International for warrenty work.	3	\$0.00	J
02/17/17	Police	1816	Check engine light on, scan computer for code, replace bank 1, sensor 2 O2Sensor, clear codes and test drive.	2	\$56.08	C
02/17/17	PW	7	Fuel up unit.	0.25	\$0.00	C
02/17/17	Fire	1603	Fuel up unit.	0.25	\$0.00	C
02/17/17	Fire	1611	Order and replace R.R. marker light.	2	\$33.79	DD,C

**FLEET STATUS REPORT**

2/24/2017

<u>DATE</u>	<u>DEPT</u>	<u>VEHICLE</u>	<u>REPAIR</u>	<u>Hours</u>	<u>Parts Costs</u>	<u>MECH</u>
02/17/17	Fire	1615	Pick up from BMFC, Repair front ladder quartz hologen lights(2), replace bulb in R.S. front ladder spot light, reattach rubber weather stripping to drivers door, return to BMFC.	5	\$15.75	DD,C
02/21/17	PW	107	Road Call: P.L.-Check fuel leak on dozer. Needs fuel pump, must order.	2	\$0.00	D,J
02/21/17	PW	12	Get unit running for use. (block heater was not plugged in over weekend)	0.5	\$0.00	D
02/21/17	Police	1819	Charge battery, check system for drain.	2	\$0.00	D
02/21/17	PW	10	Replace leaking brake line from master cylinder to ABS valve.	2.5	\$20.13	D
02/21/17	PW	1872	Check glow plugs, needs 2. vacuum pump is bad not suppling vacuum to brake booster unit. Remove from another van in parts yard and install on unit.	6	\$19.98	J,D
02/21/17	PW	Shop	To Mt. Holly Kawaski, piuck up parts for #18Q1 and #18Q2 quads.	1	\$0.00	DD
02/21/17	PW	Shop	Drop off #320 for windshield replacement at Creekside Glass.	1	\$0.00	DD,D
02/21/17	PW	Shop	To Groff Case , pick up parts for #107 Case Dozer.	1.5	\$0.00	DD
02/22/17	PW	T-31	Road Call: Replace 9 teeth and 1 holder Road Hog.	2.5	\$141.15	D
02/22/17	PW	107	Road Call: Replace fuel pump on Case Dozer.	2	\$74.09	D,J
02/22/17	Police	18Q2	Replace ignition switch, install guards back onto unit.	1	\$93.46	D
02/22/17	PW	109	Road Call: Install repaired shift lever assembly onto Compac Roller.	1.5	\$0.00	D,J
02/22/17	PW	10	Replace brake line and bleed system.	1	\$5.92	D
02/22/17	PW	1872	Replace vacuum pump with new one. Install 2 glow plugs.	2.5	\$110.99	J,D
02/22/17	PW	320	Pick up from Creekside Glass. (new windshield)	1	\$251.25	DD,J
02/22/17	PW	Shop	Pick up #28 from Hunter International for use on 2/23/17.	3	\$0.00	DD,Crls.
Total Hours Worked				72.50		
Time Off (e.g., sick, vacation, etc...)				16		
Misc. Time (e.g., Class, CDL Drug Test, etc...)						
				<hr/>		
TOTAL HOURS				91.50		
TOTAL PARTS COST					\$1,738.21	