

FLEET STATUS REPORT

3/5/2018

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
02/22/18	PW	21	Troubleshoot spreader not operating properly. Swapped cab control valve, replaced spreader hydraulic motor. Cleaned spool control valve cap.	7.00	\$249.00	D,T
02/22/18	PW	45	Checked out vehicle it needs upper and lower ball joints on both sides.	0.50	\$0.00	D
02/22/18	PW	102	Took truck to inspection.	1.00	\$0.00	T
02/22/18	PW	77	Replaced wiper blades. Took to inspection. Went over bus. Removed rusted metal off of back bumper.	2.00	\$13.68	T
02/22/18	Police	1833	Removed and replaced coil packs. Test drove, rides smooth.	1.50	\$179.99	T
02/22/18	PW	Shop	Picked parts up from auto parts store and picked up 1693 from station 3.	1.00	\$0.00	T
02/23/18	PW	Shop	Cleaned shop. Cut white board and hung up.	2.50	\$0.00	T
02/23/18	Fire	1893	Lubed up side door and all the locks on other doors. Preventive maintenance service. Replaced side flood H.I.D. Took back to station 1	4.50	\$167.20	T,DD
02/23/18	PW	45	Replaced upper and lower ball joints.	6.00	\$166.14	D
02/23/18	PW	105	Get unit running that was dead. Replaced wiper blades.	0.50	\$4.95	D
02/24/18	PW	45	Replaced upper and lower ball joints.	0.50	\$0.00	D
02/24/18	PW	37	Installed lift cylinder seal kit and engine oil.	7.00	\$112.26	D,T
02/24/18	PW	12	Pressure washed engine bay.	0.50	\$0.00	T
02/26/18	PW	45	Replaced driver side ball joints. Replaced right tie rod. Replaced two rear tires. Replaced two rear tail lights and wired reverse lights.	5.50	\$387.95	D
02/26/18	PW	3	Road call to Country Lakes Chippewa Trail, unit needs a starter.	1.00	\$0.00	D
02/26/18	PW	13	Jump started.	0.50	\$0.00	T
02/26/18	Police	1811	Cleared check engine light.	0.50	\$0.00	T
02/26/18	PW	12	Removed and replaced high pressure oil lines for injectors.	2.50	\$278.16	T
02/26/18	Police	1818	Preventive maintenance service. Replaced front right tire.	2.00	\$170.58	T
02/26/18	Police	1804	Jump started, placed on charger.	0.50	\$0.00	T
02/26/18	PW	113	Jump started case roller.	0.50	\$0.00	T
02/27/18	PW	Shop	Removed GPS, batteries and radios from cars going to the junk yard.	4.00	\$0.00	T
02/27/18	PW	23	Would not stay running. Checked out.	1.50	\$12.88	T
02/27/18	Police	1324	Battery checked out good. Charged it for 30 minutes.	1.00	\$0.00	T
02/27/18	PW	Shop	Fabricated metal brackets for garage door opening. Welded brackets for garage door supports.	5.50	\$0.00	D

FLEET STATUS REPORT

3/5/2018

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
02/27/18	PW	25	Tightened loose gland nut on dump body hoist cylinder that was leaking.	1.00	\$0.00	D,T
02/28/18	PW	Shop	Welded garage door tracks together. Fabricated mounting brackets for garage door.	4.00	\$61.47	D
02/28/18	PW	3	Replaced starter.	2.00	\$85.00	D,T
02/28/18	PW	25	Checked oil leak. Test drove. Found transmission was leaking at pan gasket and transmission input seal.	1.00	\$12.99	D
02/28/18	PW	1809	Troubleshoot - lights are out, brakes are good. Front end needs upper control arms and lower ball joints. Ordered parts.	1.00	\$0.00	T,D
02/28/18	PW	Shop	Removed parts from vehicles.	1.00	\$0.00	T
02/28/18	Code	52	Troubleshoot. Preventive maintenance service. Fixed washer motor plug connection.	3.00	\$0.00	T
02/28/18	Water	63	Took to inspection.	1.00	\$0.00	T
Total Hours Worked				73.50		
Time Off (e.g., sick, vacation, etc....)				40.00		
Misc. Time (e.g., Class, CDL Drug Test, etc....)						
TOTAL HOURS				113.50		
TOTAL PARTS COST					\$1,902.25	