

FLEET STATUS REPORT

4/13/2018

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
04/05/18	PW	Shop	Grind brush.	7.50	\$0.00	J,D
04/05/18	Police	1808	Cleaned and put on water pump, gaskets and spark plugs.	6.00	\$133.98	T
04/05/18	Code	90	Preventive maintenance service. Repaired transmission cooler line. Replaced wiper blades and two headlight bulbs. Checked battery and charging system.	3.00	\$67.57	D
04/05/18	Fire	1893	Removed drive shaft, replaced carrier bearing and reassembled. Delivered to Browns Mills Fire Dept.	2.50	\$55.17	D,T
04/06/18	PW	T-31	Removed fuel tank. Removed rotating turret frame from machine to prep for welding repairs.	6.00	\$0.00	D,T
04/06/18	Fire	1811	Check over unit that has check engine light on. Troubleshoot.	1.00	\$0.00	D
04/06/18	Police	1808	Put new belt on and repaired alternator plug. Put fluids in.	2.50	\$31.86	T
04/06/18	Water	162	Removed drive shaft. Pushed out of shop.	1.00	\$0.00	T
04/06/18	Police	1802	Preventive maintenance service. Replaced front tire. Tightened transmission bolt.	3.00	\$23.81	T
04/09/18	Police	1801	Picked up from Medford Ford.	2.00	\$0.00	T,D
04/09/18	Police	1808	Checked timing.	5.00	\$0.00	T
04/09/18	PW	T-31	Welded patches in cutter housing. Welded crack in frame structure.	6.00	\$0.00	D,T
04/09/18	PW	10	Got unit running.	0.50	\$0.00	D
04/09/18	PW	38	Removed front tires for replacement.	0.50	\$0.00	D
04/09/18	Water	68	Installed two batteries.	1.00	\$208.46	DD
04/09/18	Police	1808	Finished installing valve covers, intake and flushed the oil system.	2.00	\$21.81	T
04/10/18	PW	38	Replaced front tires, picked up from Tri-State. Mounted and sealed with new stems.	2.00	\$574.00	D,T
04/10/18	PW	T-31	Welded cracked frame, reassembled pivot frame to chassis. Welded one holder and replaced one tooth.	5.50	\$19.76	D,T,DD
04/10/18	Fire	1811	Deliver to Johnson and Towers.	2.00	\$0.00	T
04/10/18	Police	1805	Preventive maintenance service. Fixed passenger side fog light.	2.00	\$32.57	T
04/11/18	PW	Shop	Cleaned up trash and scrap metal, tires.	1.00	\$0.00	D,DD
04/11/18	PW	27	Checked dump body lever, adjusted cables and straightened bent control valve mounting bracket.	1.50	\$0.00	D
04/11/18	PW	15	Repaired bad wire at back up alarm, replaced driver side back up lamp bulb and replaced cab running light bulb. Picked up parts from Advance Auto	1.50	\$19.12	D

FLEET STATUS REPORT

4/13/2018

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
04/11/18	PW	28	Repaired bent tarp arms.	2.50	\$0.00	D
04/11/18	PW	105	Removed battery and put on charge.	0.50	\$0.00	D
04/11/18	Police	1805	Troubleshoot	3.00	\$0.00	T
			Total Hours Worked	71.00		
			Time Off (e.g., sick, vacation, etc....)	44.00		
			Misc. Time (e.g., Class, CDL Drug Test, etc....)			
			TOTAL HOURS	115.00		
			TOTAL PARTS COST		\$1,188.11	