

FLEET STATUS REPORT

4/25/2018

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
04/11/18	Police	1811	Replaced pig tail and bulb.	1.00	\$10.99	T
04/11/18	Police	1814	Preventive maintenance service. Changed cabin filter.	2.00	\$44.68	T
04/11/18	PW	5	Removed tail light, put new bulb in.	0.50	\$1.99	T
04/11/18	PW	T-3	Jump started.	0.50	\$0.00	T
04/12/18	PW	162	Replaced rear, drive shaft. Repaired fuel leak at fuel rail. Replaced right rear tire. Straightened bent rear leaf spring hanger.	2.50	\$260.04	D
04/12/18	PW	17	Checked for repairs needed on bed; that is badly rusted and falling off.	1.00	\$0.00	D,DD
04/12/18	PW	Shop	Cleaned new shop bay, pressure washed and prepped floor for paint.	10.50	\$20.99	D,DD,T
04/12/18	Police	1808	Diagnosed with bad fuse and relay.	1.00	\$3.99	T
04/12/18	Police	1811	Troubleshoot. Replaced fuse in light.	2.00	\$0.00	T
04/13/18	Police	1816	Preventive maintenance service, replaced cabin filter. Lubed u-joint knuckle on steering column.	2.50	\$37.92	T
04/13/18	PW	Shop	Prepped and painted garage floor.	4.00	\$0.00	T
04/16/18	Fire	1801	Troubleshoot ABS pump motor control, ESP bag light on, traction control light on.	4.50	\$0.00	T,D
04/16/18	Police	1811	Checked over lights, siren, gun holder - all work.	1.00	\$0.00	T
04/16/18	Police	1808	Jumped relays and jumped fan. Ordered fan.	1.50	\$0.00	T
04/16/18	PW	Shop	Repaired tire machine.	0.50	\$0.00	D
04/16/18	PW	62	Preventive maintenance service. Replaced two front brake calipers, cleaned rusty parts. Removed blower motor and cleaned plugged heating ducts and blower fan. Repaired leaking washer bottle. Removed decals.	8.00	\$146.56	D,DD
04/17/18	PW	27	Replaced rear mud flaps. Tried to straighten tarp. Bolted duck tail on body for paving.	2.00	\$30.22	D
04/17/18	PW	162	Replaced left front brake hose, pulled dent from rear of cab.	2.00	\$17.87	D
04/17/18	PW	T-31	Water pump was not priming. Removed water pump. Took pump apart, cleaned and reassembled. Plumbed in line filter screen to stop contamination.	2.00	\$11.84	D
04/17/18	PW	T-2	Aired up tires.	0.50	\$0.00	D
04/17/18	Fire	1801	Pulled all wire to check for shorts, swapped parts from other Dodge, ruled out bad box. ESP/ABS box. Ordered parts, will install and dealer will have to reprogram.	5.00	\$6.99	T

**FLEET STATUS REPORT**

4/25/2018

<b>DATE</b>	<b>DEPT</b>	<b>VEHICLE</b>	<b>REPAIR</b>	<b>Hours</b>	<b>Parts Costs</b>	<b>MECH</b>
04/17/18	Police	1816	Replaced steering column/shaft.	1.50	\$272.56	T
04/18/18	Water	63	Dropped off at Lucas Chevy and picked back up.	4.00	\$0.00	T,D
04/18/18	Police	1811	Preventive maintenance service.	1.50	\$27.80	T
04/18/18	Police	1808	Replaced fans and topped off coolant.	2.00	\$188.00	T
04/18/18	Water	65	Took to inspection.	2.00	\$0.00	T,D
04/18/18	PW	Shop	Moved battery and battery charging system station for shop construction. Ran loader for construction.	2.00	\$0.00	D,DD
04/18/18	Code	52	Checked charging system and load tested battery. Erased codes. Check engine light was on, small evap leak. Test drove.	1.00	\$0.00	D
04/18/18	PW	211	Removed and repaired front spray bar that was cracked. Picked up parts at O'Brien and Sons	2.00	\$9.00	D
Total Hours Worked				70.50		
Time Off (e.g., sick, vacation, etc....)				52.00		
Misc. Time (e.g., Class, CDL Drug Test, etc....)						
TOTAL HOURS				122.50		
TOTAL PARTS COST					\$1,091.44	