

FLEET STATUS REPORT

5/9/2018

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
04/26/18	Police	1807	Removed the rest of the evaporator, installed new and put back together. Hooked up heater core lines, air conditioner lines and intake manifold.	6.00	\$125.41	T,D
04/26/18	PW	36	Replaced driver side rear tail light bulb. Went over all other lights.	0.50	\$1.83	T
04/26/18	PW	30	Replaced two batteries, got unit running. Checked air conditioning and checked lights that were not working.	1.00	\$114.85	D
4/26/208	PW	29	Reinstalled driver side mud flap.	0.50	\$0.00	D
04/26/18	Police	1805	Troubleshoot light bar. Removed light and siren box from console. Checked all power and ground points. Checked all fuses. Removed covers from light bar. Checked all internal fuses, power and ground terminals.	3.00	\$0.00	D
04/26/18	PW	99	Checked bucket for recall.	1.50	\$0.00	D,DD,T
04/26/18	PW	T-2	Troubleshoot lights. Replaced plug.	0.50	\$5.15	D
04/26/18	PW	1821-saw	Checked choke lever. Adjusted chain. Tested unit.	0.50	\$0.00	D
04/27/18	PW	99	Plumbed auxiliary system for working on saws. Fabricated mounting bracket.	2.00	\$34.52	D
04/27/18	PW	30	Troubleshoot lights.	2.50	\$5.99	D,T
04/27/18	Police	1807	Put dash in place.	2.00	\$0.00	T,D
04/27/18	Police	1802	Delivered to Medford Ford for transmission issue.	2.00	\$0.00	T,D
04/27/18	Police	1818	Preventive maintenance service.	1.50	\$36.56	T
04/27/18	Police	1802	Preventive maintenance service.	1.50	\$36.56	T
04/27/18	Police	1801	Preventive maintenance service. Put brace on computer stand.	1.50	\$36.56	T
04/30/18	Police	1830	Inspected shift cable connection at transmission. Ordered new cable.	1.50	\$0.00	T,D
04/30/18	PW	40	Dropped off and picked up from Creekside Glass.	1.50	\$259.00	D
04/30/18	PW	T-4	Fixed driver side trail light / blinker.	0.50	\$0.00	T
4/30/20187	PW	1891	Checked over lights.	1.00	\$0.00	D,T
04/30/18	Police	1807	Put dash back together.	2.00	\$0.00	T
04/30/18	Fire	1811	Picked unit up from Johnson and Towers and delivered to Browns Mills Firehouse.	3.00	\$0.00	D,T
04/30/18	Senior	77	Preventive maintenance service. Replaced right rear inside tire valve stem.	3.00	\$42.89	D
05/01/18	Police	1830	Removed old shift cable and put new shift cable on.	1.00	\$57.13	T
05/01/18	Police	1807	Hooked up passenger side air bag, put parts in dash.	2.50	\$0.00	T

**FLEET STATUS REPORT**

**5/9/2018**

<b>DATE</b>	<b>DEPT</b>	<b>VEHICLE</b>	<b>REPAIR</b>	<b>Hours</b>	<b>Parts Costs</b>	<b>MECH</b>
05/01/18	Police	1811	Replaced battery.	0.50	\$115.35	T
05/01/18	AC	1834	Ran codes for inspection.	0.50	\$0.00	T
05/01/18	PW	18T1	Checked on right hand signal and repaired bad connection at plug.	0.50	\$0.00	D
05/01/18	PW	17	Removed badly rusted bed from #17 and replaced it with bed from #8.	5.50	\$0.00	D,T
05/01/18	PW	211	Road call to Rancocas Lane. Removed right hand lift bar, so that damaged sweeper deck could be lifted and transported back to the shop. Removed bent frame bracket and straightened. Reinstalled and adjusted sweeper deck.	2.00	\$0.00	D
05/01/18	PW	15	Checked not working turn signals or running lights at trailer plug. Checked transmission fluid leak. No power at parking light circuit, wiring problem.	0.50	\$0.00	D
05/02/18	AC	1834	Took to inspection and ordered parts.	1.00	\$0.00	T
05/02/18	PW	31	Removed split hose. Had new one made and put on.	1.00	\$68.05	T
05/02/18	Police	1807	Worked on dash.	4.00	\$0.00	T
05/02/18	PW	17	Continued replacing bed.	1.00	\$0.00	D
05/02/18	Fire	1821	Picked up at Browns Mills Fire Dept. and delivered to Blaze Emergency. Picked up from Blaze and delivered to Browns Mills Fire Dept.	1.00	\$0.00	D
05/02/18	PW	30	Went to Giberson's Farm in Pemberton. Folded up batwings and towed unit out for loading on to low bed trailer.	2.50	\$0.00	D
05/02/18	PW	JDZ2	Checked hydraulic oil leak. Changed hydraulic oil and filters.	2.00	\$70.70	D,T
05/02/18	AC	43	Charged air conditioning and tested.	0.50	\$0.00	D
Total Hours Worked				65.00		
Time Off (e.g., sick, vacation, etc....)				56.00		
Misc. Time (e.g., Class, CDL Drug Test, etc....)						
<b>TOTAL HOURS</b>				<b>121.00</b>		
<b>TOTAL PARTS COST</b>					<b>\$1,010.55</b>	