

FLEET STATUS REPORT

6/14/2018

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
06/07/18	PW	Shop	Clean up shop - trash, tires, metals and swept.	0.50	\$0.00	T
06/07/18	PW	T-31	Lubed kill switch.	2.00	\$0.00	T,DD
06/07/18	Police	1806	Replaced and balanced tire. Inspected all other tires and topped off with air.	1.00	\$0.00	T
06/07/18	Fire	1804	Troubleshoot. Replaced battery terminal.	1.50	\$1.56	T
06/07/18	Police	1846	Troubleshoot.	1.50	\$0.00	T
06/07/18	PW	Shop	Went to Lucas Dodge to pick up part for police1846 and fire 1804.	1.00	\$0.00	T
06/07/18	Fire	1836	Replaced two fuses in on board charger power circuit. Rewired on board compressor to battery. Picked up and delivered to Country Lakes Firehouse.	4.50	\$6.69	DD,T
06/08/18	PW	38	Road call to Country Lakes for hydraulic leak.	1.50	\$0.00	DD
06/08/18	PW	JD	Repaired tire.	0.50	\$1.50	DD
06/08/18	PW	14	Plugged tire. Removed rusted wheel well skirt.	0.50	\$1.50	DD
6/11/201	PW	38	Replaced blown hose under rear of machine. Got hose made at Hainesport Truck.	7.00	\$271.28	D,T,DD
06/11/18	PW	37	Aired up tire. Checked for leaks.	1.00	\$0.00	D,T
06/11/18	PW	210	Checked electric brakes that were locking up. Switched to secondary trailer plug on truck.	1.00	\$0.00	D,DD
06/11/18	PW	T-31	Road call to Country Lakes. Checked belts that were loose.	1.00	\$0.00	D
06/11/18	Water	70	Checked front end. Replaced and balanced tires.	2.00	\$265.42	T
06/11/18	Fire	1804	Replaced crankshaft sensor.	1.50	\$108.34	T
06/11/18	Police	1805	Replaced missing belt. Removed tensioner, lubed and put new belt on.	1.50	\$39.65	T
06/12/18	PW	Shop	Bat Wing Mower - cut seized blade off, started removing blade hub.	3.00	\$0.00	D
06/12/18	PW	JD	Checked unit, tightened middle mower blade and tightened belt idler. Tested unit.	1.00	\$0.00	D
06/12/18	PW	19	Checked air leak at regulator. Replaced air regulator and checked for leaks. Picked up parts at O'Brien and Sons.	3.00	\$12.18	D,DD
06/12/18	PW	30	Charged batteries. Towed bat wing mower into shop for repairs.	1.00	\$0.00	D
06/12/18	Police	1846	Heated up and removed old O2 sensors. Removed and replaced oil sensor. Test drove.	2.50	\$166.52	T
06/12/18	Police	1851	Replaced fuel pump fuse. Checked fluids.	1.50	\$2.49	T
06/12/18	Police	1812	Preventive maintenance service and replaced cabin filters.	2.00	\$34.28	T
06/12/18	Rec	79	Preventive maintenance service and replaced cabin filters.	1.50	\$48.89	W

**FLEET STATUS REPORT**

6/14/2018

<u>DATE</u>	<u>DEPT</u>	<u>VEHICLE</u>	<u>REPAIR</u>	<u>Hours</u>	<u>Parts Costs</u>	<u>MECH</u>
06/12/18	PW	21	Checked truck for air pressure build up. Found air leak under door, air tank has a hole.	0.50	\$0.00	W
06/12/18	PW	Shop	Cleaned up bay and emptied dirty oil into outside container.	0.50	\$0.00	W
06/12/18	PW	25	Jump started with jumper box and checked charging system.	0.50	\$0.00	W
06/12/18	Fire	818	Jump started with jumper box.	0.50	\$0.00	W
06/12/18	PW	29	Repaired both mud flaps and license plate bracket. Replaced air conditioner filter. Inspected air filter and fluids. Added window washer.	1.00	\$14.25	W
06/12/18	Rec	75	Road call to recreation. Jump started and brought back to shop. Checked charging system and load tested battery. Checked tires and fluids.	1.50	\$0.00	W,T
06/12/18	PW	27	Repaired mud flap brackets and license plate bracket. Replaced mud flap.	1.00	\$15.11	W
06/13/18	Fire	1818	Troubleshoot truck shutting off while driving. Dropped down fuel tank to check fuel pump for power. Checked fuses and relays.	4.50	\$0.00	W,T
06/13/18	PW	T-16	Filled diesel fuel tanks. Checked all fluids and lubed all grease points.	1.50	\$6.50	W
06/13/18	PW	34	Refilled external diesel fuel tank.	0.50	\$0.00	W
06/13/18	PW	335	Refilled diesel fuel from truck 34.	0.50	\$0.00	W
06/13/18	PW	T-16	Filled DEF tank up.	1.00	\$8.50	T
06/13/18	Police	1846	Took to inspection - passed.	1.50	\$0.00	T
06/13/18	PW	2	Put on new bearings and bushings in wheel.	1.00	\$12.84	T
06/13/18	Police	1851	Took dash apart to troubleshoot radio not working.	2.00	\$1.00	T
06/13/18	PW	Shop	Bat Wing Mower - removed stuck blade hub assembly. Removed left gear box for repairs. Cut rusted metal from left mower wing for welding repairs.	5.00	\$0.00	D
06/13/18	PW	45	Repaired coolant lead at heater hoses.	0.50	\$0.00	D
06/13/18	PW	100	Weld front of mower deck.	1.00	\$0.00	D
Total Hours Worked				69.50		
Time Off (e.g., sick, vacation, etc....)				96.00		
Misc. Time (e.g., Class, CDL Drug Test, etc....)						
<b>TOTAL HOURS</b>				<b>165.50</b>		

FLEET STATUS REPORT

6/14/2018

<u>DATE</u>	<u>DEPT</u>	<u>VEHICLE</u>	<u>REPAIR</u>	<u>Hours</u>	<u>Parts Costs</u>	<u>MECH</u>
			TOTAL PARTS COST		\$1,018.50	