

FLEET STATUS REPORT

9/6/2017

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
08/24/17	Shop	PW	Hearing test.	1.00	\$0.00	D,J
08/24/17	Fire	1812	Check lights in all tool compartments. Calibrated water tank level sensor. Checked on board charging system.	4.50	\$0.00	DD,J
08/24/17	Water	61	Replace right hand upper control arm. Bring unit to Tri-State Tire for front end alignment.	1.50	\$96.39	D
08/24/17	PW	1804	Bring in shop and look over for recruit training.	0.50	\$0.00	J
08/24/17	PW	T-31	Change out worn teeth. Weld on missing tooth holders. Change out front skid and mounting plate.	7.00	\$628.58	J,D
08/24/17	PW	31	Air up front tires.	1.00	\$0.00	D,J
08/25/17	PW	9	Install new hold down strap for stowing boom. Replace and relocate rear marker lights.	1.00	\$10.46	J
08/25/17	Police	1819	Replace upper steering shaft. Remove steering column and reinstall shaft that fell out.	2.00	\$221.19	D,DD
08/25/17	PW	208	Remove front tires and replace two leaking valve stems.	2.00	\$3.20	D,DD
08/25/17	PW	18T1	Repair jack handle crank and lubricate jack.	0.50	\$0.00	J
08/25/17	Police	1804	Preventive maintenance service. Check out for recruit training. Remove and replace right rear tire. Replace left front wheel hub assembly.	3.50	\$345.86	J
08/25/17	PW	7115	Make tow receiver for spray tank. Lengthen wiring harness. Prime water pump and adjust spray nozzles.	1.50	\$0.00	J,D
08/28/17	PW	5464	Repair bad connection at trailer plug.	0.50	\$0.00	D
08/28/17	Police	1804	Replace upper steering shaft. Clean paint marker from windows.	1	\$216.68	D
08/28/17	PW	107	Check dozer edges for wear, order new edges and hardware.	1	\$0.00	D,DD
08/28/17	Code	52	Check vibration/front end noise. Balance four tires. Found bad passenger side outer tie rod.	2	\$0.00	D,DD
08/28/17	PW	208	Jump start dead batteries.	0.5	\$0.00	D
08/28/17	Police	1819	Repair broken shift indicator.	1	\$0.00	D
08/28/17	Water	64	Check starting and charging system and install battery.	0.75	\$114.85	D
08/28/17	PW	T-2	Weld new jack on trailer.	1	\$42.08	D
08/29/17	PW	67	Replace exhaust pipe off turbo. Repair broken air line. Troubleshoot and repair electric brake for trailer. Install new trailer plug.	8	\$306.43	J,D
08/29/17	PW	17	Preventive maintenance service.	1.5	\$555.36	D,J

FLEET STATUS REPORT

9/6/2017

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
08/29/17	Code	52	Replace right front outer tie rod end. Swap tires and troubleshoot front end shake.	1.5	\$59.96	D,D
08/29/17	PW	JDZ1	Replace rear tires.	1	\$0.00	D
08/29/17	Police	1816	Replace driver side headlight bulb.	0.5	\$10.44	D
08/29/17	Police	1813	Repair plug at blower motor that wasn't working. Erase codes, cat inefficiency, bank 2, code. Preventive service.	2.5	\$20.36	D
08/29/17	Police	1819	Install good used shift indicator in dash.	1.5	\$0.00	DD
08/30/17	Code	52	Troubleshoot front end shake. Swap tires front to back.	1	\$0.00	D
08/30/17	PW	17	Preventive maintenance service.	1.5	\$26.25	D
08/30/17	Police	1812	Troubleshoot check engine light on. Preventive maintenance service. Replace spark plugs.	3	\$102.61	D
08/30/17	Police	1810	Troubleshoot fuel gauge fluctuating. Swap out #5 cylinder cellpak with known good one.	1	\$0.00	D
08/30/17	Water	67	Replace electric brake controller. Figure out and repair faulty wiring going from brake controller to rear of truck.	10.5	\$86.53	J,DD
08/30/17	PW	T-1	Replace sheer pin on auger.	0.5	\$0.00	J
08/30/17	Police	1804	Replace motor mount.	0.5	\$76.70	J
			Total Hours Worked	68.25		
			Time Off (e.g., sick, vacation, etc...)	12.00		
			Misc. Time (e.g., Class, CDL Drug Test, etc...)			
			TOTAL HOURS	80.25		
			TOTAL PARTS COST		\$2,923.93	