

FLEET STATUS REPORT

8/12/2019

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
4/11/2019	Fire	1815	Troubleshoot charge lights not going to 100 percent. Disconnected and load tested batteries. Checked on board charger.	3	\$0.00	D,DD
4/11/2019	PW	210	Replaced failed water pressure gauge.	1	\$0.00	D,DD
4/11/2019	PW	102	Removed and replaced transmission lines.	2.5	\$88.63	D
4/11/2019	PW	T-3	Charged batteries, got unit running. Repaired left tire.	1.5	\$0.00	D,T
4/11/2019	PW	32	Fixed gasket and put intake manifold back together. Filled up coolant.	3	\$14.44	T
4/11/2019	Police	1803	Preventive maintenance service. Checked TPMS system.	2	\$25.96	T
4/11/2019	PW	Shop	Cleaned up, mopped and removed trash.	1	\$0.00	T,D
4/11/2019	PW	100	Preventive maintenance service. Checked over for mowing season.	1	\$105.85	J
4/11/2019	Rec	77	Installed new door module. Set radio time.	0.5	\$0.00	J
4/11/2019	Police	1814	Picked up from Medford Ford.	2	\$0.00	J,DD
4/11/2019	PW	100	Replaced mower belt tensioner assembly.	3	\$248.15	J
4/11/2019	PW	107	Painted rollers and sprockets.	1	\$0.00	J
4/11/2019	PW	T-3	Road call to Route 72 Wawa. Removed flat put on spare.	1	\$0.00	D
4/11/2019	PW	102	Replaced power steering pump.	2.5	\$172.75	D
4/11/2019	Fire	1815	Troubleshoot air leak. Replaced faulty air governor. Delivered to Browns Mills Fire Dept.	0.5	\$64.99	D,T
4/12/2019	Fire	1815	Replaced air conditioner compressor, evacuated system. Charged system. Returned to firehouse.	4	\$588.86	DD
4/12/2019	Fire	1811	Road call to Browns Mills Fire Dept. Replaced driver side headlight bulb.	1	\$10.99	D
4/12/2019	Police	1816	Preventive maintenance service. Plugged right rear tire and put in trunk for spare. Put spare on. Ran codes.	2	\$26.95	T
4/12/2019	Police	1814	Preventive maintenance service. Mounted and balanced two front tires. Checked TPMS system.	2.5	\$292.00	T
4/12/2019	Police	1809	Preventive maintenance service. Checked TPMS system. Shut cage window.	2	\$30.65	T,DD
4/12/2019	PW	100	Finished preventive maintenance service. Cleaned up. Installed in line fuel filter. Center on both rear wheels was loose, tightened all wheels.	3	\$43.35	J
4/12/2019	PW	15	Preventive maintenance service. Checked over. Relocated hole on ladder rack and fastened. Put air in tire.	3.5	\$46.09	J
4/15/2019	PW	T-3	Removed, dismounted and mounted new tire. Put spare back on T-15.	1	\$145.95	D
4/15/2019	PW	107	Installed track rock guards.	2	\$0.00	D

FLEET STATUS REPORT

8/12/2019

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
4/15/2019	Police	1807	Something got wet causing the car to shut off. Cleared codes and let run for most of the day.	1	\$0.00	T
4/15/2019	PW	2	Checked fluids. Gassed up. Put wipers on.	0.5	\$9.98	T
4/15/2019	Police	1805	Preventive maintenance service. Replaced coil #6 and plug. Checked air conditioning.	3.5	\$133.07	T
4/15/2019	PW	16	Welded patches over holes on dump body. Painted body.	6	\$0.00	J,T
4/15/2019	Water	64	Repaired broken brake line on front right wheel.	2	\$9.58	J
4/16/2019	PW	205	Started installing air tires - swapped out solid tires.	1	\$0.00	D
4/16/2019	Fire	1815	Checked coolant level and checked for coolant leaks. Road call to Browns Mills Firehouse.	1	\$0.00	D,T
4/16/2019	PW	40	Troubleshoot unit missing at half throttle. Pulled trouble codes.	1.5	\$0.00	D
4/16/2019	PW	Shop	Went to Groff Tractor for parts. Compared invoices to parts list.	2	\$0.00	D
4/16/2019	PW	5	Road call to Ridge Road. Jump started dead unit. Replaced blown gauge cluster fuse.	1	\$0.00	D
4/16/2019	PW	16	Painted body and wheels.	6.5	\$59.88	J
4/16/2019	Police	4126	Unplugged passenger front door switch for dome lights, that came on while driving. Charged battery.	1	\$0.00	T
4/16/2019	Police	1812	Preventive maintenance service. Checked TPMS system.	2	\$35.01	T
4/16/2019	Fire	1893	Preventive maintenance service. Took hose off to fix oil tube. Took back to Station 1.	3.5	\$80.22	T,D
4/17/2019	PW	205	Installed air tires and put solid tires on pallet to be stored on top of tire trailer.	1	\$0.00	D
4/17/2019	PW	38	Road call to Presidential Lakes Firehouse. Aired up flat front tires.	1	\$0.00	D
4/17/2019	PW	113	Replaced faulty pump switch.	1	\$57.24	D
4/17/2019	Fire	M181	Troubleshoot hard starting. Fuel ball check valve was bad. Checked water pump. Installed battery. Took back to Browns Mills Firehouse.	2	\$239.65	D,T
4/17/2019	Fire	M183	Picked up unit from Country Lakes Fire Dept. Checked water pump.	1	\$0.00	D
4/17/2019	PW	Shop	Moved new beds to back of shop and moved shop equipment around the back of shop.	1	\$0.00	D
4/17/2019	Water	61	Removed and replaced side caliper.	1.5	\$59.99	J
4/17/2019	PW	36	Straightened out driver's side fender; so door will open and close. Added brake fluid to master cylinder and light went out. Checked over. Aired up tires.	3	\$0.00	J
4/17/2019	PW	24	Removed and replaced 4-way flasher. Checked out strobes.	0.5	\$0.00	J

FLEET STATUS REPORT

8/12/2019

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
4/17/2019	PW	16	Preventive maintenance service.	2.5	\$154.90	J
4/17/2019	Police	1804	Troubleshoot, checked codes. Preventive maintenance service. Mounted and balanced front passenger tire. Relearned TPMS system.	2.5	\$168.03	T
4/17/2019	Police	1805	Troubleshoot rough idle, misfire. Air conditioner fans/coolant getting hot and not running right because of a draw and misfire.	3	\$0.00	T
4/17/2019	PW	Shop	Installed three door prop holders.	0.5	\$20.91	T
Total Hours Worked				99.5		
Time Off (e.g., sick, vacation, etc....)				48.00		
Misc. Time (e.g., Class, CDL Drug Test, etc....)						
TOTAL HOURS				147.50		
TOTAL PARTS COST					\$2,934.07	