

FLEET STATUS REPORT

8/12/2019

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
5/16/2019	Insp.	50	Plugged right rear tire.	1	\$0.00	J
5/16/2019	PW	5204	Road Call. Remove and replace inner cooler broken clamp.	1	\$12.89	J
5/16/2019	PW	T-16	Preventive maintenance service. Glued rubber door seal on control panel.	6	\$174.22	J,D
5/16/2019	PW	18	Removed bed and stripped parts off old bed.	1.5	\$0.00	J,D
5/16/2019	Water	73	Preventive maintenance. Replaced cabin filter. Inspected brakes and tires.	2	\$89.78	W
5/16/2019	PW	2	Checked TPMS with scan tool. Removed front brake. Cleaned all rust and dirt. Lubed and put new front pads and rotors on. Started taking rear brakes apart.	4	\$117.60	T,W
5/16/2019	PW	8	Buffed and cleaned truck. Painted wheels. Mounted and balanced four tires.	7.5	\$810.06	T,D,W
5/16/2019	PW	37	Replaced all rear brakes. Bled brakes.	1	\$0.00	D
5/16/2019	PW	101	Road call to Rancocas Lane. Removed air conditioner belt. Test drove. Pulled four wheels found bad tie rod ends, front drive shaft, u-joints and rear brake rotors and pads bad.	1	\$0.00	D
5/16/2019	PW	31	Removed and cleaned out rear belly pan. Replaced broken off grease fitting in rear drive shaft. Greased.	1.5	\$12.98	D
5/17/2019	PW	35	Removed blown hydraulic line.	1	\$0.00	D
5/17/2019	PW	18-T1	Replaced four tires up at Tri-State.	2.5	\$217.08	D,T,J
5/17/2019	PW	2	Cleaned rust off rear brakes and replaced with new.	2	\$194.79	W,T
5/17/2019	Police	1807	Preventive maintenance service. Checked TPMS.	2	\$35.42	T
5/17/2019	Police	1830	Jump started. Replaced battery with oil stock. Traced for draw.	3	\$0.00	T
5/17/2019	PW	24	Plunger in brake valve froze up.	0.5	\$0.00	J
5/17/2019	PW	18	Fit new bed to truck. Power washed frame. Made brackets for bed.	5	\$0.00	J,D
5/17/2019	PW	30	Road call. Tractor was stuck in mud. Transmission would not go in gear.	4	\$0.00	J,D
5/17/2019	PW	Shop	Cleaned shop bays and office. Took out scrap metal and oil drums. Put away tires.	1.5	\$0.00	W,D
5/17/2019	Water	61	Replaced transmission cooler lines.	3	\$182.76	W
5/17/2019	Water	70	Preventive maintenance service. Inspected brakes, tires and checked TPMS with scanner.	2	\$40.25	W
5/20/2019	PW	JDZ2	Replaced belt and greased.	0.5	\$108.38	T
5/20/2019	PW	101	Replaced tie rod ends and tie rod. Replaced steering stabilizer. Replaced rear rotors. Rear calipers would not compress, badly rusted.	4.5	\$762.65	D
5/20/2019	PW	37	Dropped belly pan, checked transmission leak.	0.5	\$0.00	D

FLEET STATUS REPORT

8/12/2019

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
5/20/2019	PW	35	Replaced blown hydraulic hose at 4 in 1 bucket. Fabricated hose. Test drove and inspected front brakes. Greased slides and replaced front pads.	1	\$170.45	D
5/20/2019	Fire	1838	Took back to Country Lakes Firehouse.	2.5	\$51.99	T,DD
5/20/2019	PW	T-65	Put tire back on bead.	0.5	\$0.00	T
5/20/2019	Police	1805	Replaced headlight harness and bulb.	1	\$30.15	T
5/20/2019	Fire	1802	Jump started at Country Lakes Firehouse. Brought back to shop, charged battery and fixed driver front seat. Took back to Browns Mills.	3.5	\$0.00	T,DD
5/20/2019	PW	Shop	Organized and labeled CAS #'s, SDS for chemicals. Inspected all tires. Three had nails in them. Replaced three tires checked TPMS	7.5	\$0.00	W,DD
5/20/2019	Police	1808	with scan tool Road tested.	2	\$399.06	W
5/20/2019	PW	Misc.	Went to Urgent Care.	1.5	\$0.00	J
5/20/2019	PW	18	Mount bed and bumper.	2.5	\$0.00	J
5/21/2019	Fire	1821	Pick up from Browns Mills Fire for air leak.	1	\$0.00	T,W
5/21/2019	Fire	1893	Removed and replaced bulb. Put new fill neck in valve cover.	6.5	\$79.24	T,W
5/21/2019	PW	208	Checked drive line noise. Carrier bearing needs to be replaced.	0.5	\$0.00	D
5/21/2019	Police	1816	Replaced passenger side headlight.	0.5	\$10.99	D
5/21/2019	PW	JDZ2	Adjusted drive linkage. Checked right rear tire that was leaking. Charged and load tested batteries. Checked charging system and topped off	1	\$0.00	D
5/21/2019	PW	66	hydraulics and power steering.	1.5	\$0.00	D
5/21/2019	PW	101	Replaced rear brake calipers.	2.5	\$244.92	D,T
5/21/2019	PW	Shop	Loaded dump trucks with mulch.	1	\$0.00	D
5/21/2019	Admin.	2	Road tested rear brakes. Inspected calipers.	1.5	\$0.00	W
5/21/2019	PW	Shop	Went to Advance Auto and picked up parts.	0.5	\$0.00	W
5/21/2019	PW	Shop	Put away and marked labels for chemicals. Cleaned shop. Preventive maintenance. Replaced cabin filter. Inspected brakes and tires.	1	\$0.00	W
5/21/2019	Police	1812	Checked TPMS with scan tool.	2	\$45.60	W
5/21/2019	PW	26	Replaced inner cooler clamp. Fuel tank must be removed to change sender.	1	\$41.31	J
5/21/2019	PW	T-16	Changed air filters, oil filter, fuel filter and clean up.	2	\$496.54	J
5/21/2019	PW	18	Installed new bed. Hooked up lights and trailer plugs. Cleaned up.	3.5	\$4.76	J
5/22/2019	PW	Shop	Picked up tires from Tri-State Tire.	1	\$0.00	T,DD
5/22/2019	PW	101	Dropped off at Craig's for alignment.	1	\$0.00	T,DD

FLEET STATUS REPORT

8/12/2019

<u>DATE</u>	<u>DEPT</u>	<u>VEHICLE</u>	<u>REPAIR</u>	<u>Hours</u>	<u>Parts Costs</u>	<u>MECH</u>
5/22/2019	PW	208	Balanced and replaced front tires. Replaced support bearing on drive shaft.	2	\$230.56	T,D
5/22/2019	Police	1803	Preventive maintenance service. Tire rotation.	2	\$35.42	T
5/22/2019	Fire	1821	Removed air pressure switch from under dash. Topped off passenger side hub with oil. Filled tires. Checked for codes.	3	\$34.31	T,DD
5/22/2019	PW	105	Troubleshoot mower, outer boom not working. Found control boxes were out of synchronization, reset and synchronized. Tested all operations. Repaired rubbed wires in mower harness.	2.5	\$0.00	D,DD
5/22/2019	PW	107	Replaced fan belt and tensioner. Checked air conditioner not working.	3	\$280.11	D,DD
5/22/2019	PW	T-3	Repaired broken shoot extension hinges.	1	\$0.00	D
5/22/2019	PW	Shop	Cut metal plate 27 inches for Ron to mount air compressor.	0.5	\$0.00	D
5/22/2019	PW	26	Replaced diesel fuel gauge and filled diesel tank.	1.5	\$184.07	W
5/22/2019	PW	T-16	Fueled with diesel, DEF. Fueled #34.	1	\$8.50	W
5/22/2019	PW	Shop	Put away tires in conex.	0.5	\$0.00	W
5/22/2019	PW	28	Replaced tarp and welded exhaust shield.	4	\$0.00	W,T
5/22/2019	Police	4126	Charged air conditioning.	0.5	\$6.66	DD
Total Hours Worked				130		
Time Off (e.g., sick, vacation, etc....)				20.00		
Misc. Time (e.g., Class, CDL Drug Test, etc....)				2		
TOTAL HOURS				<u>150.00</u>		
TOTAL PARTS COST					\$5,113.50	