FLEET STATUS REPORT

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
			Road call to Dans Road. Checked engine noise, found a bad belt and belt			
5/2/2019	PW	107	tensioner.	1	\$0.00 D	1
5/2/2019	PW	T-31	Welded one new holder on and replaced one tooth.	1	\$11.88 D	
5 /0 /00 A	D14/	00	Removed and charged batteries. Fabricated bracket and mounted battery,		, , , , , , , , , , , , , , , , , , ,	
5/2/2019		30	disconnected switch. Checked over unit levels and topped off mower gear boxes.	2	•	•
5/2/2019		40	Removed and replaced mass air flow sensor.	1	* · · · · · · ·	•
5/2/2019		T-3	Installed one new bearing on rear of cutter wheel.	1.5		
5/2/2019		3026	Removed batteries and took to shop, hooked up to charger.	1.75	·	,W,D
5/2/2019) PW	33	Installed batteries and got running. Burnt off old bracket. Removed part.	2	·	
5/2/2019	PW	18	Finished replaced leaf spring. Cleaned up floor and lift.	2	\$292.45 J	
5/2/2019	PW	T-16	Moved in pole barn for maintenance.	0.5	\$0.00 J	
5/2/2019	Police	7965	Remade all brake lines.	4	\$34.94 T	,D
5/2/2019	Police	4125	Started vehicle with no problems. Needs to be run. Checked over.	0.5	\$0.00 T	
5/2/2019	Police	7110	Replaced spark plugs. Replaced coil packs. Replaced intake manifold gasket.	1.5	\$290.34 T	
5/2/2019	PW	32	Checked fuel pressure. Ordered fuel filter. Added injector cleaner.	1	\$5.99 T	
5/2/2019	PW	4	Checked tires and fluids. Has a class three leak transmission fluid.	1	\$0.00 W	1
5/2/2019	Police	1810	Pulled radio and electronic devices out.	0.5	\$0.00 W	1
5/2/2019	Police	1803	Pulled radio and electronic devices out. No gauge cluster.	0.5	\$0.00 W	1
5/2/2019	Police	1817	Pulled out radio and electronic devices.	0.5	\$0.00 W	I
5/2/2019	Code	52	Pulled out electronic devices and counter mount bracket.	0.5	\$0.00 W	I
5/2/2019	PW	209	Repaired driver side front wiper arm.	0.3	\$0.00 W	I
			Inspected passenger side front under carriage. Washer pump on order. Repaired			
5/2/2019	Police	1805	fender liner. Road tested pulled to left. Dropped off at Craig's for alignment.	2	\$0.00 W	/,D
5/2/2019	PW	12	Checked fluids and batteries. Jumped dead batteries.	1	\$0.00 W	1
5/2/2019	PW	34	Checked tires. Checked and topped off fluids. Diesel fuel on outside tank.	0.5	\$0.00 W	I
5/2/2019	Police	1833	Serviced air conditioning.	0.5	\$6.66 D	D
5/2/2019	PW	JDZ1	Replaced mower blade switch.	0.5	\$21.25 D	D
			Picked and delivered to Browns Mills Fire Dept. Replaced on board air			
- /- /			compressor, adjusted pressure switch to cut off at 110 psi. Troubleshoot privacy			
5/3/2019		1891	windows not working. Found bad fuse holder in circuit board panel.	4.5	•	
5/3/2019		40	Checked for trouble codes and reinstalled dog house engine cover. Test drove.	1	*	
5/3/2019	Fire	1804	Picked up and delivered to Creekside Glass for windshield replacement.	2	90.00 D	,DD,T

FLEET STATUS REPORT

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
5/3/2019	PW	Shop	Washed shop truck.	0.5	\$0.00	D
5/3/2019	Police	1808	Test drove; pulls a little. Took to Craig's. Preventive maintenance service.	3.5	\$125.18	T,D,W
5/3/2019	Police	1818	Repaired tire; put in trunk - spare only. Put spare on. Codes went to Ford.	1	\$0.00	Т
5/3/2019	PW	32	Replaced spark plugs. Replaced fuel filter.	1.5	\$37.99	Т
5/3/2019	Police	1805	Put washer fluid pump in. Picked up from Craig's.	1	\$114.76	T,D
5/3/2019	PW	4	Replaced transmission cooler and transmission cooler lines.	3.5	\$341.26	W
5/3/2019	PW	11	Jumped batteries. Checked fluid and tires.	1	\$0.00	W
5/3/2019	PW	8	Charged batteries and load tested. Checked fluids. Needs new batteries.	1.5	\$0.00	W
5/6/2019	Police	1807	Burnt headlight plug; replaced with OEM pigtail and new bulb.	0.5	\$43.15	Т
5/6/2019	Police	1809	Preventive maintenance service. Checked TPMS system.	2	\$37.62	Т
			Checked sensors. Checked and replaced fluids. Checked tires. Topped off air			
5/6/2019	Police	1838	conditioning system.	1.5	\$4.39	T
5/6/2019	PW	5	Preventive maintenance service. Mounted and balanced two tires.	3	\$37.67	Т
5/6/2019	PW	JDZ2	Power washed. Started removing drive motor/pump assemblies. Troubleshoot intermittent engine miss. Removed upper intake plenum and	1	\$0.00	D
			checked harness for shorts or broken wires. Exchanged coil 4 and 6. Erased codes			
5/6/2019		1805	and test drove. Replaced driver side headlight bulb.	2	•	
5/6/2019			Preventive maintenance service.	2	•	
5/6/2019	PW	T-32	Uncrated and put tires away in tire trailer.	0.5	\$586.82	D
5/6/2019	Police	1823	Preventive maintenance service. Inspected brakes and tires. Blew out inside of car.	2	\$29.58	W
5/6/2019	PW	4	Put front grill back on and checked for leaks. Cleaned back and inside of truck. Replaced two batteries, checked fluids and tires. Repaired passenger side door	1.5	\$0.00	W
5/6/2019	PW	8	handle. Cleaned out truck.	2	\$237.44	W
5/6/2019	Police	1818	Picked up vehicle at Medford Ford.	2	\$0.00	W,D
5/6/2019	PW	T-3	Started to assemble cutter wheel.	4.5	\$513.87	J
5/6/2019	PW	106	Moved machine from Whispering Pines to yard.	2	\$0.00	J
5/7/2019	PW	JDZ-2	Power washed, removed and replaced drive pumps and hydraulic motors.	5.5	\$2,773.94	D
5/7/2019	Rec	79	Preventive maintenance service. Checked TPMS system.	1.5	\$23.10	Т
5/7/2019	Police	1812	Remove and replace tires.	1	\$302.82	Т
5/7/2019	Code	50	Right rear tire low. Put tire in water tank, found nail in tire. Plugged and put back on vehicle. Checked TPMS system.	1	\$0.99	Т

FLEET STATUS REPORT

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
5/7/20	19 Police	1800	Preventive maintenance service. Checked TPMS system.	2	\$35.42 T	
5/7/20)19 Rec	78	Fixed passenger side rear bumper cover. Repaired air cleaner. Finished assembly. Repaired tailgate pins. Repaired chute lock pin. Blew out radiator to grease. Replaced air filter. Replaced missing metal on	1	\$0.00 T	
5/7/20)19 PW	T-3	guard.	7	\$34.13 J,E)
5/7/20)19 PW	JDZ-1	Troubleshoot no start. Checked and replaced with new battery.	0.5	\$32.99 W	
5/7/20)19 PW	8	Preventive maintenance service. Cleaned inside and outside of truck. Repaired fuel leak out of fuel bowl housing. Cleaned up fuel on bay floor.	5	\$88.08 W	
5/7/20)19 PW	4	Power washed truck and truck bed.	1	\$0.00 W	
5/8/20)19 PW	Shop	Cleaned interior of shop truck.	0.5	\$0.00 D	
5/8/20)19 PW	JDZ-2	Finished installing drive pump/motor assemblies. Filled up hydraulic tank. Test drove unit. Picked up filters from Central Jersey Equipment.	2.5	\$35.66 D	
5/8/20)19 PW	T-25	Disconnect goose neck from trailer. Straighten bent safety latches at goose neck.	1	\$0.00 D	
5/8/20)19 PW	100	Adjusted mower proximity switch so blades would shut off when deck is up.	0.5	\$0.00 D	
5/8/20)19 PW	100	Road call to Springfield Road. Adjusted hydraulic pump belt.	1	\$0.00 D,	Γ
5/8/20)19 PW	32	Took broken brake line off and make new brake line.	3.5	\$10.48 T,E)
			Browns Mills Firehouse for low coolant light. Put three gallons of coolant in and			
5/8/20)19 Fire	1815	found a loose hose clamp.	3	\$14.97 T,[)
5/8/20)19 Water	Mower	Checked over.	1	\$0.00 T	
5/8/20)19 PW	104	Broke bead on tire and cleaned dirt from around rim. Put sealant to reseat the bead.	0.75	\$0.00 T	
)19 PW	4	Changed wipers.	0.25	•	
0,0,20	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	•	Pulled out rear tail lights and pulled out bed liner. Cut off body bolts, took off truck	0.20	Ψσ.	
5/8/20)19 PW	101	bed.	2.5	\$0.00 W	
5/8/20)19 PW	12	Charged batteries. Cleaned inside and outside. Power washed.	1.5	W	
5/8/20)19 PW	JDZ-3	Will not start. Replaced battery.	0.5	\$0.00 W	
5/8/20)19 PW	11	Charged batteries, pulled plow off. Cleaned inside and outside. Power washed.	2	\$0.00 W	
			Total Hours Worked	121.05		
			Time Off (e.g., sick, vacation, etc) Misc. Time (e.g., Class, CDL Drug Test, etc)	48.00 2		

DATE	DEPT VEHICLE	REPAIR	Hours	Parts Costs	MECH
		TOTAL HOURS	169.05	5	
		TOTAL PARTS COST	\$7,061.77	7	