FLEET STATUS REPORT

DATE DE	PT VEHICLE	REPAIR	Hours	Parts Costs	MECH
6/13/2019 PW	/ 13	Reinstalled rebuilt loader bucket cylinder. Replaced fan belt.	3.5	\$171.99 E	D,J
6/13/2019 PW	/ 38	Repacked hydraulic cylinders right hand lift, rear bucket and rear crowd.	9.5	\$505.89 E),J
6/13/2019 Pol	lice 1846	Put new valve stem in driver front tire, plugged passenger front tire.	1	\$1.35 T	_
6/13/2019 Pol	lice 1814	Checked fuses, took center console apart. Found loose wire.	1	\$0.00 T	-
		Took rear cat off. Removed axle to replace seal. Replaced passenger side engine			
6/13/2019 Pol	lice 1816	mount.	4.5	\$114.91 T	_
6/13/2019 PW	/ 17	Replaced passenger side brake pads and rotor.	1	\$94.93 V	٧
6/13/2019 PW	/ Shop	Meeting.	1	\$0.00 V	٧
		Installed new rotor, brake pads on passenger side and drag link on truck. Checked			
6/13/2019 PW	/ 16	fluids. Road tested.	4.5	\$270.28 V	٧
6/13/2019 PW	/ JDZ1	Changed blades, oil and air filter. Greased bearings.	1.5	\$98.13 H	I W
6/13/2019 PW	/ JDZ3	Changed blades, oil and air filter. Greased bearings.	1.5	\$100.30 E)G
6/13/2019 PW	/ JDZ2	Replaced air filter.	0.25	\$17.59 J	M
6/14/2019 PW	/ 35	Removed loader bucket. Replaced blown hose. Reinstalled bucket.	2	\$80.00)
6/14/2019 PW	/ 112	Road call to Catesville Road. Changed batteries and got unit running.	1	\$0.00 [)
6/14/2019 PW	/ 209	Replaced wiper blades.	0.5	\$9.98 🗅)
6/14/2019 PW	/ 38	Repacked hydraulic cylinders. Cleaned up.	9.5	\$289.36 J	,D
		Put axle back in. Filled PTO up. Filled transmission. Put tie rod end on passenger			
6/14/2019 Pol	lice 1816	side. Put exhaust back on. Took to inspection - passed.	5.5	\$55.88 T	-
6/14/2019 PW	/ 212	Replaced wipers and added fluid.	0.5	\$20.75 T	-
6/14/2019 Pol	lice 1806	Checked codes. Ordered part.	0.5	\$0.00 T	-
		Replaced passenger side rotor, pads, sway bar, end links, hub assembly and four			
6/17/2019 PW	/ 17	tires.	7	\$1,531.37 V	V,D
6/17/2019 Pol	lice 1823	Put in new radiator, fan, thermostat and fill with coolant. Checked for leaks.	3	\$687.42 T	_
6/17/2019 Pol	lice 1805	Inspected damage after crash.	1	\$0.00 T	-
6/17/2019 PW	/ Shop	Went to Tri State Tire to pick up tires. Put tires away in trailer.	2.5	\$0.00 T	,DD,D
6/17/2019 Pol	lice 4126	Took to inspections - passed. Found air conditioner leak. Ordered parts.	1.5	\$0.00 T	_
6/17/2019 PW	/ 31	Started removing blown hydraulic hose from bucket cylinder to control valve.	1	\$0.00 🗅)
6/17/2019 PW	/ 38	Removed and replaced swing cylinder seal kit.	4.5	\$459.58 E),J
6/17/2019 Fire	e 1815	Cleaned up service truck from road call on Saturday.	1	\$0.00 J	
6/17/2019 PW	/ 29	Troubleshoot tail light - plug came out. Replaced tag light with good used one.	1	\$0.00 J	

FLEET STATUS REPORT

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
6/17/2019	PW	212	Drained and removed water tanks out of truck. Put all tools and hose on pallet.	1	\$0.00	J
6/17/2019	PW	Shop	Checked over car from Auto Lenders.	1	\$0.00	J
6/17/2019	PW	211	Replaced right gutter broom.	1	\$80.00	J
6/17/2019	PW	27	Road tested, troubleshoot. Replaced male hydraulic coupler. Greased body pivot.	2	\$8.69	J,D
6/18/2019	PW	Shop	Sharpened mower blades.	1.5	\$0.00	D
			Replaced blown hose from loader valve to bucket cylinder. Picked up parts at			
6/18/2019	PW	31	Hainesport.	3	\$336.17	D
6/18/2019	PW	38	Air up flat left front tire.	0.5	\$0.00	D
6/18/2019	PW	T-4	Checked trailer plug wiring.	0.5	\$0.00	D
6/18/2019	Police	4126	Replaced air conditioner condenser.	1.5	\$131.74	Т
6/18/2019	Police	1809	Preventive maintenance service. Checked TPMS system.	2	\$35.41	Т
6/18/2019	Police	1805	Replaced passenger rear tire. Showed Fante's the truck on the lift.	1.5	\$0.00	T,DD
6/18/2019	PW	2510	Dropped off for air bag recall.	3	\$0.00	T,DD
6/18/2019) PW	6	Preventive maintenance service. Checked brakes and tires. Greased front end and rear lift gate. Checked front end.	2	\$44.19	W
6/18/2019) PW	Shop	Took out trash, metal and tires. Mopped and cleaned up office bathroom. Cleaned, mopped and waxed big blue lift.	4	\$0.00	W
6/18/2019	PW	17	Dropped off 17 at Craig's for an alignment.	1	\$0.00	W,T
6/18/2019	Fire	1815	Looked for numbers for parts.	0.5	\$0.00	J
6/18/2019	PW	Shop	Went to Central Jersey Urgent Car for CDL physical.	1.5	\$0.00	J
		•	Replaced pins and blades. Greased unit. Removed leaking hydraulic line to make			
6/18/2019	PW	105	new one. Removed broken bolt and ordered new ones. Cleaned up.	3	\$130.84	J
6/18/2019	PW	18	Raised bumper - cannot move any further because of bed.	1	\$0.00	J
6/18/2019	PW	111	Removed buck and install auger.	2	\$0.00	J,D
6/19/2019	PW	218	Replaced all cutter teeth.	5	\$522.67	D
6/19/2019	PW	Shop	Take apart leaking trash pump.	1.5	\$0.00	D
6/19/2019) PW	12	Inspected the brake line for a leak. Master cylinder switch assembly is bad. Ordered parts.	1	\$55.57	W
6/19/2019		4	Put truck on lift to prep to removed exhaust manifold.	1	\$0.00	
6/19/2019		1802	Replaced driver side door latch and pulled out driver side hinge pins to replace.	3.5		
			•			

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs M	IECH
			Checked codes for inspection. Needs blower motor and resistor4 for air			
6/19/2019	9 Police	1842	conditioner. Exhaust leak parts on order.	2	\$0.00 T	
			Picked up from Toyota for air bag recall. Replaced front brake pads, greased			
6/19/2019	9 PW	2510	slides. Dropped off for alignment at Craig's.	4	\$46.79 T,W	
6/19/201	9 PW	17	Picked up from Craig's from alignment.	0.5	\$93.55 T	
6/19/201	9 Police	4126	Evacuation system, charge system.	1	\$8.88 T	
			Total Hours Worked	124.25	5	
			Time Off (e.g., sick, vacation, etc)	16.00)	
			Misc. Time (e.g., Class, CDL Drug Test, etc)	2.5	,)	
			TOTAL HOURS	140.25	<u>-</u> 5	
			TOTAL PARTS COST	\$6,099.58	3	