

FLEET STATUS REPORT

8/7/2019

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
3/7/2019	Fire	M-183	Road call to Country Lakes Fire Department. Checked fuel primer bulb. Removed fuel tank and fuel hose, brought back to shop.	0.5	\$0.00	D
3/7/2019	Fire	1893	Troubleshoot patient compartment lights. Replaced and rewired two overhead light/socket assemblies. Replaced three bad bulbs. Replaced license plate light bulb. Picked up and delivered to Country Lakes Fire Department.	2.5	\$5.46	D
3/7/2019	PW	16	Charged batteries and got unit running.	0.5	\$0.00	D
3/7/2019	PW	111	Replaced battery.	1	\$124.65	D
3/7/2019	Fire	1891	Checked air horn. Unit needs an air compressor. Troubleshoot privacy windows. Adjusted e-brake pedal. Run to Lucas Dodge to get parts. Change oil pressure sensor.	3	\$5.10	D,D,J
3/7/2019	Police	1851	Replaced and balanced three tires. Checked TPMS. Test drove.	2.5	\$32.73	T
3/7/2019	Police	4126	Got machine going and brought into shop.	1	\$0.00	T
3/7/2019	PW	218	Cleaned up and swept.	0.5	\$0.00	J
3/7/2019	A/C	1834	Plugged tire.	1	\$0.00	J,T
3/7/2019	A/C	1834	Plugged right rear tire and air up.	0.5	\$0.00	J
3/7/2019	Water	64	Installed and balanced two new front tires. Cleaned up.	1.5	\$231.90	J
3/7/2019	PW	208	Traced fuel leak from top of engine. Tore down.	1.5	\$0.00	J
3/7/2019	Fire	1832	Replaced tower light bulb. Checked all lists and set tire pressure. Picked up and returned for firehouse.	4	\$14.70	DD,J,T
3/8/2019	PW	218	Replaced all cutting teeth. Cleaned dirt and asphalt from tooth holders. Installed water shut off valve at conveyor to regulate wear pressure. Check over unit.	9.5	\$884.06	D,DD,J
3/8/2019	PW	1891	Removed drum spray bar and cleaned nozzles.	1	\$0.00	T,DD
3/8/2019	PW	102	Took back to Browns Mills firehouse.	0.5	\$0.00	T
3/8/2019	Water	74	Put bracket on for trailer plug.	0.5	\$0.00	T
3/8/2019	Fire	1802	Put on exhaust pipe with flapper to keep rain out.	1.5	\$155.00	T,J
3/8/2019	Police	1390	Replaced alternator. Ordered hood cable. Dropped off at Browns Mills Firehouse.	1	\$0.00	T
3/8/2019	PW	40	Took through inspection - passed.	1.5	\$255.18	T
3/8/2019	Police	1805	Checked front end. Preventive maintenance is good. Mounted and balance two tires.	0.5	\$0.00	T
3/8/2019	PW	208	Passenger side headlight.	3	\$2.59	J
			Found top of fuel filter loose, tightened up. Washed off top of motor, ran to check for leaks.			

FLEET STATUS REPORT

8/7/2019

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
3/8/2019	Water	64	Delivered to Craig's for an alignment.	1	\$0.00	J,T
3/8/2019	PW	2	Replaced battery. Checked all lights, fluids and air psi.	1.5	\$114.80	J,T
3/11/2019	PW	113	Checked and troubleshoot water pump. Adjusted fan belt and drained full water separator. Checked out unit.	3	\$0.00	D
3/11/2019	PW	31	Road call to Mt. Misery Road. Checked oil leak. Found oil coming from front axle breather.	1.5	\$0.00	D
3/11/2019	PW	Shop	Set up new personal tool cart and tools.	1	\$0.00	D
3/11/2019	Police	1806	Preventive maintenance service. Took to Tri-State for an alignment.	4	\$129.65	T,D
3/11/2019	Police	1802	Replaced driver side rear tire with old stock. Mounted and balanced.	1	\$0.00	T
3/11/2019	Police	1803	Picked up rom Fante's and inspected when it was back at shop.	2	\$0.00	T,DD
3/11/2019	PW	212	Removed wire from spreader and tucked inside.	1	\$0.00	T,DD
3/11/2019	Code	90	Checked out and charged battery.	0.5	\$0.00	T
3/11/2019	Water	65	Removed wires for spreader and hooked dump bed back up and tucked wires.	1	\$0.00	T,DD
3/11/2019	Water	67	Removed old air compressor and found new one was wrong. Cleaned up.	4	\$0.00	J
3/12/2019	PW	T-31	Road call to Mt. Misery Road. Removed blown hydraulic hose at clutch housing. Fabricated a new hose and went back and installed.	2	\$41.80	D
3/12/2019	PW	107	Brought new parts and tracks into pole barn with forklift Removed right side track and started stripping adjuster covers and rock guards from left side. Started removing rollers.	7	\$0.00	D,T,J
3/12/2019	PW	16	Removed salt spreader off and put tail gate on.	1	\$0.00	T,D
3/12/2019	Police	1802	Water pump is bad. Covered by Ford warranty. Took to Medford Ford.	2.5	\$0.00	T,D
3/12/2019	Water	64	Picked up from Craig's Auto for alignment.	1	\$93.55	T,D
3/12/2019	Fire	1802	Removed and replaced hood release cable assembly. Checked lights. Checked air psi. Removed and replaced wiper blades.	2.5	\$117.96	J
3/12/2019	PW	34	Jump started unit.	0.5	\$0.00	J
3/12/2019	PW	109	Checked over and jump started.	0.5	\$0.00	J
3/12/2019	Water	67	Started installing new air compressor.	4	\$787.89	J,D
3/13/2019	PW	T-31	Road call to Mt. Misery Road. Removed engine cover and removed blown hydraulic hose. Brought cover back to shop and notched out area that was rubbing hoses. Made hydraulic hose and installed.	2.5	\$10.95	D
3/13/2019	Police	1855	Charged battery and got unit running. Put air in tire. Replaced left front tire. Checked transmission fluid leak. Replaced broken transmission cooler clamp.	1.5	\$138.78	D

FLEET STATUS REPORT

8/7/2019

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
3/13/2019	PW	38	Road call to Presidential Lakes Firehouse. Put air in front tires.	0.5	\$0.00	D
3/13/2019	Police	1853	Diagnosed bad water pump. Ordered parts. Replaced water pump.	1	\$105.21	T
3/13/2019	PW	107	Removed roller and cleaned dirt from tensioner.	3	\$0.00	D,T
		1820				
3/13/2019	Police	1819	Jump started and brought back to shop lot and charged.	1.5	\$0.00	T,D,DD
3/13/2019	Police	1802	Picked up from Medford Ford; water pump was replaced.	2	\$0.00	T,DD
			Dropped off 1802; picked up 1892 and took to inspection - passed. Took back to			
3/13/2019	Fire	1892	Browns Mills Firehouse.	2.5	\$0.00	DD,T
3/13/2019	Police	3356	Got running and picked up from BCC. Ordered parts.	1.5	\$0.00	T,DD,D
			Removed and replaced compressor. Hung switch box on dash and cleaned up			
3/13/2019	Water	67	wiring. Replaced spinner hydraulic motor.	6.5	\$210.94	J
			Total Hours Worked	106		
			Time Off (e.g., sick, vacation, etc....)	51.00		
			Misc. Time (e.g., Class, CDL Drug Test, etc....)			
			TOTAL HOURS	157.00		
			TOTAL PARTS COST		\$3,658.92	