

# FLEET STATUS REPORT

11/30/2018

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
11/15/2018	PW	Shop	Snow duty. Installed snow plows on trucks, cleaned up shop.	3	\$0.00	W
11/15/2018	Police	1813	Battery is dead needs to be jumped bring down to shop.	0.5	\$0.00	W
11/15/2018	Water	64	Road tested vehicle for readiness for NJ inspection, took to inspection-passed.	1.5	\$0.00	W
11/15/2018	Fire	1893	Dropped of 1892 at Browns Mills Firehouse and picked up 1893 at Country Lakes and brought back to shop.	2	\$0.00	W,D
11/15/2018	PW	Shop	Started up trucks in the yard.	0.5	\$0.00	W
11/15/2018	Police	1801	Replaced alternator, tensioner belt. Checked charging system.	3	\$630.46	W
11/15/2018	PW	Shop	Snow duty.	3	\$0.00	D
11/15/2018	PW	Shop	Put snow plows and salt spreaders on for snow duty.	3.5	\$0.00	D,T,DD
11/15/2018	PW	21	Troubleshoot and repair salt spreader/auger circuit. Repaired warning light circuit.	4	\$0.00	D,DD
11/15/2018	Fire	1893	Replaced auto-eject. Pick up and delivery to Country Lakes Fire Dept. Replaced auto eject cord receptacle at firehouse.	3	\$240.57	D,DD
11/15/2018	Fire	1892	Recheck on board charger. Delivered to Browns Mills Firehouse.	1	\$0.00	D
11/15/2018	Police	1805	Replaced rear CAT. Replaced sway bar end links and bushings. Put intake manifold back on.	5	\$310.31	T
11/16/2018	PW	111	Road call to old Acme. Installed tires on left side that were repaired.	2	\$0.00	D,T
11/16/2018	PW	31	Troubleshoot unit not charging. Replaced alternator.	1.5	\$195.00	D,DD
11/16/2018	PW	330	Check deficiency list. Repaired air leak at air valve. Replaced leaking elbow fitting. Repaired marker lights.	2	\$17.34	D,T
11/16/2018	AC	1834	Troubleshoot. Check codes, repair exhaust leak, had to weld y-pipe	2	\$0.00	D,T
11/16/2018	PW	Shop	Dump trash and scrap metal.	0.5	\$0.00	D
11/16/2018	PW	9	Replaced rear cab mounts.	1	\$100.10	W
11/16/2018	Police	1813	Blower motor not working. Inspected, cleaned and repaired wiring.	1	\$0.00	W
11/16/2018	Police	1802	Preventive maintenance service. Replaced wiper blade. Inspected brakes, tires. Replaced front tire. Reset TPMS light.	5	\$187.53	W,T,D,DD
11/16/2018	Rec	79	TPMS training. Came in with TPMS light on.	4	\$0.00	W,D,T,DD
11/16/2018	PW	16	Plow would not go up or down.	0.5	\$0.00	T
11/16/2018	PW	18	Replaced driver side. Battery with old stock.	0.5	\$0.00	T

## FLEET STATUS REPORT

11/30/2018

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
11/16/2018	Police	1816	Removed intake manifold to replace rear upper O2 sensor and replaced front. Clear codes.	1	\$0.00	T
11/16/2018	PW	21	Jump started.	0.5	\$0.00	T
11/19/2018	PW	Shop	Cut and set up cross bracing at Acme demolition site.	13	\$0.00	D,DD
11/19/2018	PW	29	Installed mud flap. Rewired rear plow lamp and license tag light and replaced rear brake lamp assembly, installed new rear plow light.	5.5	\$0.00	W
11/19/2018	PW	19	Replaced dash bracket.	1	\$94.28	W
11/19/2018	Police	1802	Troubleshoot tire losing air. Replaced TPMS sensor, balanced and relearned the new sensor.	1	\$56.86	T
11/19/2018	PW	27	Repaired driver lower tail light. Put driver rear inner tire back on bead with plug. Repaired tag light.	5.5	\$2.96	T
11/20/2018	PW	Shop	Weld cross bracing at old Acme sight.	13	\$0.00	D,DD
11/20/2018	PW	PW	Traced wires. Fixed ground on strobes.	1	\$0.00	T
11/20/2018	PW	111	Road call to Country lakes. Swapped rim and tire out.	1	\$0.00	T
11/20/2018	Police	1801	Troubleshoot random misfire.	0.5	\$0.00	T
11/20/2018	PW	207	wired up and installed salt spreader and made box for it.	4	\$0.00	T
11/20/2018	PW	26	Took off plow and brought on lift. Checked horn. Inspected transmission lines. Added fluid. Inspected tarp.	4	\$6.66	W
11/20/2018	PW	17	Replaced front t-case drive shaft. Checked TPMS Road tested.	2	\$335.82	W
11/20/2018	PW	Shop	Parked 19 in yard, pulled in 99 and 9 for inspection.	0.5	\$0.00	W
11/21/2018	PW	111	Road Call Country Lakes: Replace left rear tire (flat)	2	\$0.00	D,T
11/21/2018	PW	205	Replace broken wiper arm. (Acme Plaza)	2	\$89.04	D,T
11/21/2018	PW	PW	Operate skid steer at Acme Plaza.	4	\$0.00	D
11/21/2018	PW	26	Replace electric horn.	0.5	\$86.22	D
11/21/2018	PW	18	Jump battery to move truck.	0.5	\$0.00	W
11/21/2018	PW	Shop	Move trucks in yard,plug in plow trucks..5	0.5	\$0.00	W
11/21/2018	PW	26	Greased truck.	0.5	\$0.00	W
11/21/2018	PW	Shop	Clean up shop.	3	\$0.00	W
11/21/2018	PW	207	Finish install of new spreader. Hook up spreader light, disable tilt bed.	3	\$15.95	T,DD

## FLEET STATUS REPORT

11/30/2018

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
11/21/2018	PW	Shop	Put plows on 5 pick up's for possible bad weather.	6	\$0.00	T,W,DD
11/21/2018	PW	Shop	Pick up and clean up shop.	1	\$0.00	T,D
11/21/2018	PW	217	Install new tail light.	0.5	\$41.41	T
11/26/2018	PW	208	Remove cabin door handle, repair and re-install.	1.5	\$0.00	T
11/26/2018	Police	1807	PM Service, Replace front tires, order R.S. lower control arm.	3	\$305.74	T
11/26/2018	Fire	1604	Check charging system, charge battery and check.	1	\$0.00	T
11/26/2018	Police	37	R.S. strut bolt backed out.	1	\$0.00	T
11/26/2018	PW	Shop	Paint maintenance shop break room.	1	\$0.00	W
11/26/2018	PW	213	PM service, Replace marker/stop light.	2.5	\$76.41	W
11/26/2018	PW	61	Check heater box for foul smell.	1	\$0.00	W
11/26/2018	PW	Shop	Suck/pump water out of hydraulic room.	1.5	\$0.00	W
11/26/2018	PW	12	Jump start unit for repairs.	0.5	\$0.00	W
11/26/2018	PW	PW	Acme Plaza: cut and fit I-beams for welding braces.	11	\$0.00	D,DD
11/26/2018	PW	Shop	Install rolling jack on drive on lift.	2	\$0.00	D,DD
11/27/2018	PW	Shop	Paint break room and suck up water in hydraulic room.	3	\$0.00	W
11/27/2018	PW	1802	Replace O2 sensors, clear codes and test drive.	1.5	\$91.44	W
11/27/2018	PW	Shop	Start all dump trucks in yard to charge batteries.	0.5	\$0.00	W
11/27/2018	Police	1805	Replace R.S. headlight.	0.5	\$9.99	W
11/27/2018	PW	320	Ck. Brakes, adjust brakes, adjust sweeper blade control handle.	1	\$0.00	W
11/27/2018	PW	PW	Weld I-beams at Acme plaza.	5.5	\$0.00	D
11/27/2018	PW	12	Road Call: pick up and drive back to shop.	1	\$0.00	D,T
11/27/2018	PW	208	Rebuild door handle and re-install on door.	3	\$0.00	T
11/27/2018	Police	1807	Replace R.F. control arm.	3.5	\$121.22	T,D
11/28/189	Water	tamper	Look for parts to repair unit.	0.5	\$0.00	D
11/28/2018	PW	T-3	Pump out contaminated fuel, order fuel filter.	1.5	\$0.00	D
11/28/2018	PW	107	Road Call: repair wiring to altenator and heater blower.	2	\$0.00	D
11/28/2018	PW	66	Road Call: Jump start unit, open valves for heater.	1	\$0.00	D
11/28/2018	PW	104	Road Call: pump up front tire.	1.5	\$0.00	D
11/28/2018	PW	Shop	Pick up paint and paint in break room.	4	\$0.00	W

# FLEET STATUS REPORT

11/30/2018

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
11/28/2018	Fire	1604	Replace battery and 1 battery terminal.	0.5	\$117.02	W
11/28/2018	Police	1807	Replace L.S. headlight bulb and repair wiring.	1.5	\$32.79	W
11/28/2018	PW	212	Build platform for new spreader and start installation.	5	\$0.00	T
11/28/2018	PW	Shop	Urgent care for right eye.	2	\$0.00	T,DD
11/28/2018	Police	1808	Replace R.R. tire. (with spare)	0.5	\$0.00	T
Total Hours Worked				192.50		
Time Off (e.g., sick, vacation, etc....)				8.00		
Misc. Time (e.g., Class, CDL Drug Test, etc....)				0		
TOTAL HOURS				200.50		
TOTAL PARTS COST					\$3,165.12	