

FLEET STATUS REPORT

3/17/2017

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
03/09/17	PW	24	Repair engine oil leaks.	3.00	\$129.36	J
03/09/17	PW	23	Repair/replace top radiator hose, replace nipple and hose from over flow.	2.50	\$19.84	J
03/09/17	PW	Shop	Pick up charger for #1612 at Blaze.	0.50	\$0.00	C
03/09/17	Police	1390 uc	Replace rear brake pads and rotors, install 5 new lug studs, replace L.F. window regulator, test drive.	5.00	\$212.63	C
03/09/17	Police	1823	Load test battery, check charging and starting system, install battery terminal protectors, adjust and lube hood latch.	1.00	\$1.94	C
03/09/17	PW	T-31	Continue to weld and fabricate gussets to repair cracked frame.	7	\$0.00	C,J
03/09/17	Water	65	Install electric trailer brake controller, install license plate.	2	\$73.38	DD,J
03/10/17	PW	208	PM Service.	5	\$96.25	J
03/10/17	Police	1390 uc	Repair gas filler door. 1	1	J	
03/10/17	PW	T-31	Check belt tension, Replace teeth, cut and weld new holders on and greese drum bearings.	7	\$502.66	D,J
03/13/17	PW	T-31	Drill out broken bolts for air cleaner mounting plate.	2	\$6.30	D
03/13/17	PW	35	Air up R.F. tire, check fluids,replace missing radiator cap.	1	\$34.89	D
03/13/17	PW	208	Get unit running , charge battery.	0.5	\$0.00	D
03/13/17	Adm.	2	Replace battery, check starter draw, alternator volt and amp output and check for a power draw.	1.5	\$111.07	D,DD
03/13/17	PW	21	Adjust brakes.	0.5	\$0.00	D
03/13/17	Police	43	Check heater blower, needs speed control switch.	0.5	\$0.00	D
03/13/17	PW	22	Replace R.F. head light bulb and socket.	1	\$14.03	C
03/13/17	PW	21	Pressure check cooling system and replace radiator cap.	1	\$0.00	C
03/13/17	Police	1390 uc	Bleed brake system.	2	\$0.00	C,DD
03/13/17	Police	1819	Replace fuse for GPS.	0.5	\$0.00	C
3/13/17	PW	19	Jump start.	0.5	\$0.00	C
03/13/17	PW	14	Install tire plug in R.F. tire.	0.5	\$0.49	C
03/13/17	PW	4	Repair plow lights and install plow markers.	0.5	\$25.10	C
03/13/17	PW	11	Put plow on truck.	1	\$0.00	C
03/13/17	PW	18	Flip rubber on plow.	1	\$0.00	C
03/13/17	PW	18	Install wiper blades.	0.25	\$19.38	DD
03/13/17	PW	Shop	Check and plug in block heaters on plow trucks.	0.5	\$0.00	J
03/13/17	PW	102	Clean terminals on spreader starter solinoid. Now no start, troubleshoot.	2	\$0.00	J
03/13/17	PW	Ploice	Road Call: pick up bicycle for police impound.	0.25	\$0.00	J
03/13/17	PW	24	Flip rubber on plow, replace steel edge, install grease fittings on plow wheels and lube up, install new o-rings on rear couplers, install new hose on spreader.	3	\$298.46	J,D

FLEET STATUS REPORT

3/17/2017

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
03/13/17	PW	21	Replace blower motor, clean out ducts.	1	\$0.00	J
03/13/17	PW	23	Replace control valve and air spring on air ride seat.	0.5	\$201.13	J
03/14/17	Police	1811	PM Service.	2	\$19.83	J
03/14/17	Water	70	Remount plow. (hooked up improperly)	0.5	\$0.00	J
03/14/17	PW	63	Replace u-joints in rear driveshaft.	2	\$30.16	J
03/14/17	PW	12	Get running.(was not plugged in)	0.5	\$0.00	J
03/14/17	PW	28	Flip plow rubber.	1	\$0.00	D,J
03/14/17	PW	102	Replace coil on spreader, repair electrical wires.	2	\$0.00	J
03/14/17	PW	Shop	Clean snow off trucks and start up for snow storm.	2	\$0.00	D,J
03/14/17	PW	25	Check out head lights flashing, replace relay.	1	\$10.99	D
03/14/17	PW	Shop	Replace broken swiych on shop battery charger.	1	\$3.83	D
03/14/17	PW	Shop	Clean out shop tool box, install drawer liners. Find, clean, and organize old and new tools for shop mechanics use.	4.5	\$0.00	D,DD
03/14/17	Police	1805	PM Service.	2	\$28.51	C
03/14/17	PW	Shop	Went to Tractor Supply, Auto Parts Connection and Hainesport Truck.	1.5	\$0.00	C
03/14/17	Adm.	90	Air up tire, check for leak.	0.5	\$0.00	C
03/14/17	PW	5	Install new wiper arm and both blades.	0.5	\$39.63	C
03/14/17	Police	1807	Replace battery, install battery protectors.	1	\$0.95	C
03/14/17	PW	34	Check and remove broken hose from refueling tank.	0.5	\$0.00	C
03/14/17	Police	1821	No start, jump start.	1	\$0.00	C,D
03/14/17	Fire	equip.	Portable power unit, no start due to low engine oil level.	0.5	\$2.55	D
03/15/17	Fire	1618	Pick up from Lucas Chevy.	2	\$0.00	C,DD
03/15/17	PW	5	Grade front end, remove and inspect front locking hubs, secure wire harness on underside of vehicle.	2	\$0.00	C
03/15/17	PW	Shop	Clock in at 5am for snow mode.	4	\$0.00	C,D
03/15/17	PW	Shop	Pick up tires from Tri-State.	1	\$0.00	C,DD
03/15/17	PW	22	Head lights inop., replace relay.	1	\$0.00	C
03/15/17	PW	208	Balance front tires.	1	\$0.00	C
03/15/17	PW	101	PM Service, install back up alarm, scan computer for codes, remove heater blower switch for replacement.	3.5	\$50.61	C
03/15/17	PW	17	Get spreader running, frozen up.	0.5	\$0.00	J
03/15/17	PW	102	Get spreader running, frozen up.	0.5	\$0.00	J
03/15/17	PW	34	Replace hose on refueling tank, tighten pump in tank, repair L.R. turn signal, air up all tires.	2	\$40.00	J
03/15/17	Fire	chn.saw	check oil leak, replace o-ring at oil reservoir.	1	\$0.00	D
03/15/17	PW	PTPD2	Troubleshoot no start, Has bad battery master switch	1	\$0.00	D

**FLEET STATUS REPORT**

**3/17/2017**

<b>DATE</b>	<b>DEPT</b>	<b>VEHICLE</b>	<b>REPAIR</b>	<b>Hours</b>	<b>Parts Costs</b>	<b>MECH</b>
03/15/17	PW	Shop	To Cherry Hill DMV, reschedule CDL road test.	2.5	\$0.00	D
03/15/17	PW	31	Check center frame pivot points for excessive wear.	1	\$0.00	D
03/15/17	Police	1809	PM Service	1.5	\$41.27	D
03/15/17	Police	43	Repair wire harness and replace heater blower motor switch.	1	\$37.84	D

	Total Hours Worked	105
	Time Off (e.g., sick, vacation, etc...)	8
	Misc. Time (e.g., Class, CDL Drug Test, etc...)	<hr/>
	<b>TOTAL HOURS</b>	<b>113.00</b>
	<b>TOTAL PARTS COST</b>	<b>\$2,053.08</b>