

FLEET STATUS REPORT

3/13/2017

| DATE | DEPT | VEHICLE | REPAIR | Hours | Parts Costs | MECH |
|----------|--------|---------|---|-------|-------------|-------|
| 3/2/17 | Police | 1808 | Install new flash light charger. | 0.50 | \$0.00 | DD |
| 03/02/17 | Police | 1817 | PM Service, mount and balance 1 tire. | 1.50 | \$132.46 | C |
| 03/02/17 | Police | 1810 | PM Service, replace rear brake pads, replace wiper blades. | 1.50 | \$70.17 | C |
| 03/02/17 | Police | 1813 | Reinstall plastic covers on interior of unit. | 0.50 | \$0.00 | C |
| 03/02/17 | PW | Shop | Sweep and clean in shop. | 0.50 | \$0.00 | J |
| 03/02/17 | PW | Shop | Defensive driving class. | 10.50 | \$0.00 | J,D,C |
| 03/02/17 | PW | 7 | PM Service, clean inside of truck. | 2.00 | \$33.24 | J |
| 03/02/17 | Water | 65 | PM Service, begin to install trailer brake module. | 3 | \$329.22 | D |
| 03/03/17 | PW | 1603 | PM Service. | 1.5 | \$22.94 | D |
| 03/03/17 | Water | 65 | Install new style trailer plug on truck, troubleshoot electric brakes, instrument cluster needs to be programed for brake set up. | 4 | \$9.00 | D |
| 03/03/17 | PW | Shop | CDL Test in Cherry Hill. | 4.5 | \$0.00 | C |
| 03/03/17 | PW | 109 | Road Call: No Start, clean battery terminals. | 2 | \$0.00 | D,C |
| 03/03/17 | PW | Shop | Clean back of shop, take scrap metal to pile, take old tires to trailer. | 0.5 | \$0.00 | C |
| 03/03/17 | Police | 1801 | Install air bag clock spring in steering column. | 2.5 | \$181.57 | DD |
| 03/03/17 | PW | Shop | Install Fuel Fox fuel conditioner after delivery on 2/2/17 in pump tank. | 0.5 | \$0.00 | DD |
| 03/06/17 | PW | 105 | PM Service. | 1.5 | \$292.55 | J |
| 03/06/17 | PW | T-20 | Replace roof vent cover. | 0.5 | \$13.83 | J |
| 03/06/17 | PW | 101 | Install new trailer plug. | 0.25 | \$64.14 | J |
| 03/06/17 | PW | 24 | Thaw out air brake line, Check oil leak and order parts needed. | 1 | \$0.00 | J |
| 03/06/17 | PW | 23 | Check air seat leak and order parts needed, Check coolant leak and order parts needed. | 1 | \$0.00 | J |
| 03/06/17 | PW | 12 | PM Service. | 2 | \$85.41 | J |
| 03/06/17 | PW | 4 | Jump start. (unit not plugged in) | 0.5 | \$0.00 | D |
| 03/06/17 | PW | 11 | PM Service, charge both batteries, (key left on) remove snow plow. | 2 | \$111.15 | D |
| 03/06/17 | PW | T-1 | Replacing front axle seals bearings and bushings. | 2 | \$0.00 | D |
| 03/06/17 | PW | T-31 | Get unit running, thaw out frozen water pump(again) and water lines, repair leaking spray bar. Road Call. | 2 | \$0.00 | D |
| 03/06/17 | PW | 102 | PM Service, Repair tag light. | 3 | \$46.14 | C |
| 03/06/17 | Ploice | 1817 | Mount and balance 1 tire. | 0.5 | \$103.96 | C |
| 03/06/17 | Water | 65 | Take to Labars to program Instrument cluster for trailer brake activation. | 1 | \$50.00 | C,DD |
| 03/06/17 | PW | 37 | Repair flat tire. (needs tires). | 0.5 | \$1.50 | DD |
| 03/06/17 | Fire | 1693 | Go to CLFD and replace wiper blades and adjust. | 2.5 | \$8.76 | C,DD |
| 03/06/17 | Fire | 1611 | Go to BMFC: Replace bulb on tower lights, Replace front left compartment light, Replace wiper blades. (waiting for more parts). | 3 | \$34.47 | C,DD |
| 03/06/17 | Fire | 1612 | Check battery charger, needs new Auto Charger 1000. (locating replacement) | 1.5 | \$0.00 | C,DD |

FLEET STATUS REPORT

3/13/2017

| DATE | DEPT | VEHICLE | REPAIR | Hours | Parts Costs | MECH |
|-------------|-------------|----------------|---|--------------|--------------------|-------------|
| 03/07/17 | PW | T-1 | Replace rebuilt front rear parts onto tractor. | 6 | \$422.63 | D |
| 03/07/17 | PW | T-31 | Road Call: Check cracked main frame on unit. (must be brought back) | 1 | \$0.00 | J |
| 03/07/17 | PW | 5 | Balance front tires. | 1 | \$0.00 | J |
| 03/07/17 | PW | 105 | Finish up service. | 0.5 | \$2.92 | J |
| 03/07/17 | PW | 24 | Repairing oil leak on truck. | 4.5 | \$161.21 | J |
| 03/07/17 | Police | 1839 | Replace wiper blades. | 0.25 | \$9.98 | C |
| 03/07/17 | Water | 65 | Replace broken pressure switch on master cylinder. | 0.5 | \$42.72 | C |
| 03/07/17 | Fire | 1618 | Take to Lucas Chevy for repairs. | 1 | \$0.00 | C,DD |
| 03/07/17 | Fire | 1612 | Go to BMFC to check on board charger. | 1 | \$0.00 | C,DD |
| 03/07/17 | PW | 17 | PM Service. | 2.5 | \$56.08 | C |
| 03/07/17 | Water | 71 | PM Service. | 2 | \$27.41 | C |
| 03/07/17 | PW | 27 | Install male coupling on rear of truck. | 0.5 | \$14.48 | DD |
| 03/08/17 | PW | 23 | Drain down cooling system and remove top hose. | 1 | \$0.00 | J |
| 03/08/17 | PW | 24 | Repair engine oil leak. | 4.5 | \$222.24 | J |
| 03/08/17 | PW | 1672 | Jump start unit. (main switch not shut off) | 0.25 | \$0.00 | J |
| 03/08/17 | PW | T-31 | Strip parts off unit to repair frame crack. | 6.5 | \$0.00 | D,J |
| 03/08/17 | Police | 1390 uc | Replace front brakes, rotors, calipers, hoses and 1 wheel lug stud. | 5 | \$237.57 | C,D |
| 03/08/17 | Fire | 1621 | Pick up at BMFC. Drop off at Blaze for parts number research, then take back to BMFC. | 2 | \$0.00 | C,DD |
| 03/08/17 | Fire | 1631 | Take unit to Johnson/Towers for diagnostic test on computer. | 2 | \$0.00 | DD,C |

| | |
|---|-------------------|
| Total Hours Worked | 102.25 |
| Time Off (e.g., sick, vacation, etc...) | 1 |
| Misc. Time (e.g., Class, CDL Drug Test, etc...) | 4 |
| TOTAL HOURS | 107.25 |
| TOTAL PARTS COST | \$2,787.75 |