

FLEET STATUS REPORT

4/28/2017

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
04/20/17	Sen.	77	PM Service, Replace R.F. outter wheel bearing and race.	3.50	\$55.51	C,D
04/20/17	PW	106	Straighten body damage and belly pan.	1.50	\$0.00	D
04/20/17	AnCon	43	Replace drivers side window regulator.	2.00	\$56.61	D
04/20/17	Fire	1602	Drop off at firehouse(BMFC).	1.00	\$0.00	C,D
04/20/17	Police	1820	Install repaired bumper wrap, sand fibreglass work and paint.	4.00	\$0.00	C,DD
04/20/17	Sen.	77	Replace worn tire and rim on R.F.	1.00	\$0.00	C
04/20/17	Fire	1691	Disconnect battery to reset computor, replace wiper blades.	2.00	\$19.38	C
04/21/17	Water	64	PM Service, replace wiper blades.	2	\$48.34	C
04/21/17	Water	61	PM Service,replace L.F. outter tie rod end, axle, front brake job, wipers.	4.5	\$302.63	C
04/24/17	Police	1807	Front and rear brake job, replace spot light bulb, off lift inspection.	4	\$316.53	J
04/24/17	PW	T-2	Weld pin for cross bar back on trailer.	0.75	\$0.00	J
04/24/17	PW	29	Replace missing mud flap, off lift inspection.	1	\$2.57	J
04/24/17	Fire	1691	Check door alarm staying on.	1.5	\$0.00	D
04/24/17	PW	T-1	Make parts list for broken grills.	0.5	\$0.00	D
04/24/17	PW	12	Road Call: Country Lakes, fuel pump going bad.(on order)	1	\$0.00	D,DD
04/24/17	PW	35	Remove battery for grader.	0.5	\$0.00	D
04/24/17	PW	37	Check unit no start, charge batteries, load check, replace 1 bad battery.	1.5	\$168.50	D
04/24/17	Fire	1693	Check for excessive exhaust smell, repair exhaust leak and return to BMFC.	2.5	\$0.00	D,DD
04/25/17	PW	101	Check and order new door steps for truck.	0.5	\$0.00	C
04/25/17	PW	208	Jump start.	0.25	\$0.00	C
04/25/17	Water	61	Set toe in on front end.	0.5	\$0.00	C
04/25/17	Fire	1691	PM Service.	3	\$81.89	C
04/25/17	Police	1812	PM Service.	2	\$19.83	C
04/25/17	PW	105	Rotate front tires side to side.	0.5	\$0.00	J
04/25/17	PW	23	Locate fuel leak (parts on order), remove exhaust for repairs.	5.5		J
04/25/17	PW	PW	Weld stops on storm grate.	1	\$0.00	J
04/25/17	PW	12	Check fuel pump, starter, and flex plate. (all parts on order)	3	\$0.00	D
04/25/17	Fire	1691	Remove and test all door and cabinet sensors.	2.5	\$0.00	D
04/25/17	Insp.	41	Replace wiper blades.	0.5	\$11.98	D
04/26/17	PW	102	Check for loose bed,(looking into new bed rails).	0.5	\$0.00	C
04/26/17	PW	40	Removed two way radio.	0.5	\$0.00	C
04/26/17	Fire	1693	PM Service, return to BMFC.	4	\$132.94	C,D,DD
04/26/17	PW	27	Repair wires for tail lights.	1	\$0.00	C
04/26/17	Fire	1603	PM Service.	2	\$48.45	C
04/26/17	Police	1812	Replace L.F. head light.	0.5	\$2.80	C
04/26/17	PW	T-13	Engine swap on stump cutters.	5	\$0.00	D,J

FLEET STATUS REPORT

4/28/2017

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
04/26/17	PW	23	Finish exhaust repairs,change out turbo inlet tube.	3	\$6.19	J
04/26/17	PW	12	Remove transmission, replace flex plate, start to reinstall transmission.	4.5	\$541.22	D

Total Hours Worked	75
Time Off (e.g., sick, vacation, etc...)	33
Misc. Time (e.g., Class, CDL Drug Test, etc...)	0
TOTAL HOURS	108.00
TOTAL PARTS COST	\$1,815.37