

FLEET STATUS REPORT

5/17/2018

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
05/10/18	PW	30	Removed three point hitch and lift arms that were interfering with bat wing mower hitch. Repaired left side door handle latch.	2.50	\$0.00	D,T
05/10/18	Fire	Chainsaw	Checked leak at gas tank. Replaced leaking gas cap and leaking oil cap.	0.50	\$7.14	D,T
05/10/18	PW	T-31	Replaced front skid plate.	1.50	\$433.67	D,DD,T
05/10/18	PW	Rhino Mowe	Make parts and metal supply list. Freed up seized drive shafts and drive couplings. Check over unit. Went to Jersey AG for parts.	2.50	\$0.00	D
05/10/18	PW	31	Road call to Country Lakes. Aired up left front tire. Replaced grease fitting and 2 bar linkage and greased.	1.00	\$0.00	D
05/10/18	Police	1800	Swapped out driver front rim/tire spare with repaired valve stem that was on original rim and tire. Preventive service maintenance.	2.00	\$31.71	T
05/10/18	Code	51	Preventive maintenance service. Cabin filter replaced.	2.00	\$38.68	T
05/10/18	Police	1807	Removed steering wheel to replace clock spring and checked out air bag system.	2.00	\$187.07	T
05/10/18	PW	211	Adjust side suction units.	1.00	\$0.00	D
05/11/18	Police	1816	Preventive maintenance service. Replaced O2 sensors. Replaced driver side wiper.	3.50	\$206.18	T
05/11/18	PW	Shop	Dump trash and cleaned up shop.	1.00	\$0.00	T
05/11/18	PW	35	Removed broken off key from ignition.	1.00	\$4.47	T
05/11/18	Police	1811	Picked up from Medford Ford - recall work.	2.00	\$0.00	T,D
05/11/18	Seniors	78	Preventive maintenance service.	2.50	\$50.85	D
05/11/18	PW	T-31	Replaced 11 teeth and welded two holders, supplied operators with 24 teeth. Repaired positive power feed wires from battery box.	1.50	\$329.16	D
05/11/18	PW	31	Road call to Country Lakes. Troubleshoot air conditioning. Unit kept blowing blower motor fuse. Replaced fuse, cleaned relay connections and checked switch connections.	1.00	\$0.00	D
05/11/18	PW	100	Checked broken flail mower belts. Removed mower drive cover, removed worn idler pulleys and broken belts.	0.50	\$0.00	D
05/11/18	PW	211	Replaced right and left side brooms.	1.00	\$281.04	DD
05/14/18	Police	1816	Replaced sway bar links, passenger side engine mount and driver side tie rod end.	2.50	\$173.45	T
05/14/18	Police	1812	Towed back to shop.	1.00	\$0.00	T,D

FLEET STATUS REPORT

5/17/2018

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
05/14/18	PW	105	Replaced battery.	1.00	\$114.35	T,W
05/14/18	PW	112	Replaced driver side rear blinker.	0.50	\$1.83	T
05/14/18	Police	1816	Dropped off at Medford Ford for recall.	2.00	\$0.00	T,W
05/14/18	PW	T-20	Tow unit in shop started repairing broken rear door hinge.	0.50	\$0.00	D
05/14/18	PW	T-31	Replaced two holders and two teeth. Road call to Country Lakes.	1.50	\$41.00	D
05/14/18	PW	24	Checked exhaust leak and transmission oil leak.	0.50	\$0.00	D
05/14/18	PW	31	Checked hydraulic level, hand checked heater blower motor.	1.50	\$0.00	D
05/14/18	PW	210	Installed back up guides near rear of unit.	0.50	\$0.00	D
05/14/18	PW	107	Road call to Country Lakes. Checked air conditioning that was not working. Recharged air conditioning and checked system for leaks.	1.50	\$4.17	D
05/14/18	Police	1809	Checked transmission, added Lucas stop slip to transmission, ordered parts - upper and lower control arm.	2.00	\$11.99	W,T
05/14/18	Police	1820	Preventive maintenance service. Rotated tires, checked breaks, checked lights and replaced cabin filter.	5.00	\$41.19	W,T
05/15/18	PW	6	Troubleshoot no parking lights, replaced blown fuse and blown bulb at rear body. Tied up loose wires, greased tailgate.	2.50	\$1.00	D
05/15/18	PW	T-20	Repaired broken rear door hinge - plate and weld. Supplied new registration and installed registration holder inside trailer door.	1.50	\$6.59	D
05/15/18	Police	1829	Road call to Country Lakes Firehouse. Picked up unit that was overheating.	2.00	\$14.56	D,DD
05/15/18	Police	1807	Replaced belt tensioner and air conditioner compressor.	3.00	\$437.54	T
05/15/18	PW	Shop	Went to Tractor supply to get grease guns.	2.00	\$0.00	T,D
05/15/18	Police	1816	Picked up from Medford Ford for recall. Rear toe links replaced and alignment.	2.00	\$0.00	T,DD
05/15/18	Fire	1801	Replaced ABS, traction control and ESP computer.	1.00	\$314.50	T
05/15/18	PW	T-31	Replaced air filters.	0.50	\$64.64	DD
05/15/18	Water	Trailer	Replaced tire. Checked all tires for proper pressure.	1.50	\$0.00	W,T
05/15/18	PW	Shop	Cleaned and organized tire shed.	4.00	\$0.00	W
05/15/18	PW	35	Preventive maintenance service.	4.00	\$198.07	D,W
05/15/18	PW	Shop	Changed engine oil drum and repair hose reel leaks and repaired leaking fittings.	0.50	\$0.00	D
05/16/18	Police	1810	Pulled radiator.	2.50	\$0.00	W

FLEET STATUS REPORT

5/17/2018

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
05/16/18	PW	JDZ1	Got mower back and set up tools	0.50	\$107.15	T
05/16/18	PW	JDZ2	Got parts and changed oil and hydraulic fluid	0.25	\$107.15	T
05/16/18	PW	JDZ3	Got parts and changed oil and hydraulic fluid	0.25	\$107.15	T
05/16/18	Police	1807	Recharged air conditioning	2.00	\$7.77	T,DD
05/16/18	Police	1824	Lower gas tank and hoses, removed fuel pump	2.50	\$157.59	T,D
05/16/18	PW	Shop	Cleaned shop, prepped for new lift, dumped trash.	3.00	\$0.00	T,W
05/16/18	Police	1525	Drained coolant, removed radiator and replaced radiator coolant.	4.00	\$3.98	T,W
05/16/18	PW	2841	Checked all fluids and checked all tires for pressure	0.50	\$0.00	W
Total Hours Worked				89.00		
Time Off (e.g., sick, vacation, etc....)				56.00		
Misc. Time (e.g., Class, CDL Drug Test, etc....)						
TOTAL HOURS				145.00		
TOTAL PARTS COST					\$3,485.64	