

FLEET STATUS REPORT

6/7/2018

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
05/31/18	Police	1846	Troubleshoot check engine light on. Road test.	3.50	\$1.56	W
05/31/18	Police	1624	Continued troubleshooting, no start.	4.00	\$2.50	T,D
05/31/18	PW	212	Dropped 212 off at Monmouth Truck and picked up 214.	6.00	\$0.00	T,W
05/31/18	Fire	1892	Checked air conditioning leak. Removed battery, battery box, air box and window washer bottle. Removed expansion valve at fire wall, checked all o-ring connections.	2.00	\$0.00	D
05/31/18	PW	T-16	Checked cutter head that came off drum. Replaced four teeth and flipped six teeth.	2.00	\$115.88	D
05/31/18	PW	107	Replaced broken parking brake handle spring and checked relay connections. Road call to Country Lakes.	1.50	\$0.00	D
06/01/18	Police	1846	Checked and replaced fluids and wiper blades. Troubleshoot for inspection. Test drove	4.00	\$21.49	W
06/01/18	PW	21	Lubed truck.	0.50	\$6.50	W
06/01/18	PW	25	Lubed truck.	0.50	\$6.50	W
06/01/18	PW	24	Lubed truck.	0.50	\$6.50	W
06/01/18	PW	29	Lubed truck.	0.50	\$6.50	W
06/01/18	PW	8	Lubed truck.	0.50	\$6.50	W
06/01/18	Police	1624	Worked on electrical problem.	3.00	\$0.00	T,DD
06/01/18	Police	1808	Replaced oil sensor and cleaned block.	2.00	\$9.08	T
06/01/18	PW	Mower 2	Adjusted belt and tensioner. Took wheel apart to order new bearings.	1.00	\$0.00	T,D
06/01/18	Police	1807	Preventive maintenance service. Order O2 sensor.	2.50	\$34.81	T
06/01/18	Police	1390	Troubleshoot air conditioner blowing warm air.	2.00	\$23.06	D
06/01/18	Fire	1892	Replaced air conditioner expansion valve and seal kit.	1.00	\$78.61	D
06/01/18	PW	17	Replaced passenger side mirror.	1.00	\$440.05	D
06/01/18	PW	37	Checked front tire for wear, checked front end for play and toe adjustment.	0.50	\$0.00	D
06/01/18	PW	26	Checked air conditioning for leak. Recharged air conditioner.	1.00	\$4.17	D

FLEET STATUS REPORT

6/7/2018

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
06/04/18	Water	63	Dropped off to Monmouth Truck for evap leak repair.	6.00	\$0.00	T,DD
06/04/18	Police	1804	Preventive maintenance service. Replaced and balanced front tires.	2.50	\$316.87	T
06/04/18	Police	1804	Dropped off to Ford for toe links recall.	2.00	\$0.00	T,DD
06/04/18	Fire	1892	Removed and replaced leaking high pressure air conditioner hose.	2.00	\$0.00	D
06/04/18	PW	27	Road call to Country Lakes. Repaired rear hydraulic coupler.	1.00	\$0.00	D
06/04/18	PW	Tractor 855	Got unit running and checked over. Greased.	1.00	\$0.00	D
06/04/18	PW	37	Put tire back on that was flat and off the bead.	1.00	\$0.00	D
06/04/18	PW	27	Straightened mud flap brackets and replaced two mud flaps.	1.00	\$30.22	D
06/04/18	Police	1390	Replaced air conditioner clutch switch.	0.50	\$23.06	D
06/05/18	Police	1837	Replaced fuse for cigarette lighter. Replaced serpentine belt. Charged battery.	2.50	\$32.69	T
06/05/18	Water	63	Picked truck up from Monmouth Truck.	6.00	\$0.00	T,DD
06/05/18	Fire	1892	Replaced blown high pressure air conditioner hose.	5.50	\$20.70	D,DD,T
06/05/18	Police	1820	Dropped off and picked up at Medford Ford for recall 17G01 rear toe links. Replaced battery in carbon monoxide detector.	1.00	\$2.99	D
06/05/18	104	4199	Picked up from Medford Ford. Recall 17G01-rear toe link replacement.	1.00	\$0.00	D
06/05/18	Police	1812	Dropped off at Medford Ford. Recall 17G01-rear toe link replacement.	1.00	\$0.00	D
06/05/18	PW	28	Road call to Country Lakes. Repaired broken hydraulic couplers.	1.00	\$1.68	DD
06/06/18	PW	Shop	Took shop truck to beach building for work that needed to use the air hammer.	2.00	\$0.00	T,DD
06/06/18	Police	1804	Mounted speed detector.	1.00	\$1.69	T
06/06/18	Police	1812	Picked up from Medford Ford - recall 17G01.	1.00	\$0.00	T
06/06/18	Police	1805	Picked up from Medford Ford - recall 17G01.	1.00	\$0.00	T
06/06/18	PW	Shop	Put tire machine into place.	1.50	\$0.00	T,DD
06/06/18	Police	1807	Replaced O2 sensor. Cleared code and test drove.	2.00	\$66.97	T
06/06/18	Fire	1892	Charged air conditioner. Put covers and clamp back on hose after repair. Checked for leaks. Test drove. Delivered to Browns Mills Fire Department.	3.50	\$0.00	D,DD,T
06/06/18	PW	Shop	Jump started pot hole killer.	0.50	\$0.00	D
06/06/18	PW	111	Replaced broken door shock.	0.50	\$29.68	D

FLEET STATUS REPORT

6/7/2018

DATE	DEPT	VEHICLE	REPAIR	Hours	Parts Costs	MECH
06/06/18	PW	Shop	Repaired water line on Stihl saw.	0.50	\$6.80	D
06/06/18	PW	45	Road call to Country Lakes. Checked coolant leak. Blocked off heater hoses that were leaking for a temporary repair.	1.00	\$15.23	D
06/06/18	Fire	1836	Picked up unit from Country Lakes Fire House. Troubleshoot on board charger. Replaced two blown internal fuses.	3.50	\$0.00	D,DD,T
Total Hours Worked				92.50		
Time Off (e.g., sick, vacation, etc....)				80.00		
Misc. Time (e.g., Class, CDL Drug Test, etc....)						
TOTAL HOURS				172.50		
TOTAL PARTS COST					\$1,312.29	